

District I  
1625 N. French Dr , Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

30-045-24176

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company BP America Production Company	Contact Courtney Cochran	
Address 200 Energy Ct. Farmington, NM 87401	Telephone No. 505-326-9457	
Facility Name GCU 169E	Facility Type Natural Gas Well	
Surface Owner Fee	Mineral Owner Fee	API No. 300452417600

**LOCATION OF RELEASE**

Unit Letter H	Section 35	Township 29N	Range 12W	Feet from the 1850	North/South Line North	Feet from the 790	East/West Line East	County San Juan
---------------	------------	--------------	-----------	--------------------	------------------------	-------------------	---------------------	-----------------

Latitude 36.68519 Longitude 107.06251

**NATURE OF RELEASE**

Type of Release Condensate	Volume of Release Unknown	Volume Recovered none
Source of Release unknown	Date and Hour of Occurrence unknown	Date and Hour of Discovery 10:00 am 4/3/2012
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD; Glenn VonGonten - NMOCD	
By Whom? Jeff Blagg	Date and Hour 2:45 pm and 3:10 pm on 4/3/2012	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

RCVD APR 12 '12  
OIL CONS. DIV.  
DIST. 3



Describe Cause of Problem and Remedial Action Taken.\*

During the investigation of legacy soil impacts at the GCU 169E free floating hydrocarbon was discovered on the water table. The water table is located about 4 feet below grade. The immediate investigation of impacts revealed that they are contained in a small area less than 50 feet in diameter. No private or public water wells are known to exist in the immediate area or down gradient of the site. The landowner has been informed of the impacts.

Describe Area Affected and Cleanup Action Taken.\*

The area is currently undergoing further investigation and remediation of impacted areas.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Courtney Cochran		Approved by Environmental Specialist: 	
Title: Field Environmental Advisor		Approval Date: 4/9/2012	Expiration Date:
E-mail Address: Courtney.Cochran@bp.com		Conditions of Approval.	
Date: 4/5/2012	Phone: 326-9457	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

nJK121036090