

CONFIDENTIAL - TIGHT HOLE

Form 3160-5
(April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0137
Expires March 31, 2007

5. Lease Serial No

11 NMFS 0081226

6. If Indian, Allottee or Tribe Name

RECEIVED

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Bolack Minerals Company

3a. Address 3901 Bloomfield Highway
Farmington, NM 87401

3b. Phone No (include area code)
(505) 325-4275

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1935' FSL and 806' FEL, Section 3
Township 30 North, Range 16 West, N.M.P.M.

7. If Unit or CA/Agreement, Name and/or No

8. Well Name and No

Thomas F. Bolack #1 Well

9. API Well No

3004532583

10. Field and Pool, or Exploratory Area

Wildcat McCracken

11. County or Parish, State

San Juan County, New Mexico


12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

(See attached Exhibit "A")

RCVD FEB22'07
OIL CONS. DIV.
DIST. 3



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Tommy Bolack

Title General Partner

Signature

Tommy Bolack

Date

February 15, 2007

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD

**EXHIBIT "A" TO
SUNDRY NOTICES AND REPORTS ON WELLS
OF
BOLACK MINERALS COMPANY
THOMAS F. BOLACK #1 WELL
DATED FEBRUARY 15, 2007**

01/17/07 DRLG 6.25" HOLE F/9260' TD/9300'.
CIRC & COND HOLE FOR E-LOGS @ 9300'.
DROP TOTCO SURVEY & TOH SLM FOR LOGS. [NO DRAG]
[TOTCO SURVEY @ 9268' = 1.5 DEG]

01/18/07 RU SCHLUMBERGER & LOG W/SAME. [DRILLERS SLM = 9300',
LOGGERS TD = 9288']
PU BAKER INTEC CORING TOOLS & TIH W/SAME.

01/19/07 PU BAKER INTEC CORING TOOLS & TIH W/SAME.
WASH & REAM F/9260' T/9300'.
CORE F/9300' T/9329'.
CIRC & COND MUD & HOLE.
TOH SLM W/CORE BBL.
[SNOWED 3" OVERNIGHT & STILL COMING DOWN]

01/20/07 TOH SLM W/CORE BBL.
UNLOAD 4.5" LINER, STRAP & INSPECT LINER.
RU CSG CREW & HOLD PJSM.
RUN 94 JTS 11.6#, N-80, LTC CSG, FLOAT SHOE ON BOTTOM & LANDING
COLLAR ON TOP OF 1'ST JT. TOTAL LENGTH OF LINER & HANGER = 3751.41.
TRIP LINER IN HOLE ON 3.5" D.P. & HANG OFF. SET @ 8934', SHOE @ 8933',
LANDING COLLAR @ 8892', LINER TOP @ 5182'.
CIRC LINER @ 8935', RU BJ SVC & HOLD SAFETY MTG.
CMT AS FOLLOWS. 10 BBLS GEL H2O, 10 BBLS FW AHEAD. SCAVENGER
CMT 100 SX, 308 CU FT, 55 BBLS, PREM LITE HS. .6% R-3+1/4# SK CELLO-
FLAKE, .3% CD-32, 1% FL-52. [YLD=3.08 CU FT SK WT=11#GAL]
TAIL SLURRY. 540 SX, 1064 CU FT, 189 BBLS. PREM LITE HS, + .6% R-3, 1/4# SK
CELLO-FLAKE, .3% CD-32, + 1% FL-52. [YLD=1.97 CU FT SK WT=12.5# GAL]
DROP PLUG & DISPLACE W/96 BBLS FW, PD@2:20 AM 1/21/2007. [FINAL
PRESS 1898#, BUMP PLUG @2343# FLOAT HELD]
STING OUT OF LINER TOP & PACK OF LINER.
REVERSE OUT 7" CSG THE LONG WAY W/200 BBLS FW, [CIRC OUT
CONTAMINATED MUD & CELLO FLAKE. NO GOOD CMT]
RD BJ SVC & LDDP & SETTING TOOL.

Report TOC