RECEIVED

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIN 29 2012 BUREAU OF LAND MANAGEMENT

Farmington Field Office Bureau of Land Managemen FORM APPROVED OMB No 1004-0137 Expires: July 31, 2010

5 Lease Serial No

SF-078197

SUNDRY NOTICES AND REF	Bureau of Land Manageme	31-0/8/3/
		6 If Indian, Allottee or Tribe Name
Do not use this form for proposals		
abandoned well. Use Form 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE - Other in	structions on page 2	7. If Unit of CA/Agreement, Name and/or No
1 Type of Well		
Oil Well X Gas Well Other		8 Well Name and No Nye Federal 2N
2 Name of Operator Burlington Resources Oil & Gas	s Company LP	9 API Well No 30-045-35256
3a Address PO Box 4289, Farmington, NM 87499	3b Phone No (include area code) (505) 326-9700	10 Field and Pool or Exploratory Area Blanco Mesaverde / Basin Dakota
4 Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit A (NENE) 678' FNL & 756' F Bottomhole Unit A (NENE) 700' FNL & 966' F		11. Country or Parish, State San Juan , New Mexico
12. CHECK THE APPROPRIATE BOX(ES	S) TO INDICATE NATURE OF N	OTICE, REPORT OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF A	CTION
Notice of Intent Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete X Other
Final Abandonment Notice Convert to Injection	Plug and Abandon Plug Back	Temporarily Abandon Completion Report Water Disposal
13. Describe Proposed or Completed Operation Clearly state all pertinent de If the proposal is to deepen directionally or recomplete horizontally, giv Attach the bond under which the work will be performed or provide the following completion of the involved operations. If the operation result Testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection)	e subsurface locations and measured and Bond No on file with BLM/BIA. Requ s in a multiple completion or recompletio	true vertical depths of all pertinent markers and zones. red subsequent reports must be filed within 30 days on in a new interval, a Form 3160-4 must be filed once
Please See Attached		RCVD JUL 9'12 OIL CONS. DIV.
		DIST. 3
		JUL 0 5 2012 FARMINATION FIRE D OFFICE BY II. Solver 2
14. I hereby certify that the foregoing is true and correct Name (Printed/Typ	ped)	

Staff Regulatory Technician	
29/2012	
E OFFICE USE	
e	Date
	ince

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Nye Federal 2N API# 30-045-35256 Burlington Resources Oil & Gas Company, LP Blanco Mesaverde / Basin Dakota

RU W/L. RIH w/ gauge ring. Run GR/CCL/CBL Logs. TOC @ 2500'. 7" shoe @ 4/3/2012 Install Frac valve. PT csg to 6600#/30min. Test – OK. 5/1/2012 5/4/2012 RU W/L. Perf **Dakota** w/ .34" diam. - 2SPF @ 6570', 6574', 6578', 6580', 6584', 6588', 6590', 6594', 6598', 6600', 6604', 6608', 6610', 6614', 6618', 6620', 6624', 6626', 6630', 6632', 6636', 6640', 6642', 6646', 6650' = 50 Holes. Acidize w/ 10bbls 15% HCL. Frac w/ 36,162gals 85% SlickWater Form w/ 25,100# of 20/40 Arizona Sand. N2:4,711,000SCF. Set CBP @ 5200'. Perf Point Lookout w/ .34" diam. - 1SPF @ 4510', 4530', 4540', 4550', 4570', 4590', 4608', 4624', 4636', 4654', 4668', 4678', 4694', 4710', 4726', 4736', 4760', 4774', 4792', 4806', 4816', 4826', 4836', 4858', 4884' = 25 Holes. Acidize w/ 10bbls 15% HCL. Frac w/ 40,740gals 70% SlickWater w/ 100,574# of 20/40 Arizona Sand. N2: 1,273,000SCF. Set CFP @ 4490'. Perf **Menefee** w/ .34" diam. – 1SPF @ 4176', 4192', 4232', 4238', 4268', 4278', 4280', 4286', 4298', 4308', 4320', 4330', 4340', 4352', 4362', 4372', 4404', 4414', 4432', 4442', 4458', 4464' = 22 Holes. Acidize w/ 10bbls 15% HCL. Frac w/ 23,856gals 70% SlickWater Foam w/ 49,490# of 20/40 Arizona Sand. N2:964,000SCF. Start Flowback. ✓ 5/7/2012 RIH w/ CBP set @ 3950'. RD Flowback & Frac Equipment. 6/1/2012 MIRU KEY 28. ND WH. NU BOPE. PT BOPE. Test - OK. Tag 4 1/2" CBP set @ 3950' & D/O. CO & D/O CBP @ 4490'. Circ clean. 6/4/2012

6/1/2012 MIRU KEY 28. ND WH. NU BOPE. PT BOPE. Test – OK.

1 ag 4 ½" CBP set @ 3950' & D/O. CO & D/O CBP @ 4490'. Circ clean.

1 c/O to CBP @ 5200'.

2 c/O to CBP @ 6712'.

3 c/O to CBP @ 5200'.

3 c/O to CBP @ 6712'.

4 c/O to CBP @ 4490'. Circ clean.

5 c/O to CBP @ 4490'. Circ clean.