

RECEIVED

Form 3160-5
(April 2004)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JUL 23 2012

FORM APPROVED
OMB No 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
 BCO Operating
 Nacogdoches Oil and Gas Inc.

3a. Address
 816 North Street, Nacogdoches Texas, 75961

3b. Phone No. (include area code)
 936-560-4747

4. Location of Well (Footage, Sec, T, R, M, or Survey Description)
 630 FSL & 2060 FWL, Sec. 6 17N 8W

5. Lease Serial No
 NMNM-052931

6. If Indian, Allottee or Tribe Name
 Navajo

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
 Hanson 16

9. API Well No.
 3003120144

10. Field and Pool, or Exploratory Area
 Hospah

11. County or Parish, State
 McKinley County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

In reference to the December 21, 2011 letter, NOG drilled out a cement plug from 16' to 240' and circulated well clean to 2511' TD. Well was plugged on 7-2-2012 from 2511' to surface using 101 Sacks of Portland @ 15.1 ppg. Cement fell back and well was topped off with 16 sacks on 7-3-2012. Well casing will be cut off at 3 feet below ground, place PA Marker and location leveled, re-seeded per BLM rules.

RCVD JUL 25 '12
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct
 Name (Printed/Typed)

Mike Allen

Title Engineering

Signature *Mike Allen*

Date 07/12/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

JUL 23 2012

NMOCD

FARMINGTON FIELD OFFICE
 57