NMOCO

RECEIVED OTO FARMINGTON NM

V

District I ' PO. Box 1980, Hobbs, NM 88241-1980

District II PO Drawer DD, Antesia, NM 88211-0719

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV PO Box 2088, Santa Fe. NM 87504-2088

5286.60

State of New Mexico Energy, Minerals & Natural Resources Department

Revised February 21, 1994 Instructions on back

Certificate Number

Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088

AMENDED REPORT

Form C-102

30-045 32708 Pool Code 71629				ACREAGE DEDICATION PLAT  *Pool Name  BASIN FRUITLAND COAL						
Property 370k	Code		*Property Name HERRY MONSTER			ell Number · 90				
. 'OGRID I 00651	- 1			DUGAN	*Operator PRODUCTION	Name ON CORPORAT	ION	*Elevation 6606		
			•		<sup>10</sup> Surface					
UL or lotino.	Section 11	Township 24N	11W	Lat Idn	Feet from the	North/South line SOUTH	Feet from the 1400	East/Wes		SAN JUA
UL or lot no.	Section	11 E Township	Bottom	Hole L	ocation I	f Different	From Sur	face East/Wes	st line	County
Dedicated Acres	326	HO Acre	es - (S	6/2)	<sup>13</sup> Joint or Infill	<sup>14</sup> Consolidation Code	<sup>25</sup> Order No.			
140C		-09-A	5.3	11- UGAN 4-17015	APT 2005	i F	BY THE DIV  17 OPE I here contain to the Signatu  Printed  Title  Date  18 SURV I hereby shown or notes of my stown or notes of my sugard Survey Signatur	RATOR	CERTII  t Fag  ology  v. 20,  CERTII  t the well  eys made eys made f Profess  EDWA  MEXICO	FICATIOn formation of complete and belief and belief and belief and belief and belief and belief and formation and from field by me or under same is true belief.  ER 10, 200-ional Surveyor

Form 3160-5 (April 2004)

である。 「「「「「「「」」」」というでは、「「」」というでは、「「」」というでは、「「」」というでは、「「」」というでは、「「」」というできない。「」」というできない。「」」」
「「」」」というできない。「」」というできない。「」」
「「」」」」
「「」」」
「「」」」
「「」」」
「「」」」
「「」」」
「「」」
「「」」」
「「」」」
「「」」
「「」」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」」
「「」
「「」」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「「」
「

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OM B No. 1004-0137
Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.  SUBMIT IN TRIPLICATE- Other instructions on reverse side.  1. Type of Well Gas Well Other  2. Name of Operator Dugan Production Corp.  3a. Address 709 East Murray Drive, Farmington, NM 87401  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						5. Lease Serial No. NM-17015  6. If Indian, Allottee or Tribe Name  7. If Unit or CA/Agreement, Name and/or No.  8. Well Name and No. Herry Monster #90  9. JAPI Well No. 30-045- 32708  10. Field and Pool, or Exploratory Area Basin Fruitland Coal  11. County or Parish, State		
Sec.11, T24N, R11W. 1950' FSL &	1400' FWL, NMPM, Un	iit K, Lat. 36.1	934, Long:	100.5833		n County, NM		
12. CHECK APPRO	PRIATE BOX(ES) TO	INDICATE	NATURE	OF NOTICE,	REPORT, OR	OTHER DAT	'A	
TYPE OF SUBMISSION			TYPE	OF ACTION				
Notice of Intent  Subsequent Report  Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture T New Cons Plug and A Plug Back	struction Abandon	Production (St Reclamation Recomplete Temporarily A Water Disposal	bandon	Water Shut-	y nge to original	
<ol> <li>Describe Proposed or Completed Ope If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for final 1. Casing program will be characteristic.</li> </ol>	ally or recomplete horizontal will be performed or provoperations. If the operation and onment Notices shall be nal inspection.)	lly, give subsurfa vide the Bond No n results in a mul e filed only after	ace locations on file with tiple complet all requireme	and measured and tr h BLM/BIA. Requi- tion or recompletion ents, including reclan	ue vertical depths red subsequent re in a new interval	s of all pertinent meters shall be filed, a Form 3160-4 stormpleted, and the completed, and the completed of the complete	narkers and zones. d within 30 days hall be filed once	
Surface Casing	Hole Size Casing 11" 8-5/8"		Vt./ft. 24#	Setting Depth 120'	Grade J-55	RE FAR		
Production Casing All cement volumes will re	7" 5-1/2"	•	14#	1530'	J-55	RECEIVED FARMINGTON NH	1 80 11 49	
14. Thereby certify that the foregoing	; is true and correct				<del></del>			
Name (Printed/Typed)  Kurt Fagrelius			Title Geo	ologist				
Signature Kurt Fa	anti		Date	(	02/25/2005			
, Ti	HIS SPACE FOR	FEDERAL	OR ST	ATE OFFICE	USE		······································	
Approved by  Conditions of apphoval, if any, are attached certify that the applicant holds legal or equivilent would entitle the applicant to conditions.	uitable title to those rights			M.	eld D	ate 4	20 25	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## EXHIBIT B OPERATIONS PLAN

Herry Monster #90

#### APPROXIMATE FORMATION TOPS:

Total Depth	1380′
Pictured Cliffs	1225′
Fruitland	935′
Kirtland	400′
Ojo Alamo	325′

Catch samples every 10 feet from 1150 feet to total depth.

#### LOGGING PROGRAM:

Run cased hole GR-CCL-CNL from total depth to surface.

#### CASING PROGRAM:

Hole	Casing		Setting	Grade and
Size	Size_	Wt./ft.	Depth	Condition
9-7/8"	7"	20#	120'	J-55
6-1/4"	4-1/2"	10.5#	1380′	J-55

Plan to drill a 9-7/8" hole and set 120' of 7" OD, 20#, J-55 surface casing. Then plan to drill a 6-1/4" hole to total depth with gel-water mud program to test the Fruitland Coal. 4-1/2", 10.5#, J-55 production casing will be run and cemented. Cased hole GR-CCL-CNL log will be run. Productive zone will be perforated and fractured. After frac, the well will be cleaned out and production equipment will be installed.

#### CEMENTING PROGRAM:

Surface: Cement to surface with 70 cf Class B + 2% CaCl<sub>2</sub>. Circulate to surface.

Production Stage-Cement with 140 cf 2%lodense with

%# celloflake/sx followed by 70 cf Class "B" with

%# celloflake/sx.

Total cement slurry for production stage is 210 cf

Circulate cement to surface.

An adequate spacer will be pumped ahead of the cement slurry to help prevent mud contamination of the cement. An adequate number of casing centralizers will be run through usable water zones to ensure that casing is centralized through these zones. The adequate number of centralizers will be determined based on

API standards. Centralizers to impart a swirling action around the casing will be used just below and into the base of the lowest usable water zone. These devices will assist mud displacement, increase cement bonding potential and create an effective hydraulic seal. A chronological log will be kept which records the pump rate, pump pressure, slurry density, and slurry volume for the cement job. The log will be sent to the BLM after completion of the job.

#### WELLHEAD EQUIPMENT:

Huber 7"x4-1/2" casing head, 1000# WP, tested to 2000#. Huber 4-1/2"x2-7/8" tubing head, 1000# WP, tested to 2000#.

BOP and Related Equipment will include for a 2000 psi system:
(Exhibit D)

Annular preventer, double ram, or 2 rams with one being blind and one being a pipe ram.

Kill line (2" minimum)

- 1 kill line valve (2" minimum)
- 1 choke line valve
- 2 chokes

Upper kelly cock valve with handle available Safety valve and subs to fit all drill string connections in use.

Pressure gauge on choke manifold.

2" minimum choke line.


Fill-up line.

#### Contacts:

Dugan Prod.Corp. Office & Radio Dispatch: 325-1821

Mark	Brown	327-3632 320-8247	
Kurt	Fagrelius	325-4327 320-8248	
John	Alexander	325-6927 320-1935	

### EXHIBIT D.



**BOP DIAGRAM** 

BOP and Related Equipment will include for a 3000 pol system;

2000 PSI DOUBLE BAM BLOWOUT PREVENTER

Kill line (8" minimum)

l kill line valve (2" minimum)


Upper kelly cock valve with handle available

Safety valve and subs to fit all drill string connections in use

minimum choke line

7111-up 1184 above the uppermost preventer

BOP equipment will be tested as required in Section III A.1 of Onshore Order 2, plus a 30% safety factor.



**DUGAN PRODUCTION CORP. HERRY MONSTER #90**