BURLINGTON RESOURCES

San Juan Division - Drilling Program

In case of Major Emergency Call 911
Give the following information to Operator:
Well Name: San Juan 23-6 Unit 8211M County: Rio Arriba
Latitude: 36 degrees, 40.3228 minutes
State: NM
Longitude: 107 degrees, 28,8956 minutes
From the Post Office in Blanco, NM: Take Hwy 64 east for 22.8 miles. Turn right (southwesterly) for 1.96 miles. Turn right (southwesterly) for 1.90 miles. Turn right (run left for 650° of new access on the left side of the Turn left for 650° of new access.

| DK DP# |

Prepared: Jennifer McCarthy - Drilling Engir

Environmental, Health & Safety

Restrict'd Duty OSHA Rec 1st Aid

Official Community (see otherward Occupation community for datable)

ation Survey every 500', @ Bit Trips and @ TD

- Zero Spills on Location - Remove Trash from Roads and Locations

San Juan 28.6 Holt 1459 /HV/DK 2004 0.5 ml SW): Drilled later holo w/J SNID w/ 9.40MH E/4200/T/TD due to	

n <u>Juan 26-0 Unit (1998 (1971). C. V. S. III. SYY):</u> United inter note wit SNID wit S-10VIL F1 2007 If 1D due to epage. No tight hole or circulation problems while drilling. Pulled 30-40K over in Kulfand on short tip. Cmfd in 1-stg wi % excess, did not circ. Lost returns @ 40 bbls of displacement, regained @ 80, lost 95 & regained at 107 bbls out of 135

20 bbis. Cmfd in 1-stg w 110% excess. circ 74 bbts. N2 drilled Prod hole w no problems and cmfd LS w) 30% excess, activities (1000 coverlap.

San_Juan 28-5 Unit 147N LW/DK, 2002, 1.5 mil 5E); No surface problems. Drilled Inter hole w LLSND w < 10.0 WL. Had spitch to the cover of the cover o

Special Notes:
- Return well file with checksheets to Hollee

- Back up bit will be GT09C (2-13's) if 605Z is not performing
- Install drilling head rotating rubber once BHA is burried.
Use Weatherford/Gemoco float equipment for Production hole.
- Contact John White w/ Southwest Bit and Tool for PDC Bits (632-1452)
Reserve pits must be lined according to the APD.
 Call all proper regulatory agencies 24 hours in advance of BOP testing, spud, running csg, or cementing. Leave messa if after hours.

Approved:	 	