		hΛ				
Form 3160-5 (August 2007)	UNITED STA DEPARTMENT OF TH BUREAU OF LAND MA	ENTERIOR	JAN 23	· · · ·	OMB No.	PPROVED 1004-0137 Jy 31, 2010
		e⊣ Bure	armington Pland I	5. Lease Serial No.	SF.	.079266
SU	NDRY NOTICES AND REP			6. If Indian, Allottee		
	se this form for proposals d well. Use Form 3160-3 (RC	VD JAN 25'13
	SUBMIT IN TRIPLICATE - Other i	nstructions on page	2.	7. If Unit of CA/Ag	reement, Nap	kandena. DIV.
I. Type of Well Oil Well	8. Well Name and N	DIST 3 8. Well Name and No. Vaughn 32N ✓ 9. API Well No. Vaughn 32N ✓				
2. Name of Operator	9. API Well No.					
Burlington Resource	10 Field and Pool c	30-039-30983 ✔ 10. Field and Pool or Exploratory Area				
			326-9700		Blanco	WV/Basin DK 🖌
4. Location of Well (Footage, Sec., T. Surface Unit F (SE	.,R.,M., or Survey Description) /NW), 1790' FNL & 1740' F	FWL, Section 2	9, T26N, R6W	11. Country or Paris Rio Ar	sh, State riba∽,	New Mexico 🛩
	THE APPROPRIATE BOX(E	S) TO INDICATE			OR OTHER	R DATA
TYPE OF SUBMISSION			TYPE OF A	1		
Notice of Intent	Acidize	Deepen Fracture Treat	t I	Production (Start/Rest Reclamation	ume)	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construct		Recomplete		X Other Change of Plan
	Change Plans	Plug and Aba	ndon	Temporarily Abandon	ı	Deepen TD
I3. Describe Proposed or Completed	Convert to Injection	Plug Back		Water Disposal		
	for final inspection.)					
approx. 160' deeper on site. Deepening		be mud drilling s to test the End	the producti	on hole and will form better frac	l have a r k on the	nud logger entire DK zone.
approx. 160' deeper on site. Deepening	es requests permission to than permitted. We will t to this depth will allow us	be mud drilling s to test the End	the producti	on hole and will form better frac	l have a r k on the	nud logger
approx. 160' deeper on site. Deepening	es requests permission to than permitted. We will t to this depth will allow us	be mud drilling s to test the End	the producti	on hole and will form better frac ACC	l have a r k on the	nud logger entire DK zone. OR RECORC
approx. 160' deeper on site. Deepening	es requests permission to than permitted. We will t to this depth will allow us	be mud drilling s to test the End	the producti	on hole and will form better frac ACC FARM	I have a r k on the EPTED F JAN 2 (nud logger entire DK zone. OR RECORC 3 2013
approx. 160' deeper on site. Deepening to The cement volumes	es requests permission to than permitted. We will t to this depth will allow us s will be adjusted accord	be mud drilling s to test the End ingly.	the producti cinal and per	on hole and will form better frac ACC FARM	I have a r k on the EPTED F JAN 2 (NGTON F ILLICAM	nud logger entire DK zone. OR RECORD 2013 Tambelcon
approx. 160' deeper on site. Deepening to The cement volumes	es requests permission to than permitted. We will to to this depth will allow us s will be adjusted according g is true and correct. Name (Printed/A Arleen White	be mud drilling s to test the End ingly.	the producti cinal and per	on hole and will form better frac ACC FARMI BY	I have a r k on the EPTED F JAN 2 (NGTON F ILLICAM	nud logger entire DK zone. OR RECORD 2013 Tambelcon
approx. 160' deeper on site. Deepening to The cement volumes	es requests permission to than permitted. We will to to this depth will allow us s will be adjusted according g is true and correct. Name (Printed/A Arleen White	pe mud drilling s to test the End ingly.	the producticinal and per	on hole and will form better frac ACC FARMI BY Staff Reg	I have a r k on the EPTED F JAN 2 (NGTON F ILLICAM	nud logger entire DK zone. OR RECORD 2013 Tambelcon
approx. 160' deeper on site. Deepening of The cement volumes	es requests permission to than permitted. We will to to this depth will allow us s will be adjusted according g is true and correct. Name (Printed/A Arleen White	See mud drilling s to test the End ingly.	the producticinal and per	on hole and will form better frac ACC FARMI BY Staff Reg	I have a r k on the EPTED F JAN 2 (NGTON F ILLICAM	nud logger entire DK zone. OR RECORD 2013 Tambelson
approx. 160' deeper on site. Deepening of The cement volumes	es requests permission to than permitted. We will to to this depth will allow us s will be adjusted accord s will be adjusted accord g is true and correct. Name (Printed/A Arleen White MULL THIS SPACE F tached. Approval of this notice does to able title to those rights in the subject tions thereon.	be mud drilling to test the Endingly.	the productic cinal and per 1 = 2 - (1) OR STATE O Title Office	on hole and will form better frac ACC FARMI BY_L Staff Reg Staff Reg	I have a r k on the	nud logger entire DK zone. OR RECORC 2013 Tambelcon
approx. 160' deeper on site. Deepening of The cement volumes	es requests permission to than permitted. We will to to this depth will allow us s will be adjusted accord s will be adjusted accord g is true and correct. Name (Printed/A Arleen White MULL THIS SPACE F THIS SPACE F tached. Approval of this notice does a able title to those rights in the subject tions thereon. le 43 U.S.C. Section 1212, make it a	be mud drilling s to test the End ingly. <i>Typed)</i> Title Date FOR FEDERAL Not warrant or certify lease which would prime for any person ku	the productic cinal and per 1 = 2 - (1) OR STATE O Title Office	on hole and will form better frac ACC FARMI BY_L Staff Reg Staff Reg	I have a r k on the	nud logger entire DK zone. OR RECORC 2013 Tambelcon

٠.



DEVELOPMENT

PROJECT PROPOSAL - New Drill / Sidetrack

VAUGHN 32N

	ConocoPhillips
ick	San Juan Business Unit

AFE #: WAN.CDR.9336. Loase: AFE \$: 1,845,134,24 County: RIO ARRIBA Rig: Aztec Rig 920 API #: 3003930983 Field Namo: SAN JUAN State: NM Phone: Geologist: Phone: Geophysicist: Geosciontist: Phone: Prod. Engineer: Phone: Res. Engineer: Prol. Field Lead: Phone: Phone Primary Objective (Zones): Zone Name Zone FRR **BASIN DAKOTA (PRORATED GAS)** RON BLANCO MESAVERDE (PRORATED GAS) ** Datum Code: NAD 27 Location: Surface Straight Hole Longitude: -107.493656 Latitude: 36.459574 X: Y: Section: 29 Range: 006W Footage X: 1740 FWL Footage Y: 1790 FNL Elevation: 6764 (FT) Township: 026N Tolerance: Start Date (Est.): 1/1/2013 Location Type: Restricted Completion Date: Date In Operation: Formation Data: Assume KB = 6779 Units = FT SS MD Formation Call & Depth Depletion BHP BHT Remarks (Ft) (Yes/No) (PSIG) Casing Points (TVD in Ft) (Ft) Surface Casing 200' 9 5/8" 32.3 ppf, J-55, STC casing. Cement with 121 6579 200 cuft. Circulate cement to surface. OJO ALAMO 2290 4489 Γ **KIRTLAND** 2462 4317 ~ FRUITLAND 2549 4230 Possible Gas 3823 PICTURED CLIFFS 2956 LEWIS П 3057 3722 HUERFANITO BENTONITE \Box 3376 3403 CHACRA 3821 2958 П UPPER CLIFF HOUSE 4549 2230 П MASSIVE CLIFF HOUSE 4611 2168 П 446 **Cliffhouse Is Wet** MENEFEE 4627 2152 Г Est. Top Perf - 4827(1952) INTERMEDIATE CASING DEEP 4777 2002 П 132 8 3/4" Hole. 7", 23 ppf, J-55, LTC Casing. Cement with 929 cuft. Circulate cement to surface. SET POINT LOOKOUT 5200 1579 GAS П MANCOS 5531 1248 6281 498 UPPER GALLUP 7139 -360 П GREENHORN GRANEROS 7195 -416 П 7251 -472 П 2746 **TWO WELLS** Gas 7292 -513 PAGUATE UPPER CUBERO 7336 -5**57** П LOWER CUBERO Suggest mud drilling due to area wells getting condensate 7366 -587 wet in Gallup -614 OAK CANYON 7393 Est. Btm Perf - 7422 (- 643) based on offset wells ENCINAL TD - T/ENCN plus 160' which will be close to Morrison top -658 7437 this assumes mud drilling. **BURRO CANYON** -704 7483 If air drilled then go 50' into Encinal.

Printed on: 1/23/2013 3:52:20 PM





ConocoPhillips

San Juan Business Unit

÷.

				1)EVI	/ELOPMENT			
Total Depth	7597	-818		184	6.25" hole, 4-1/2" 11.6 ppf, L-80 LTC casing. Comunt wi 353 cuft. Circulate coment to inside 7" csg.			
MORRISON	7611	-832			· · · · · · · · · · · · · · · · · · ·			
Reference Well	5:							
Reference Type	Well Name		Comments					
roduction Vaughn 31		26N 6W 29 SE NW NE						
Production Vaughn 32M			26N 6W 29 SE NW NW					
Production Vaught 32			26N 6W 29 SW NE SW					
Intermediate Log	s: Log only if show [Triple Combo	,,,,,				
TD Logs:	Triple Combo	Dipmeter		/SP 🔲 T	TDT 🔽 Other			
TD Logs:	Cased Hole GR / CBL		RFT Sonic N					
TD Logs: Additional Inform	Cased Hole GR / CBL Muclog from 100' abo							

Printed on: 1/23/2013 3:52:20 PM