

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR RUBEAU OF LAND MANAGEMENT

DEC 11 2012

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT Farmington Field Off Lease Serial No. SUNDRY NOTICES AND REPORTS ON WEELS I Land Manage 1785-1078766 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Rosa Unit 1. Type of Well 8. Well Name and No. Rosa Unit #160 Oil Well Gas Well Other 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-039-25890 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-333-1806 Mesaverde 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State 1250' FSL & 790' FEL, sec 25, T31N, R6W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Well Integrity Reclamation Recomplete Other /Squeeze PC Casing Repair New Construction Subsequent Report Plug and Abandon Change Plans Temporarily Abandon Convert to Final Abandonment Notice Plug Back Water Disposal Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 11/1/12 - MIRU HWS #22. 11/2 thru 11/10/12 - TOOH with short string of tubing. TOOH with long string of tubing. Drill out packer and TOOH with 4-1/2" Arrow Model D packer at 3464'. RCVD JAN 25'13 OIL CONS. DIV. 11/12/12 - TIH with 7" RBP set at 3511'. 11/13/12 - TIH set CR at 3211'. Mix Cement with 4.98 gals fresh water per sack of cement, Start down well w/ 41 bbls (200 sacks) of Class G Cement with 2% H-9 at 15.8 ppg, pump at a rate of 1 bpm at 15 psi, hesitated & pump .5 bbls pressure came up to 848 psi, hesitate & pump .5 bbls pressure came up to 713 psi, dropped & stabilized @ 608 psi, pull stinger out Rev. Circ w/ 27 bbls of wtr, pumping 18.6 bbls of cement into FB Tank, pumped 14.4 bbls of cement into perforations. 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Ben Mitchell Title Regulatory Specialist Date 12/10/2012 Signatur ACCEPTED FOR THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title FARMINGTON F Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease BY which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of them.

(Instructions on page 2)

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

11/15 thru 11/16/12 - TIH to TOC at 3209'. Drill out cement from 3209'to sand on top of RBP at 3511', including CR at 3211'.

11/17/12 - TOOH with 7" RBP at 3511'.

11/18/12 - TIH and set 4-1/2" RBP at 5075'.

<u>11/19/12</u> – Test well from 5075' to surface. Per Jonathan Kelly with NMOCD need to test BH on WH, BH passed NMOCD Test, Antelope arrives RU Tester, load casing to 560 psi, hold for 30 Min, had a slight loss 5 psi in 30 min, well held solid. Per Jonathan Kelly well passed.

11/20/12 - TOOH with 4-1/2" RBP. Clean out well.

11/21/12 - Land well @ 6063' KB (12' KB) as follows: MS collar, 1 Jt of 2-3/8" 4.70# J-55 8RD EUE, 1.78" seating nipple, & 193 joints of 2-3/8" 4.70# J-55 8RD EUE production tubing. seating nipple @ 6031' (total of 194 joints).

11/23/12 - RDMO HWS #22.

ROSA UNIT #160 BLANCO MV

Location: 1250' FS & 790' FEL SW/4 SE/4 Section 25(O), T31N, R06W

Rio Arriba Co., NM

Elevation: 6438' GR API # 30-039-25890

Tops	Depth	
Kirtland	2655'	
Fruitland	3035	
Pictured Cliffs	3270'	
Cliff House	5445'	
Point Lookout	5705'	
Mancos	6220'	


STIMULATION: 9-30-98

<u>CliffHouse/Menefee</u> 5172' - 5616' (35, 0.38" holes) 78,000# of 20/40 sand in 2050 BBI's slick water.

Point Lookout 5678' - 6003' (50, 0.38" holes) 82,000# of 20/40 sand in 2790 BBI's slick water.

STIMULATION: 5-25-00

<u>Pictured Cliffs</u> 3299' - 3411' (20, 0.38" holes) 80,000# of 20/40 Az sand & 2100# 14/40 flex sand in 70Q foam & 30# x-link gel



Spud Date: 08/31/98 MV Completion Date: 10/01/98

TD @ 6220' PBTD @ 6185'

HOLE SIZE	CASING	CEMENT	VOLUME	СМТ ТОР
12-1/4"	9-5/8",36#	150 s x	180 cu.ft.	SURFACE
8-3/4"	7",20#	685 sx	B07 cu.ft.	SURFACE
6-1/4"	4-1/2", 10.5#	3 15 s x	451cu.ft.	3562'

