

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 25 2013

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

Farmington Field Office
Bureau of Land Management

5. Lease Serial No.

SF-077874

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐

Oil Well

☒

Gas Well

☐

Other

2. Name of Operator

Burlington Resources Oil & Gas Company LP

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Hanks 17

9. API Well No.

30-045-06781

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface UNIT N (SESW), 940' FSL & 1755' FWL, Sec. 5, T27N, R9W

10. Field and Pool or Exploratory Area

Basin Dakota

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☒

Notice of Intent

☐

Subsequent Report

☐

Final Abandonment Notice

TYPE OF ACTION

☐

Acidize

☐

Alter Casing

☐

Casing Repair

☐

Change Plans

☐

Convert to Injection

☐

Deepen

☐

Fracture Treat

☐

New Construction

☐

Plug and Abandon

☐

Plug Back

☐

Production (Start/Resume)

☐

Reclamation

☒

Recomplete

☐

Temporarily Abandon

☐

Water Disposal

☐

Water Shut-Off

☐

Well Integrity

☐

Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plans are to recomplete this well in the Mesaverde formation and then DHC the existing Dakota with the Mesaverde. Attached is the MV plat and procedure. The DHC application will be submitted and approved before the work proceeds.

OIL CONS. DIV DIST. 3

JAN 30 2013

** Submit CSL for Agency review prior to parts*

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Denise Journey

Regulatory Technician

Title

Signature

Denise Journey

Date

1/24/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

JAN 28 2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOC

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico**Energy, Minerals and Natural Resources****Oil Conservation Division****1220 S. St Francis Dr.****Santa Fe, NM 87505**

Form C-102
August 1, 2011

Permit 160983

RECEIVED**JAN 25 2013**

Farmington Field Office

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-045-06781	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 7082	5. Property Name HANKS	6. Well No. 017
7. OGRID No. 14538	8. Operator Name BURLINGTON RESOURCES OIL & GAS COMPANY LP	9. Elevation 6511

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
N	5	27N	09W		940	S	1755	W	SAN JUAN

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 334.48 <i>W/2</i>		13. Joint or Infill		14. Consolidation Code		15. Order No.			

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OPERATOR CERTIFICATION <i>I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.</i> E-Signed By: <i>Patsy Clugst</i> Title: Sr. Regulatory Specialist Date: 1/17/13		
	SURVEYOR CERTIFICATION <i>I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.</i> Surveyed By: Ernest Echohawk Date of Survey: 5/19/1960 Certificate Number: 1545		



Hanks 17

Unit N, Section 5, Township 27N, Range 9W

API#: 3004506781

Mesa Verde Recompletion

1/15/2013

Procedure:

1. MIRU service rig. TOOH and lay down current production tubing string.
2. Wireline set a 4-1/2" composite bridge plug @ 6,700' above the existing Dakota completion.
3. Run a GR/CCL/CBL correlation log. The GR will be used to pick formation tops and the CBL will be used to pick the TOC.
4. ND well head & NU frac valve. Pressure test frac valve and casing.
5. Complete the Mesa Verde formation.
6. Flow back well to clean-up.
7. RIH with wireline and set a composite bridge plug above top perf.
8. TIH with a mill and drill out the top composite plug. Flow test MV up the casing.
9. Drill out the CBP set above the DK @ 6,700' and clean out to PBTD @ 7,105'
10. Flow test entire wellbore up the casing.
11. TIH and land production tubing.
12. Release service rig and turn over to production.

CURRENT SCHEMATIC

ConocoPhillips

HANKS #17

District	Field Name	API / UWI	County	State/Province	Edit
Original Spud Date	Surface Legal Location	E/W Dist (ft)	E/W Ref	N/S Dist (ft)	N/S Ref

Well Config: - Original Hole, 1/15/2013 11:04:12 AM

