Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APP	ROVEL
QMB NO. 10	004-013
Expires: July	31,201

,	Lease	Seri	al	No.
	NMN	M60	38	30

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM6680				
			6. If Indian, Allotto				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/A	7. If Unit or CA/Agreement, Name and/or No.			
Type of Well			8. Well Name and I DOME RUSTY	8. Well Name and No. DOME RUSTY 24-22-7 #1			
2. Name of Operator Contact: ALIPH REENA DUGAN PRODUCTION CORPORATION CORPORATION all aliph.reena@duganproduction.com			9. API Well No. 30-043-2032	9. API Well No. 30-043-20320-00-S1			
3a. Address	10. Field and Pool,	or Exploratory					
FARMINGTON, NM 87499							
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Paris	11. County or Parish, and State			
Sec 24 T22N R7W NWSE 184 36.122253 N Lat, 107.523944	SANDOVAL	COUNTY, NM					
12. CHECK APPR	ROPRIATE BOX(ES) TO INDIC	CATE NATURE OF N	NOTICE, REPORT, OR OTH	IER DATA			
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize ☐	<b>]</b> Deepen	☐ Production (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing ☐	Fracture Treat	☐ Reclamation	■ Well Integrity			
Subsequent Report	Casing Repair	New Construction	□ Recomplete	Other -			
☐ Final Abandonment Notice	Change Plans	3 Plug and Abandon	☐ Temporarily Abandon	•			
BP .	☐ Convert to Injection ☐	7 Plug Back	■ Water Disposal	☐ Water Disposal			
Attach the Bond under which the wor following completion of the involved	ally or recomplete horizontally, give subs it will be performed or provide the Bond operations. If the operation results in a nandonment Notices shall be filed only after and inspection.)	No. on file with BLM/BIA multiple completion or reco	Required subsequent reports shall mpletion in a new interval, a Form 3	be filed within 30 days 3160-4 shall be filed once			
The well was plugged and aba	andoned on 1/10/13 as per the fol	llowing procedure:	·				
1) Set CR @ 1619'. Spot Plug I w/16 sks (18.9 cu ft) Class B cement w/2% CaCl2. Wait on cement.  RCVD JAN 29 '13							
2) Test casing to 600 psi for 5	mins, held ok.			CONS. DIV. DIST. 3			
3) Spot Plug II w/52 sks (61.4 cu ft) Class B neat cement @ 1301' to top of cement @ 629' (629'-1301').							
4) Perforated @ 150'. Could not pump into the perforations. Spot Plug from 200' w/24 sks Class B neat (28.3 cu ft) to surface.							
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #189407 verified by the BLM Well Information System  For DUGAN PRODUCTION CORPORATION, sent to the Farmington  Committed to AFMSS for processing by STEVE MASON on 01/25/2013 (12SXM0300SE)							
Name (Printed/Typed) ALIPH RE	ENA	Title PRODU	CTION ENGINEER				
•							
Signature (Electronic S	ubmission)	Date 01/24/20	)13				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
_Approved By ACCEPT	ED	STEPHEN TitlePETROLE	MASON JM ENGINEER	Date 01/25/2013			
onditions of approval, if any, are attached. Approval of this notice does not warrant or criffy that the applicant holds legal or equitable title to those rights in the subject lease hich would entitle the applicant to conduct operations thereon.  Office Farmington							
Title 18 U.S.C. Section 1001 and Title 43 V States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for tatements or representations as to any ma	any person knowingly and atter within its jurisdiction.	willfully to make to any department	or agency of the United			


## Additional data for EC transaction #189407 that would not fit on the form

## 32. Additional remarks, continued

5) Cut wellhead. Tag TOC @ surface. Install dry hole marker.

## P & A Schematic

Dome Rusty 24-22-7 # 001, Rusty Chacra 300-43-20320 1840' FSL & 1520' FEL S24 T22N R7W



7" J-55 20# casing @ 100' -

Perforate @ 150'. Spot plug w/ 24 sks Class B (28.3cu.ft) neat from 200' to surface. Tag TOC @ surface.

Set plug w/ 52 sks (61.4 cu.ft) Class B neat cement. (629'-1301').

CR @ 1619'. Set Inside Plug @ 1619' with 16 sks (18.9 cu.ft) Class B w/ 2 % CaCl<sub>2</sub>. Tag TOC @ 1474'. (Plug I - 1474'-1619').

Rusty Chacra Perforated @ 1650' - 1699'

4 ½" 9.5 # casing @ 1980'.