Submit 3 Copies To Appropriate District Office.	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II	•		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-21097 5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-10400-1
	ICES AND REPORTS ON WELL	S	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Atlantic D Com K
1. Type of Well: Oil Well Gas Well Other P&A		8. Well Number 12	
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538 10. Pool name or Wildcat
3. Address of Operator P.O. Box 4289, Farmington, NM 87499-4289		Blanco Pictured Cliffs	
4. Well Location			
Unit Letter O _ : 115	66feet from theSouth	line and 180	0feet from theEastline
Section 36		Range 10W	NMPM San Juan County
	11. Elevation (Show whether DI	R, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check A	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORI			
TEMPORARILY ABANDON			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ΓJOB □
DOWNHOLE COMMINGLE			
OTHER: 🔲		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dat			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
1/17/13 Contacted Brandon Powell/OCD after running CBL. Requested permission to add 3sx cmt to Plug 1. Verbal OK			
1/18/13 Contracted Brandon/OCD requested perm to split Plug 3, set inside plug for 3A & continue to 3B. Verbal OK			
1/22/13 Contacted Brandon/OCD re procedure change for Plug 5. Requested perm to perf @ 148', pump down csg. Verbal OK			
The subject well was P&A'd on 1/23/13 per the notifications above & the attached report.			
NOVU: LU-C LAP			
			OIL CONS. DIV. DIST. 3
Spud Date:	Dia Pel	eased Date:	
Spud Date.	Kig Koi	eased Bate.	
I hereby certify that the information above is <u>true</u> and complete to the best of my knowledge and belief.			
SIGNATURE /	V Ousse TITLE_	Staff Regulatory	Technician DATE 2/1/13
Type or print name			
For State Use Only			
		Deputy Oil & C	as inspector,
APPROVED BY:	TITLE_	Distri	ct #3 DATE 2-4-13
Conditions of Approval (if any):	Δ,		

A

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Atlantic D Com K #12

January 23, 2013 Page 1 of 2

1156' FSL and 1800' FEL, Section 36, T-31-N, R-10-W San Juan County, NM Lease Number: B-10400-1 API #30-045-21097

Plug and Abandonment Report Notified NMOCD and BLM on 1/15/12

Plug and Abandonment Summary:

- **Plug #1** with 8 sxs (9.44 cf) Class B cement inside casing from 3244' to 2954' to cover the Pictured Cliffs top.
- Plug #2 with 40 sxs (47.2 cf) Class B cement from 2867' to 2709' with 2 sxs below, 35 sxs in annulus and 3 sxs above in casing to cover the Fruitland top.
- **Plug #3a** with 51 sxs (60.18 cf) Class B cement from 2070' to 2005' with 4 sxs above, 2 sxs below, 45 sxs in annulus to cover the Ojo Alamo and Kirtland tops.
- **Plug #3b** with 33 sxs (38.94 cf) Class B cement inside casing from 1913' to 1521' with 11 sxs above, 2 sxs below and 20 sxs in annulus to cover the Ojo Alamo and Kirtland tops.
- **Plug #4** with 40 sxs (35.4 cf) Class B cement inside casing from 721' to 563' with 35 sxs outside, 2 sxs below and 3 sxs above to cover the Nacimiento top.
- **Plug #5** with 57 sxs (67.26 cf) Class B cement inside casing from 148' to surface squeeze 1 sxs cement shut in well with 300 PSI to cover the surface casing shoe.
- Plug #6 29 sxs Class B cement found cement in 8-5/8" casing x 2-7/8" casing 1' from surface and install P&A marker.

Plugging Work Details:

- 1/16/13 Road rig and equipment to location. RU. Perform A-Plus Rig 6 well inspection. SDFD.
- 1/17/13 Check well pressures: no tubing, casing 100 PSI, bradenhead 0 PSI. RU relief lines. NU BOP. Note: was able to keep master valve shut and nipple up BOP and keep well blowing down. Was not able to test BOP due to wellhead. X-over to 1-1/4" handling equipment. PU 1-1/8" gauge ring and RIH to 3264'. PU 2-7/8" CIBP and TIH to 3244'. Tally and TIH openended with 1-1/4" IJ to CIBP at 3244'. Establish circulation. Pressure test casing to 1000 PSI for 10 minutes, OK. SI well. SDFD.
- 1/18/13 Open up well; no pressures. RU Basin Wireline. Ran CBL from 3244' to surface. Found TOC at 3010' and ratty cement to surface. TIH with 1-1/4" tubing 49 stands PU 1 joint and 1 6' sub (99 joints, 1-6' sub) open ended to 3244'. Spot plug #1 with estimated TOC at 2954'. Perforate 3 HSC holes at 2877'. Establish rate of 5.5 bpm at 500 PSI. RIH 2-7/8" CR set at 2817'. PU 2-7/8" stinger, TIH. Establish rate of 1.5 bpm at 700 PSI. Spot plug #2 with estimated TOC at 2709'. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Atlantic D Com K #12

January 23, 2013 Page 2 of 2

Plugging Work Details (continued):

- 1/21/13 Open up well; no pressures. Perforate 3 bi-wire holes at 2200'. Establish rate of 0.5 bpm at 1500 PSI, bled off 200 PSI in a minute. Note: V. Montoya, COPC and B. Powell, NMOCD approved procedure change. TIH open-ended 32 stands PU 6 joints (70 joint). Establish rate of 2 bpm at 500 PSI. TIH and set CR at 2150'. Establish rate of 2 bpm at 700 PSI. Spot plug #3a with estimated TOC at 2005'. Perforate 3 HSC holes at 1970'. Establish rate of 2.5 bpm at 500 PSI. TIH set CR at 1920'. Spot plug #3b with estimated TOC at 1521'. SI well. SDFD.
- 1/22/13 Open up well; no pressures. Perforate 3 Bi-wire holes at 721'. Establish rate of 3 bpm at 500 PSI. TIH set CR at 671'. Spot plug #4 with estimated TOC at 563'. Perforate 3 Bi-wire holes at 140'. Monitor for gas, no gas. Establish circulation. Spot plug #5 with estimated TOC at surface. SI well. SDFD.
- 1/23/13 Open up well; no pressures. RU High Desert. Dig out wellhead and cut wellhead off with saw. Found cement down 7" casing and down 1' in annulus surface. Spot plug #6 and install P&A marker. RD &MOL.

Paul Wiebe, NMOCD representative, was on location. Vic Montoya, MVCI representative, was on location. Teddy Rodriguez, COPC representative, was on location.