

RECEIVED

Form 3160-5
(August 2007)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

MAR 08 2013

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010Farmington Field
Bureau of Land Management

SF-080469

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well☒ Gas Well☐ Other

2. Name of Operator

ConocoPhillips Company

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface UNIT E (SWNW), 1850' FNL & 1190' FWL, Sec. 2, T29N, R11W

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

FEDERAL E COM #1

9. API Well No.

30-045-08759

10. Field and Pool or Exploratory Area

Basin Dakota

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☒ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing Repair☐ New Construction☐ Recomplete☒ Other Tubing Repair☐ Change Plans☐ Plug and Abandon☐ Temporarily AbandonSundry☐ Final Abandonment Notice☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

2/28/13 - MIRU AWS 993. ND WH. NU BOPE. PT BOPE. TEST OK. TOO H w/ 2 3/8" tubing. CO to PBTD @ 6,631'.

3/5/13 - TIH w/ 290 jts., 2 3/8", 4.7#, J-55 tubing, set @ 6,522" (new setting depth), w/ FN @ 6,520'. ND BOPE. NU WH. PT tubing to 500#. Test OK. RD RR @ 17:30 hrs on 3/6/13.

RCVD MAR 18 '13
OIL CONS. DIV.
DIST. 3


14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Denise Journey

Title

Regulatory Technician

Signature



Date

3/7/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

MAR 14 2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE
FV Sr

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

INVOICED