RECENED

Form 3150-5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR

MAY 03 20113

PORMATIKOVE	1.)
OMB No. 1004-01	37
Expires: October 31	, 2014

BUREAU OF LAND MANAGEMENT Lease Serial No SUNDRY NOTICES AND REPORTS ON WELLS of Land Mana gelfindian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-2 (ABD) form abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Salazar #10 Oil Well Gas Well Other 2. Name of Operator McElvain Energy Inc. 9. API Well No 5 30-039-2376 5 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No. (include area code) 1050 17th Street, Suite 2500, Denver, Co, 80265 Otero Chacra, South Blanco PC 303-893-0933 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1830 FSL & 1820 FWL, Sec 22, 125N R6W, Rio Arriba Co. NM 11. County or Parish, State Rio Arriba, New Mexico 12. CHECK THE APPROPRIATE BOX(ES), TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen . Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Subsequent Report Plug and Abandon ___ Change Plans Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Chacra perfs 3412-3529, PC perfs 2577-2680. Commingle order has been approved.. During well bore commingle operations a casing leak between 1867 and 1897 was encountered. Tubing and packer was run with the packer at 1958 and tubing set at 3476. McElvain Energy plans to pull the tubing and packer. Run a retrievable bridge plug at 1958. Set cement retainer at 1800. Squeeze casing leak with 50 sx class II cement to 1500 psi. Drill out cement squeeze and pressure test casing. Retrieve bridge plug. Run tubing open ended to 3476. Swab well in and return to production as a commingled PC/Chacra producer. RCVD MAY 7 '13

E A CBL is required after the Squeeze

A Groudwater investigation well may also be required.

OIL CONS. DTU. DIST. 3

District Engineer		
05/02/2013		
OR STATE OFFIC	E USE	
Title	Date	· · · · · · · · · · · · · · · · · · ·
Office		
	OR STATE OFFIC	O5/02/2013 OR STATE OFFICE USE Date Date

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.