Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	ΛPP	RO'	VED
OMB N	0.10	004-	0135
Expires:	July	31.	2010

SUNDRY NOTICES AND REPORTS ON WELLS			NMSF078905			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name EASTERN NAVAJO		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No. 892000844F		
Type of Well Oil Well	8. Well Name and No. GALLEGOS CANYON UNIT 216E					
Name of Operator BP AMERICA PRODUCTION	9. API Well No. 30-045-24271-00-S1					
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401		3b. Phone No. (include area code Ph: 281-366-7148	10. Field and Pool, or Exploratory BASIN			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State		
Sec 14 T28N R12W NESE 1825FSL 0805FEL 36.659880 N Lat, 108.074270 W Lon				SAN JUAN COUNTY, NM		
12. CHECK APP	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☐ Notice of Intent ☐ Acidize ☐ Alter Casing		☐ Deepen ☐ Produc ☐ Fracture Treat ☐ Reclan		tion (Start/Resume)		
Subsequent Report	Casing Repair	■ New Construction	□ Recom	plete	Other	
☐ Final Abandopment Notice	☐ Change Plans	□ Plug and Abandon	□ Tempo	☐ Temporarily Abandon Workover Oper		
<u>BP</u>	☐ Convert to Injection	☐.Plug Back	☐ Water l	☐ Water Disposal		
13. Describe Proposed or Completed Op	eration (clearly state all pertine	nt details, including estimated starting	ne date of any r	proposed work and appro-	ximate duration thereof.	

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP America would like to submit the daily operation summaries for the subject well. The document attached has the details of the workover operations for March and April 2013.

If perforations are above or below

existing perfs please file: c-104 and Completion Report to include new perfs before returning to production.

RCVD MAY 7'13 OIL CONS. DIV. DIST. 3

14. I hereby certify that the	te foregoing is true and correct. Electronic Submission #206013 verifie	d by the	BLM Well In	formation System	etion ot to	1 Dapon	
For BP AMERICA PRODUCTION CO, sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 05/03/2013 (13SXM1509SE)							
Name (Printed/Typed)	TOYA COLVIN	Title	REGULAT	ORY ANALYST			
Signature	(Electronic Submission)	Date	05/02/2013	3			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By. ACC	CEPTED		TEPHEN MA	ASON I ENGINEER		Date 05/03/2013	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Farmington				
	and Title 43 U.S.C. Section 1212, make it a crime for any peor fraudulent statements or representations as to any matter w			ifully to make to any depar	tment or agen	ey of the United	

Recompletion Activities for the GCU 216E - March and April 2013

March 2013

3/26/2013- LOAD OUT UNIT AND EQUIPMENT, MOVE TO THE GCU 216E, SPOT EQUIPMENT, LAY 3" LINE AND BLOW WELL DOWN, RIG UP NIPPLE DOWN WELL HEAD, NIPPLE UP BOP, SHELL TEST

3/27/2013- PRESSURE TEST BOP, PULL TBG HANGER AND 2WC, TAG FOR FILL EST TOP OF FILL @ 6360', TRIP OUT OF HOLE, M/U SCRAPER AND TRIP IN HOLE

3/28/2013- FINISH TRIPPING IN HOLE WITH SCRAPER, LAY DOWN PIPE, RIG UP FRAC VALVE AND E-LINE LUB, PRESSURE TEST LUBE AND VALVE, SET CIBP @ 6070', LOAD HOLE

3/29/2013- PRESSURE TEST CSG, NIPPLE DOWN BOP, CHANGE OUT TBG HEAD AND TEST, NIPPLE UP FRAC STACK AND TEST, MIT CSG (LOW TEST, STAGE UP TO 1000PSI AND HOLD FOR 15 MIN, STAGE UP TO 2000PSI AND HOLD FOR 15 MIN, STAGE UP TO 3000PSI AND HOLD FOR 15 MIN, STAGE UP TO 3800PSI AND MIT CSG FOR 30 MIN, PASS)

April 2013

4/01/2013- RUN LOGS, RIG DOWN AND PREP TO MOVE.

4/22/2013- JSEA MI SPOT FRAC TANKS 5654, 5657, 5656, 5646

4/27/2013- JSEA MIRU E&P, E-LINE RU ACCUMILATOR & TEST, PT LUB, RIH 3.75 GR TO 5720FT POH SPOT FLOWBACK TANK, RIH $1^{\rm ST}$ PERF GUN & PERF 5693'-5705' POH, RIH $2^{\rm ND}$ PERF GUN & PERF 5680'-5693', POH, RD E-LINE, RU FLOWBACK LINE & CHOKE MANAFOLD, PT, RD SECURE WELL

4/30/2013- JSEA MI-SPOT SAND MASTER & LOAD 100000# 20/40 BROWN SAND, SECURE LOCATION, WELL READY FOR FRIDAY FRAC.