

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or reenter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

RECEIVED

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 1996

MAY 16 2013

Lease Serial No.

NM 86082

Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SG Interests I, Ltd, c/o Nika Energy Operating, LLC

3a. Address

PO Box 2677, Durango, CO 81301

3b. Phone No. (include area code)

(970) 259-2701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1214' FNL, 1503' FEL (NWNE) Sec 5, T26N-R12W

8. Well Name and No.

WEST BISTI 26-12-5 #1

9. API Well No.

30-045-29040

10. Field and Pool, or Exploratory Area

Basin Fruitland Coal

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Temporarily Abando

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☒ Plug & Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operations (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once Testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

MIRU. Bradenhead press & CP 0 psi. TIH w/2 jts 2-3/8" tbg to tag fill to 1293.58' KB PBTD, show no fill. Pumped 3 bbls fresh water spacer, pump 13 sx type G cmt, 3 bbls @ 15.9#. TOOH w/40 jts 2-3/8" tbg, mule shoe. Let cmt set for 2 hrs. RIH w/junk basket to depth of 890' KB, tagged fluid then went to 1100' KB. Tagged cmt. POOH w/junk basket. RIH to 1025' KB to set 4-1/2" CIBP. TIH w/13 jts 2-3/8" tbg to depth of 410' KB. pumped 1 bbl fresh water spacer, pumped 45 sx type G cmt, 9 bbls @ 15.9 # with hose from 300' KB to surface. RD @ 3:30 p.m. 3/26/13. Installed P&A marker 3/27/13, waiting on orders from NAPI, NMOCD & BLM to totally reclaim location. (BLM rep Jamie Joe on location during P&A).

RCVD MAY 23 '13
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

William Schwab III

Title

Agent for SG Interests I Ltd

Date

May 14, 2013

Approved by

Title

Date

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

ACCEPTED FOR RECORD

MAY 21 2013

FARMINGTON FIELD OFFICE

NMOCD Ar