m 3160-5 JUNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT JUN 142	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007
	5. Lease Serial No.
SUNDRY NOTICES AND REPORTS ON WELLSigton Field Do not use this form for proposals to drill or to recenter and Ma abandoned well. Use Form 3160-3 (APD) for such proposals.	an agelfindian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.	7. If Unit or CA/Agreement, Name and/or No.
Type of Well Gas Well Other	8. Well Name and No.
Name of Operator Coleman Oil & Gas, Inc.	Clinton #1 9. API Well No.
Address 3b. Phone No. (include area code)	30-045-30694
P.O. Drawer 3337, Farmington NM 87499 505-327-0356 Location of Well (Footage, Sec., T., R., M., or Survey Description)	10. Field and Pool, or Exploratory Area Gallegos Fruitland Sand - PC
1800' FSL, 760' FWL L, Section 24, T26N, R12W Latitude 36.471389°, Longitude 108.069444°	11. County or Parish, State
	San Juan, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
Notice of Intent Acidize Deepen Production (S Notice of Intent Alter Casing Fracture Treat Reclamation Subsequent Report Casing Repair New Construction Recomplete	Start/Resume) Water Shut-Off Well Integrity
✓ Subsequent Report Casing Repair New Construction Recomplete Final Abandonment Notice Convert to Injection Plug Back Water Dispose	Abandon
3. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including real	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requ	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.)	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CON5. DIV. DIST. 3
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment.	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement.	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 *13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclar determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7"	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requ following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requ following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requ following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Requ following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 OIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig. " casing annulus with cement.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclar determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001 4. Thereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>)	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 OIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig. " casing annulus with cement.
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recta determined that the site is ready for final inspection.) MIRU A-Plus Well Service: Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001 4. Thereby certify that the foregoing is true and correct Name (<i>Printed/Typed</i>) MICHAEL T. HANSON Title OPERATIONS ENCLOSED	true vertical depths of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 DIL CONS. DIV. DIST. 3 . Shut well in with 1000 psig. " casing annulus with cement. GINEER
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Atach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (140.42 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001 4. Thereby certify that the foregoing is true and correct Name (<i>PrintedTyped</i>) Title MICHAEL T. HANSON Title OPERATIONS ENC Signature Date U/2/2 Put Septex by Cortify that the foregoing is true and correct Name (<i>PrintedTyped</i>) Date U/2/2 MICHAEL T. HANSON Title OPERATIONS ENC Signature Date U/2/2 Put Septex by Cortify that the foregoing is true and correct Name (<i>PrintedTyped</i>) Title	Introduction of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '13 OIL CONS. DIV. DIST. 3 Shut well in with 1000 psig. " casing annulus with cement. GINEER CONSER
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and Atach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Require following completion of the involved operations. If the operation results in a multiple completion or recompletion testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including recla determined that the site is ready for final inspection.) MIRU A-Plus Well Service. Plugged and Abandoned Clinton #1, see the following attachment. Plug #1 119 Sacks (140.42 cu ft) Class B Cement, Filled 4 1/2" Production Casing with Cement. Plug #2 21 Sacks (24.78 cu ft) Class B Cement, Topped off 4.5" production casing and 4.5" x 7" Installed Dry Hole Marker SPUD WELL SEPTEMBER 26, 2001 RELEASED ROTARY TOOLS SEPTEMBER 28, 2001 4. Thereby certify that the foregoing is true and correct Name (<i>PrintedTyped</i>) Title OPERATIONS ENV Signature MICHAEL T. HANSON Title OPERATIONS ENV Signature Date U12/2 THIS SPACE FOR FEDERAL OR STATE OFFIC Title	Introduction of all pertinent markers and zones. uired subsequent reports shall be filed within 30 days on in a new interval, a Form 3160-4 shall be filed once amation, have been completed, and the operator has RCVD JUN 19 '1.3 OIL CONS. DIV. DIST. 3 Shut well in with 1000 psig. " casing annulus with cement. GINEER GINEER DIST. SUSE JUN 1 '4 ZUIS Date FARMATION FIELD OFFIC W

調査

「読み」を言いていて



A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Coleman Oil & Gas, Inc. Clinton #1

March 19, 2013 Page 1 of 1

1800' FSL and 760' FWL, Section 24, T-26-N, R-12-W San Juan County, NM Lease Number: NO-G-9909-1359 API #30-045-30694

Plug and Abandonment Report Notified NMOCD and BLM on 3/15/13

Plug and Abandonment Summary:

Plug #1 mix 119 sxs Class B cement with 1/4# of cello flake, pump 10 sxs cement then drop 16 frac balls and pump the remaining 109 sxs and circulate to surface. SI well with 1000 PSI.


Plug #2 with 21 sxs (24.78 cf) Class B cement found cement in 4.5" casing down 2' and in 7" x 4.5" down 86'. To top off casings. Install P&A marker.

Plugging Work Details:

3/18/13 Road equipment to location. RU. J. Joe, BLM approved previous bradenhead pressure test. Pump 22 bbls of water ahead at 4bpm 0 PSI. Spot plug #1 mix 119 sxs Class B cement with ¼# of cello flake, pump 10 sxs cement then drop 16 frac balls and pump the remaining 109 sxs and circulate to surface. SI well with 1000 PSI. RD pump. SDFD.

3/5/13 Write and Perform Hot Work Permit. Cut off wellhead. Found cement in 4.5" casing down 2' and in 7" x 4.5" down 86'. To top off casings. Install P&A marker. RD & MOL.

COLEMAN OIL GAS, INC. CLINTON #1



MICHAEL T. HANSON

3

6/12/2013