

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB NO. 1004-0137
Expires July 31, 2010

JUL 01 2013

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

Farmington Field Office
Bureau of Land Management

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

XTO ENERGY INC

3a. Address

382 CR 3100 AZTEC, NM 87410

3b. Phone No. (include area code)

505-333-3630

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

737' FNL & 1686' FWL NENW Sec. 8 (C) - T30N-R12W N.M.P.M.

5. Lease Serial No.

NMNM-0498

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

FEDERAL 8 #3

9. API Well No.

30-045-30528

10. Field and Pool, or Exploratory Area

AZTEC PC/BASIN FC

FLORA VISTA FS

11. County or Parish, State

SAN JUAN

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
- ☒ Subsequent Report
- ☐ Final Abandonment Notice

TYPE OF ACTION

- | | | | |
|-----------------------------------------------|------------------------------------------------------|----------------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input type="checkbox"/> Other _____ |
| <input type="checkbox"/> Change Plans | <input checked="" type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. has plugged and abandoned this well per the attached report.

OIL CONS. DIV DIST. 3

JUL 05 2013

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

SHERRY J. MORROW

Title REGULATORY ANALYST

Signature

Date 6/27/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

JUL 02 2013

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMUCD A

Federal 08-03 (PA)

6/13/2013 MIRU rig & equip. SDFN. Notified BLM & OCD to P&A @ 9:30 a.m. 6/13/2013.

6/14/2013 TOH rods & pmp. TOH 2-3/8", 4.7#, J-55, 8rd, EUE tbg. Plug #1 w/12 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Cmt plg fr/2,110' - 1,952'. Mark Decker w/BLMon loc.

6/17/2013 TIH CICR. Set CICR @ 1,599'. Plug #2 w/24 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Cmt plg fr/1,599' - 1,283'. MIRU WLU. Perf 3 sqz holes @ 678' per BLM COA. Att to EIR into sqz holes w/no results. Press to 900 psig. Rec verbal approval fr/Mark Decker, Steve Mason w/BLM & Brandon Powell w/NMOCD to perf sqz holes @ 576' (50' below Ojo Alamo top) & fill csg fr/sqz holes @ 678' - surf & sqz cmt into sqz holes @ 576'. Perf 3 sqz holes @ 576'. Plug #3 w/76 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). Circ gd cmt fr/csg vlvs. Mark Decker w/BLM on loc.

6/18/2013 Cut off WH. Found TOC in 4-1/2" csg & 4-1/2" x 7" ann @ surf. Set BH marker w/14 sx Type B cmt (mixed @ 15.6 ppg, 1.18 cu ft/sx). RDMO. Mark Decker w/BLM on loc.