Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013
Evnice: July 31, 201

SUNDRY Do not use the abandoned we	Lease Serial No. NMSF078096 If Indian, Allottee or Tribe Name							
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. SCR465							
i. Type of Well ☐ Oil Well ☒ Gas Well ☐ Otl	8. Well Name and No. NEAL COM 2E							
2. Name of Operator BP AMERICA PRODUCTION	9. API Well No. 30-045-25893-00-S1							
3a. Address 501 WESTLAKE PARK BLVD HOUSTON, TX 77079	b. Phone No. (inclu h: 281-366-714	o. (include area code) 66-7148		10. Field and Pool, or Exploratory BASIN DAKOTA				
4. Location of Well (Footage, Sec., 7		11. County or Parish, and State						
Sec 14 T31N R11W SWSE 08 36.893402 N Lat, 107.956253	350FSL 1730FEL W Lon		SAN JUAN COUNTY, NM					
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	YPE OF SUBMISSION TYPE OF A				ACTION			
Notice of Intent	☐ Acidize	☐ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off		
_	☐ Alter Casing	☐ Fracture T	reat	□ Reclama	tion	☐ Well Integrity		
☐ Subsequent Report	equent Report		v Construction		lete	☐ Other		
☐ Final Abandonment Natice	☐ Change Plans	🛛 Plug and A	bandon	☐ Tempora	rily Abandon	•		
B	Convert to Injection		ig Back		☐ Water Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed of provide the Bond No. on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) BP has evaluated the subject well and finds no further potential. BP respectfully request permission to plug the entire wellbore.								
Please see attached P&A procedure and BLM reclamation plan documents. OIL CONS. DIV.								
In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP America Production Company will use a closed-loop system during P&A operations.								
Notify NMOCD 24 hrs prior to beginning operations								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #220792 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO., sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 09/25/2013 (13SXM0533SE) Name (Printed/Typed) TOYA COLVIN Title REGULATORY ANALYST								
Trainer Times Types		112002	ATORT AR					
Signature (Electronic Submission) Date 09/23/2013								
	THIS SPACE FOR	FEDERAL OR	STATE	OFFICE US	E			
_Approved By STEPHEN MASON	Title	TitlePETROLEUM ENGINEER		Date 09/25/2013				
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of t	itable title to those rights in the sub	ject lease	Office Farmington					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.								

NEAL COM 2E 3004525893

Unit letter Unit O - Sec 14 – T31N – R11W San Juan, NM DK OGRID Number: 000778 P&A date – Sep 2013

Basic Job Procedure:

- 1. TOH with completion.
- 2. RIH with scrapper for 4.5" casing to 6900'
- 3. RIH with CIBP and set at 6870
- 4. Balance cement plug to 2000 with total 729 sks (149.4 bbl) retarded G cement in stages
- 5. PU to 1950' and reverse circulate.
- 6. PU to 1350' and balance cement plug to 750' with total 116 sks (23.8 bbl) neat G cement
- 7. Perforate at 350'-355'
- 8. Pump from surface and circulate up surface casing 141 sks (28.9 bbl) neat G cement
- 9. Cut off well head, top off well in intermediate casing and install well marker and identification plate per regulatory requirements.
- 10. RD MO Location

Current Wellbore Diagram NEAL COM 2E Equipment / Temporary API No. 3004525893 RKB ELEVATION 5932 R2). 0 GL ELEVATION5920 R3). 0 R4). 0 Well History Completed in 1984 R5). 0 R6). 0 while drilling @ 5110, lost circulation Tenenco applied to add MV in 1985 R7). 0 but did not execute the job R8). 0 R9). 0 Spud Date: 4/19/84 R10). 0 Surface Casing Data Hole size: 12-1/4" T1). Tubing: 2-3/8" 4.7#, J55 @ 6999' 9-5/8", 36#, K-55 STC @ 307' 225 sxs cmt TOC: circulated to Surface (circ.) Oje Alamo Top: 840' Btm: 1120' TOC: @ 800' (Temp log) DV tool at 1322' Fruitland/Dakota Top: 2158'. Top of Liner: 5038' **Production Casing Data** Hole size: 8-3/4" 7" 23#, K55 STC @ 5200' 1st: 385 sxs cmt; 2nd stage 210 sxs cm TOC at TOL @ 50383' 1. Fruitland/Dakota 2. Ojo Alamo X End of Tubing @ 6999 Perforation Data 6922-7012': 68 holes, 215K# 20/40 sand Production Liner Data Hole size: 6-1/4" 4-1/2" liner, 10.5#/11.6#, K55 @ 7157' PBTD: 7150' TD: 7160' 255 sxs cmt

Proposed Wellbore Diagram

