Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT JUL 23 2013

SUNDRY NOTICES AND REPORTS ON WELLS SF-078416 Do not use this form for proposals to drill or to re-enter an bandoned well. Her Form 2400 and addition to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Hardie 4M 9. API Well No. 2. Name of Operator **Burlington Resources Oil & Gas Company LP** 30-045-33984 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area (505) 326-9700 Basin DK Blanco MV PO Box 4289, Farmington, NM 87499 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State UL: L (NWSW), 1900' FSL & 840' FWL, Sec. 24, T29N, R8W San Juan **New Mexico** Surface 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) Water Shut-Off Notice of Intent Acidize Deepen Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Other X Subsequent Report Legacy Temporarily Abandon Change Plans Plug and Abandon Reclamation Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Burlington Resources Oil and Gas Company LP completed the Legacy Reclamation of the Location on 7/10/13, as requested by Mike Flaniken during the onsite inspection. Please schedule a field inspection to verify Burlington Resources has met the BLM requirements on this reclamation work. OIL CONS. DIV DIST. 3 ACCEPTED FOR RECORD DCT 29 2013 OCT 25 2013 FARMINGTON FIELD OFFICE 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) STAFF REGULATORY TECHNICIAN Title Kepny Davis 7/22/2013 Date Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would



Title

Office

Date

Philips

ConocoPhillips

Reclamation Form:
Date: 7-15-2013
Well Name: Hardie HM
Footages: 1900 FSL, 840 FWL Unit Letter:
Section: <u>AM</u> , T- <u>A9</u> -N, R- <u>8</u> -W, County: <u>S3</u> State: <u>NM</u>
Reclamation Contractor: MM
Reclamation Start Date: 7/10/13
Reclamation Complete Date: 7/16/13
Road Completion Date: N/A
Seeding Date: 7/10/13
**PIT MARKER STATUS (When Required): Picture of Marker set needed
MARKER PLACED :(DATE)
LATATUDE:
LONGITUDE:
Pit Manifold removed(DATE)
Construction Inspector: Norman Faver Date: 7-15-2015
Inspector Signature: Tyman fave
Office Use Only: SubtaskDSMFolderPictures

Revised 6/14/2012



ENGINEERING CALCULATION

Hardie 42

clean Reseed Location