

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.*5. Lease Serial No.
NMSF078040

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.7. If Unit or CA/Agreement, Name and/or No.
NMNM91282

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other8. Well Name and No.
MUDGE GAS COM D 12. Name of Operator
BP AMERICA PRODUCTION CO.Contact: TOYA COLVIN
E-Mail: Toya.Colvin@bp.com9. API Well No.
30-045-28626-00-D13a. Address
501 WESTLAKE PARK BLVD. RM 4.423B
HOUSTON, TX 770793b. Phone No. (include area code)
Ph: 281-366-714810. Field and Pool, or Exploratory
BASIN DAKOTA
BASIN FRUITLAND COAL

4. Location of Well (Fontage, Sec., T., R., M., or Survey Description)

Sec 12 T31N R11W NWNE 0920FNL 1670FEL
36.917480 N Lat, 107.937850 W Lon

11. County or Parish, and State

SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP has evaluated the subject well and finds no further potential. BP respectfully request permission to plug the entire wellbore.

Please see attached P&A procedure and BLM reclamation plans.

In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP America Production Company will use a closed-loop system during P&A operations.

RCVD OCT 24 '13
OIL CONS. DIV.
DIST. 3**Notify NMOCD 24 hrs
prior to beginning
operations**

14. I hereby certify that the foregoing is true and correct.	
Electronic Submission #222302 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO., sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 10/23/2013 (14SXM0542SE)	
Name (Printed/Typed) TOYA COLVIN	Title REGULATORY ANALYST
Signature (Electronic Submission)	Date 10/08/2013

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By <u>STEPHEN MASON</u>	Title <u>PETROLEUM ENGINEER</u>	Date <u>10/23/2013</u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office <u>Farmington</u>

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ******NMOCD A**

Mudge Gas Com D 1
30-045-28626-00


Unit letter Unit B - Sec 12 - T31N - R11W
San Juan, NM
DK, FC
OGRID Number: 000778
P&A date - Dec 2013

Basic Job Procedure:


1. TOH with short string
2. RU e-line and cut long string below packer.
3. TOH with long string from packer
4. RIH with scrapper to packer
5. Set CICR @ 2680' and pump 82 bbl retarded cement (400 sks if 1.15 yield) thru retainer
6. Balance 29 sks (5.9 bbl) class G neat cement on retainer
7. RIH with CIBP and set at 1350'.
8. Balance plug to surface in two stages with total 103 sks (21.1 bbl) neat G cement
9. Cut off well head, top off well in intermediate casing and install well marker and identification plate per regulatory requirements.
10. RD MO Location

Set CICR @ 3100' squeeze below packer to cover Dakota, Gallup, Mancos, Mesquite
Chaco, 7" casing shoe 2 1/4" liner top.

Current well bore diagram



Proposed wellbore diagram



UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: 1 Mudge Gas Com D

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
3. The following modifications to your plugging program are to be made:
 - a) Place a CICR @ 3100'. Squeeze below to cover the Dakota, Gallup, Mancos, Mesaverde, Chacra, 7" casing shoe and 4 ½" liner top.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.