
Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**



FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

Do not use this form for proposals to drill or to re-enter an bandoned well. Use Form 3160.2 (400)

<u>Jicarilla Contract 94</u> 6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals. Farmington Field Office Jicarilla Apache SUBMIT IN TRIPLICATE - Other instructions on page 2 7. If Unit or CA/Agreement, Name and/or No. 1. Type of Well 8. Well Name and No. Oil Well X Gas Well Other Jicarilla 94 2B 2. Name of Operator ENERGEN RESOURCES CORPORATION 9. API Well No. 3b. Phone No. (include area code) 30-039-26856 2010 Afton Place, Farmington, NM 87401 505.325.6800 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Blanco Mesaverde Gavilan Pictured Cliffs 660' FSL, 1975' FWL, Sec. 27, T27N, R03W (N) SE/SW 11. County or Parish, State Rio Arriba NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Notice of Intent Acidize Deepen Production (Start/Resume) Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report Casing Repair New Construction Recomplete Other Drill out Change Plans Plug and Abandon Temporarily Abandon CBP & DHC Final Abandonment Notice Plug Back Water Disposal Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) Energen Resources drilled out the CBP @ 4300' and completed the DHC (DHC 3761 AZ) of the Blanco Mesaverde and the Gavilan Pictured Cliffs. DHC effective 10/30/13. 10/28/13 MIRU. NDWH. NU BOP. TOOH w/prod tbg. TIH, tag @ 4250'. Clean out to CBP @ 4300' Circ clean. Drill out CBP. Circ clean. 10/29/13 TIH, tag @ 6415'. c/o to PBTD. Circ clean. 10/30/13 TIH w/2.375", 4.7#, J-55 production tubing, set @ 6157'. Rig released.

> RCVD NOV 7'13 OIL CONS. DIV.

Title Regulatory Analy	rst
Date 10/31/13	AGEPTED FOR RECORD
L OR STATE OFFICE USE	NOV 0.5 2013
Title	Date PARAGRAPH DOFFICE
Office	51-
	Date 10/31/13 L OR STATE OFFICE USE Title

fictitious or fraudulent statements or representations as to any matter within its jurisdiction