

FORM APPROVED

NOV 2 2 2013

	(August 2007) UNITED STATES DEPARTMENT OF THE INT	ERIOR	OMB No. 1004-0137 Expires: July 31, 2010
	BUREAU OF LAND MANAG	EMENT NOV 19 2013	5. Lease Serial No. NM 58878
	SUNDRY NOTICES AND REPORT		6. If Indian, Allottee or Tribe Name
	Do not use this form for proposals to d abandoned well. Use Form 3160-3 (APD,	rill or to re-enter an Field O	
			,crani
	SUBMIT IN TRIPLICATE - Other insti	ructions on page 2.	7. If Unit of CA/Agreement, Name and/or No.
			8. Well Name and No. Federal L#001
			9. API Well No. 30-043-20825
	3a. Address 3b.	Phone No. (include area code)	10. Field and Pool or Exploratory Area
)-876-3926	Alamito Gallup
	4. Location of Well (Footage, Sec., T. R. M., or Survey Description) 490 FSL, 1765 FEL, SW Section 28, Township 28N, Range 7W		11, Country or Parish, State Sandoval County, New Mexico
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA		
	TYPE OF SUBMISSION .	TYPE OF ACTI	ON
ros	✓ Notice of Intent		action (Start/Resume) Water Shut-Off
	☐ Alter Casing ☐ Casing Repair	Fracture Treat Reela New Construction Record	mation
	Subsequent Report Change Plans		orarily Abandon
	Final Abandonment Notice Convert to Injection		Disposal
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and a Attach the Bond under which the work will be performed or provide the Bond No, on file with BLM/BIA. Required subsequent reports must be filed within 30 following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be file testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator determined that the site is ready for final inspection.) In an effort to return the above referenced well to production, Encana Oil & Gas (USA) Inc. proposes to recomplete the well in the Gallup Formation. I see the attached procedure and wellbore diagram for details. Encana Oil & Gas (USA) Inc. would like to request an extension to have this work completed by December 30, 2013.			d true vertical depths of all pertinent markers and zones, equired subsequent reports must be filed within 30 days etion in a new interval, a Form 3160-4 must be filed once
			recomplete the well in the Gallup Formation. Please
			ber 30, 2013.
		OIL CONS. DIV DIST. 3	
			NOV 2 6 2013
	•		101 23
		•	
	 Thereby certify that the foregoing is true and correct, Name (Printed/Typed) 		
	Jessica Gregg	Title Regulatory Analyst	
	Signature Dessitive Thegg	Date 11/14/2013	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false. fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

litte

Office

(Instructions on page 2)

Approved by



entitle the applicant to conduct operations thereon.

Original Signed: Stephen Mason

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would

Federal L1

Gallup Add-Pay Workover

Scope

Add additional perforations in the Gallup formation and place well on rod pump

Current Wellbore Details:

All depths from KB (12') 8 5./8", J55, 23# Surf csg set at 212' MD 4 ½", J55, 11.6# Prod csg set at 5,296' MD Perfs – 4,986' – 5,198' MD (8 holes)


Current Tubing Details:

All depths from KB (12') 159 jts 2 3/8", 4.7#, J55 @ 5,179 MD SN and notched collar on bottom

Procedure:

- 1. Inspect and test anchors, replace as needed.
- 2. RU pulling unit. NDWH, NUBOP, TIH and check PBTD (last tagged @ 5234' May, 2011)
- 3. TOH. PU bit & scraper, CO to ~5290', circ clean and TOH.
- 4. Perforate from 5225' 5241'.
- 5. TIH w/ 2/3'8 tbg and pkr. Set pkr @ \sim 5210'.
- 6. Acidize w/ 3000 gal 15% HCL, 20 ball sealers.
- 7. Swab perfs and evaluate for frac.
- 8. Design and pump frac as needed.
- 9. Flowtest well and evaluate for artificial lift.
- 10. If needed, install rod pumping system as follows:
- 11. TOH w/ pkr, TIH with mud anchor, perf sub, tbg, and TAC. Set TAC @ ~4950' and land mud anchor @ ~5280'.
- 12. TIH with pump and rods per design.

WELLBORE DIAGRAM





TRANSMITTED VIA OVERNIGHT MAIL

November 14, 2013

Bureau of Land Management Farmington Field Office Attn: Stephen Mason 6251 College Boulevard, Suite A Farmington, New Mexico 87402

Re:

NMNM-58878 3162.3-2 (21110)

Dear Mr. Mason:

[Jackson Jan

NOV 19 2013

Familington Fight Office Bureau of Land Managamen

On October 30, 2013, Encana Oil & Gas (USA) Inc. received a letter in reference to the Federal L#001 well in Sandoval County, New Mexico. The letter required the well to be recompleted and producing by November 30, 2013. Encana Oil & Gas (USA) Inc. would like to recomplete this well in the Gallup Formation and is requesting an extension until December 30, 2013. Please see the attached recompletion procedure and wellbore diagram for details.

Please feel free to contact me directly at (720) 876-3926 or via email at jessica.gregg@encana.com should you have any questions.

Encana Oil & Gas (USA) Inc.

Jessica Gregg Regulatory Analyst

Enclosures:

- Sundry Notice
- Recompletion Procedure
- Wellbore Diagram

OIL CONS. DIV DIST. 3 NOV **2.6** 2013