Form 3160-5 (February 2005) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT DEC 09 2013 SUNDRY NOTICES AND REPORTS ON WELLS and Manage Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	
Field ()fill 65. Lease Serial No.	_
SUNDRY NOTICES AND REPORTS ON WELL'S and Manage nemi RCVD DEC 18'13	
abandoned well. Use Form 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE – Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No.	-
1. Type of Well DIST. 3	
Oil Well Gas Well Other 8. Well Name and No. Chaco 2306-06L #179H	-
2. Name of Operator 9. API Well No.	-
WPX Energy Production, LLC 30-039-31190	
3a. Address3b. Phone No. (include area code)10. Field and Pool or Exploratory AreaPO Box 640Aztec, NM 87410505-333-1808Lybrook Gallup	-
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State SHL: 1680' FSL & 591' FWL SEC 6 23N 6W Rio Arriba County, NM BHL: 380' FSL & 230' FWL SEC 1 23N 7W Rio Arriba County, NM	-
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA	-
TYPE OF SUBMISSION TYPE OF ACTION	-
Acidize Deepen Production (Start/Resume) Water Shut-Off	-
Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity	
Subsequent Report Casing Repair New Construction Recomplete	
Change Plans Plug and Abandon Temporarily Abandon	
Image: Second	_
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. NOTE: MO-TE SET SURFACE	RÐ
10/15/13- SPUD-12-1/4" HOLE @ 1200 HRS DEC 1 2013	
10/16/13- TD 12-1/4" SURF HOLE @ 422', 1100 HRS. RAN 19 JTS, <u>9-5/8", LT&C, 40#, P-110,</u> CSG <u>SET @ 417'</u> , SHOE @ 416', FC @ 375' Pumped 10 bbls gelled water +10 bbls FW Spacer + 50.2 bbls type G cmt (245 sx)15.8 ppg. Disp. w/ 27.2 bbls FW. Bumped plug to 260 psi, circ 18 Bbls Cement <u>circ. to surface</u> . Floats held OK. Witnessed by OCD. RDMO Mo-Te.	bekou
<u>12/4/13</u> , MIRU AWS #980	
12/5/13- Install test plug & test bop pipe & blind rams, mud cross valves, choke manifold valves, 4" floor valve & Kelly valve @ 250# low 5-min each & 1500# high 10-min each. Test 9.625" csg against blind rams f/_30 min @ 1500# [good test*] Test pump, test chart & test plug used on test.	
14. I hereby certify that the foregoing is true and correct.	
Name (Printed/Typed) Larry Higgins Title Permit Suprv	
Signature Signature Signature Date 12/9/13	
ATHIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by	
Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.	

Copyright 2006 Forms in Word (<u>www.formsinword.com</u>). For individual or single-branch use only.

