Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources					m C-103 ne 19, 2008
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, winiorars and Natural Resources			WELL API NO.		
District II	OIL CONSERVATION DIVISION		1	045-28992		
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Ty	pe of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE	FEE 🗴	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	,			6. State Oil & CA NMNM-9	Gas Lease No. 1278	
(DO NOT USE THIS FORM FOR PROPO	Y NOTICES AND REPORTS ON WELLS OR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A SE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name: NORTHRIDGE		
1. Type of Well: Oil Well  Gas Well  X	8. Well Number #1					
Oil Well Gas Well X Other  2. Name of Operator				9. OGRID Number		
<b>-7</b>				5380		
3. Address of Operator				10. Pool name or Wildcat		
382 CR 3100 Aztec, NM 87 4. Well Location	382 CR 3100 Aztec, NM 87410			FULCHER KUTZ PICTURED CLIFFS		
Unit Letter <u>A</u> :	feet from the		RTH line and		t from the <b>EAST</b>	
Section 03	Township	29N	Range 13W  DR, RKB, RT, GR, etc.	NMPM	County s	an Juan
	11. Elevation (Show		DK, KKB, K1, OK, el [] [ 'GR	(C.)		
NOTICE OF INTE PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  DOWNHOLE COMMINGLE	PLUG AND ABANDO CHANGE PLANS MULTIPLE COMPL	N X	REMEDIAL WORK COMMENCE DRILL CASING/CEMENT J	ING OPNS.	REPORT OF: ALTERING C P AND A	ASING _
OTHER:			OTHER:			
<ol> <li>Describe proposed or completed of starting any proposed work). or recompletion.</li> <li>XTO Energy Inc. intends to closed loop system. Pleas</li> </ol>	SEE RULE 1103. For	Multiple this we ached c	Completions: Attach	h wellbore diagra	am of proposed com	pletion g a
Spud Date:	I	Rig Relea	ase Date:			
I hereby certify that the information a	bove is true and compl	ete to the	best of my knowledg	e and belief.		
SIGNATURE KUSTUR D. B.	ahcock	TIT		RY ANALYST	DATE <b>3</b> /	18/14
Type or print name KRISTEN D. BAL	BCOCIK	E-m	kristen_lynch@xt nail address:		PHONE	333-3206
For State Use Only			Deputy Oil  TLE Dis	& Gas Inspe	ector,	(11
APPROVED BY DY Conditions of Approval (if any):	· · · · · · · · · · · · · · · · · · ·		-7 LTE	MIN #3	<u> </u>	/ 14/p

JTB	
MTG	
Approved	

## March 13, 2014 PLUG AND ABANDONMENT PROCEDURE Northridge 1

Fulcher Kutz PC 887' FNL and 939' FEL, Section 3, T29N, R13W San Juan County, New Mexico / API 30-045-28992 Lat: 36.76006 N / Lat: 108.18654 W

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.8 ppg with a 1.18 cf/sx yield.

1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
2.	Rods: Yes_x, No, Unknown Tubing: YesX_, No, Unknown, Size2.375"_, Length1472' Packer: Yes, NoX, Unknown, Type If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.
4.	Plug #1 (Pictured Cliffs & Fruitland intervals, and Fruitland Top 1382' – 802'): PU and TIH with 5.5" cement retainer, set at 1382'. Pressure test tubing to 1000 PSI. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 74 sxs Class B cement above CR to isolate the Pictured Cliffs, Fruitland, and Fruitland top. PUH.

- 6. Plug #2 (8 5/8" Surface Shoe and Kirtland top, 174' Surface): Attempt to pressure test the bradenhead annulus to 300#. If the BH annulus holds pressure, then establish circulation down tubing and out casing valve with water. Mix approximately 21 sxs Class B cement and spot a plug from 174' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and the annulus.
- 7. ND cementing valves and cut off wellhead. Fill 5.5" casing with cement as necessary. Install P&A marker to comply with regulations. RD, MOL, cut off anchors, and restore location.

## Northridge 1 Proposed P&A

Basin Fruitland Coal 887' FNL, 939' FEL, Section 3, T-29-N, R-13-W San Juan County, NM / API #30-045-28922 Lat 36.76006 N / Long 108.18654 W RCVD MAR 25'14 OIL CONS. DIV.

DIST. 3

Today's Date: 3/13/2014

Spud: 12/9/1993

Completed: PC- 2/17/1994


Kirtland @ 32'

12 1/4" hole

Fruitland @ 852'

Pictured Cliffs @1424'

6 3/4" hole



Elevation: 5526' GL

5531' KB

Plug 2: 174'-0' Class B Cement, 21 sx

8 5/8",24# J-55 Casing set @ 124' Cement with 100 sxs , circ 3 BBL to surface

Plug 1: 1382'-802' Class B Cement, 74 sx

CICR @ 1382 '

Pictured Cliffs Perforations: 1432'-1444'

5.5",14#, M-50 Casing set @ 1684' Cement with 245 Total sxs Circulated 20 BBL to surface

TD 1685' PBTD 1616'

## Northridge 1

## Current

**Fulcher Kutz PC** 

887' FNL, 939' FEL, Section 3, T-29-N, R-13-W, San Juan County, NM / API #30-045-28992 Lat 36.76006 N / Long 108.18654 W

Today's Date: 3/12/2014

Spud: 12/9/1993

Completed: PC 2/17/1994

Kirtland @ 32'

12 1/4" hole

Elevation: 5526' GL 5531' KB

8 5/8" 24#, J-55 Casing set @ 124' Cement with 100 sxs , 3 BBL circ to surface

Fruitland @ 852'

2.375" tubing at 1503', 3/4" rods & pump 45 jts, w/ OEMA, SN @ 1472'

Pictured Cliffs @ 1424 '

6 3/4" hole

Pictured Cliffs Perforations: 1432'-44'

5.5",14#, J-55 Casing set @ 1684' Cement with 245 Total sxs Circulate 20 BBL to surface

TD 1685' PBTD 1616'