State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary-Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary Jami Bailey, Division Director
Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

and a	re in ac		on to the actions a owing 3160-4 or 3		-		on t	he			
Operator Sigr	nature Da	ate: A	April 3, 2014								
Application T			Drilling/Casing	Cha	ınge [Rec	om	plet	e/[ЭH	С
	Locati	on (Change 🗌 Othe	r:							
Well information:											
API WELL#	Well Name	Well #	Operator Name	Type S	Stat County	Surf_Owner	UL S	ec Twp	N/S	Rng	W/E
30-039-25382-00- 00	BROWN	200	THOMPSON ENGR & PROD CORP	G E	E Rio Arriba	F	N	31 29	N	4	W
Conditions of Approval:											
Notify NMOCD 24hrs prior to beginning operations											
Add PC plug above PC perfs (4396 - 4483)											

NMOCD Approved by Signature

4-10-14 Data Form 3 160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED - COMB No. 1004-0135
Expires Inovember 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

APR 04 2014

Longo Sorial No.

April 3, 2014

APR 0 7 2014

Lease Serial No.
SF 079893 A

Do not use thi abandoned well	is form for proposals to !. Use Form 3160-3 (APD	o drill or reenter any) for suchម្ចាច្រក្នុងទុះ	ton Field Offi and Manage	ਹੋਰਿ. If Indian, Al ਸਾਹਿਤ	lottee or Tribe Name			
	ICATE – Other instr				A/Agreement, Name and/or No.			
I. Type of Well				-				
Oil Well X Gas Well	Other			8. Well Name a	and No.			
				Brown #200				
Thompson Engineering and Production Corp.				9. API Well No.				
3a. Address	· · · · · · · · · · · · · · · · · · ·	3b. Phone No. (include	. (30-039-25382			
7415 E. Main, Farmington, NN	Л, 87402	505-327-4892			10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Description)	<u> </u>			Gobernador PC			
190' FSL and 1915' FWL, Sect	•			11. County or Pa	arish, State			
				The Country of Turnon, State				
				Rio Arriba, N	1M			
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REP	ORT, OR OTHEI	R DATA			
TYPE OF SUBMISSION		TYP	E OF ACTION					
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	Production Reclamatio	(Start/Resume)	Water Shut-Off Well Integrity			
Subsequent Report	Casing Repair	New Construction	Recomplete	e	Other			
	Change Plans	Plug and Abandon	Temporaril	y Abandon				
Final Abandonment Notice	Convert to Injection	X Plug Back	- -					
13. Describe Proposed or Completed Oper If the proposal is to deepen direction: Attach the Bond under which the wo Following completion of the involved Testing has been completed. Final Adetermined that the site is ready for final Adetermined tha								
Thompson Engineering un	a Froduction Corp. propo	ises to prug ana avanac	m inis weii acc	oraing to the at	<i>испеи р</i> госеииге.			
					OVD APR 9 '14 IL CONS. DIV.			
					DIST. 3			
•								
14. I hereby certify that the foregoing is	true and correct							
Name (Printed/Typed)	Title							
Paul C. Tho		F	President					
Signature	Date							

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Approved by

Original Signed: Stephen Mason

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

THIS SPACE FOR FEDERAL OR STATE USE

Title

Office

Walsh Engineering and Production

P & A Procedure for Thompson Engineering Brown #200

Location: SW/4 Sec 31 T29N R4W

Rio Arriba County, NM

Field: Basin FTC & Gobernador PC Surface: Carson Nat'l Forest Minerals: Federal SF - 079893A

API #: 30-039-25382

Date: April 3, 2014

Elev: GL 7418' 4-1/2" @ 4535' PBTD - 4492' KB

Procedure:

1. Move on location and rig up a completion rig with a flow back tank. Hold a safety meeting and explain the procedure to the crew. Nipple down the tubinghead and nipple up the BOP.

- 2. Pick up a work string of 2-3/8" tubing and tag CIBP at 4192'.
- 3. Load the casing with water. Pressure test the casing to 500 psi.
- 4. Plug #1 Ojo Alamo Pictured Cliffs (3594' 4483'). Spot a balanced plug with 49 sx (57.8 cu.ft.) of neat cement on top of the CIBP. POH to 3300' and reverse circulate the tubing clean. POH to 2409'.
- 5. Plug #2 Nacimiento 2309' 2409'. Spot a balanced plug 50' +/- from the Nacimiento top (100' with 50' excess) with 12 sx (14.2 cu.ft) of neat cement. POH with 10 joints and reverse circulate the tubing clean. POH to 592'.
- 6. Plug #3 Surface -592'. Spot a balanced plug from 50' below the surface casing shoe (592') to surface with 45 sx (53 cu.ft.) of neat cement. TOH.
- 7. Nipple down the BOP. Cutoff the casing below the wellhead and fill the 4- 1/2" and 8-5/8" X 4-1/2" annulus with neat cement as necessary.
- 8. Install a dry hole marker and cutoff or remove the anchors. Reclaim the location as per surface owner specifications.

Paul C. Thompson, P.E.

THOMPSON ENGINEERING
BROWN #200
SEC. 31, TZ9N, R4W
RID ARRIBA CO., NM.
API # 30-039-25382

i	CLIRRONT STATUS	PAA STATUS
	124" 1 8 8, 24 d 0 542 Cont. w/ 472 cu. ft. CIRC CONT TO SURFACE	PLUG 3 SURF-59Z 455x (53.1 en.tt.)
	HOLE - 7 1/8"	
	HALIMIENTO 2359	PLUG Z 2309-2409 125x (14.2 cu.ft)
	036 ALAMO 3694 KIRTLANS 3920 C189-4192 FTC 4240-4320	Peuc 1 3594-4192 455x (53.1 cuft)
	7C. 43% PC - 43% - 4483 PC - 43% - 4483 PBTD 4492 41/2", 10.5" J-55 PC - 43% - 4483	
	CIRC CIT TO SURFACE	

7ct 4/3/14