

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

MAR 21 2014

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELL COMPLETION**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMNM 1129536. If Indian, Allottee or Tribe Name
Farmington Field Office**SUBMIT IN TRIPLICATE – Other instructions on page 2.**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
Encana Oil & Gas (USA) Inc.3a. Address
370 17th Street, Suite 1700
Denver, CO 802023b. Phone No. (include area code)
720-876-53317. If Unit of CA/Agreement, Name and/or No.
N/A8. Well Name and No.
Lybrook E27-2306 03H9. API Well No.
30-043-2115010. Field and Pool or Exploratory Area
Counselors Gallup-Dakota4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
SHL: 1599' FNL and 199' FWL Section 27, T23N, R6W *These are the As-Drilled Footages. It is the intent of this Sundry to clarify
BHL: 1732' FNL and 689' FWL Section 28, T23N, R6W any confusion regarding footages.11. Country or Parish, State
Sandoval County, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Footage Clarification
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Encana Oil & Gas (USA) Inc. (Encana) wishes to submit re-clarification for the intended SHL, POE and BHL footages for the Lybrook E27-2306 03H well prior to the submittal of the Well Completions Sundry, which is dated March 12, 2014. The intended footages should have been as follows:

Surface Hole: 1599' FNL, 199' FWL Section 27, T23N R6W
Point of Entry: 1730' FNL, 330' FEL Section 28, T23N R6W
Bottom Hole: 1730' FNL, 660' FWL Section 28, T23N R6W
An executed C-102, dated March 1, 2014 reflecting the above footages is enclosed.

RCVD MAR 25 '14
OIL CONS. DIV.
DIST. 3

In order to clear up any confusion Encana submits the following Attachments in regards to the footage changes for this well:

Attachment No. 1 - Chronology of Footage Changes

- Details any Sundry that listed and/or changed SHL, POE or BHL footages
- Details the date of the Sundry documents submitted
- Details BLM and NMOCD approval of Sundries
- Details the errors on the Sundries submitted

Attachment No. 2 - Courtesy Copies of Sundries

- Copies of Sundries provided for any Sundries that have not been approved by either the BLM or NMOCD

ACCEPTED FOR RECORD

MAR 24 2014

FARMINGTON FIELD OFFICE
BY: William Tambekou

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
Holly Hill

Title Senior Regulatory Analyst

Signature

Date 03/20/2014

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

NMOCD

District II
811 S. First Street, Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720

District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-5178 Fax: (505) 334-6170

District IV
1220 S. St. Francis Drive, Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

OIL CONSERVATION DIVISION

1220 South St. Francis Drive
Santa Fe, NM 87505

Submit one copy to
Appropriate District Office

☒ AMENDED REPORT

MAR 21 2014

WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number 30-043-21150	'Pool Code 13379	'Pool Name COUNSELORS GALLUP-DAKOTA
'Property Code 40083	'Property Name LYBROOK E27-2305	'Well Number 03H
'GRID No. 282327	'Operator Name ENCANA OIL & GAS (USA) INC.	'Elevation 7054'

Farmington Field Office
Director of Land Management

¹⁰ Surface Location

U/L or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County
E	27	23N	6W		1599	NORTH	199	WEST	SANDOVAL

¹¹ Bottom Hole Location If Different From Surface


UL or lot no.	Section	Township	Range	Lot 10n	Feet from the	North/South line	Feet from the	East/West line	County
E	28	23N	6W		1730	NORTH	660	WEST	SANDOVAL

12 Dedicated Acres	320.00 Acres N/2 - Section 28	13 Joint or Infill	14 Consolidation Code	15 Order No.	RCVD MAR 25 '14 OIL CONC. PERM.
--------------------	----------------------------------	--------------------	-----------------------	--------------	------------------------------------

RCVD MAR 25 '14
OIL CRANE, BELL

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

Page 2



END-OF-LATERAL
1730' FNL 660' FWL
SECTION 28, T23N R6W
LAT: 36.19869°N
LONG: 107.47950°W
DATUM: NAD1927

LAT: 36.19871°N
LONG: 107.48010°W
DATUM: NAD1983

POINT-OF-ENTRY
1730° FNL 330° FEL
SECTION 28, T23N, R5W
LAT: 36.19861°N
LONG: 107.46501°W
DATUM: NAD1927

LAT: 36.19863 °N
LONG: 107.46561 °W
DATUM: NAD1983

SURFACE LOCATION
1599' FNL 199' FWL
SECTION 27. T23N, R6W
LAT: 36.19897°N
LONG: 107.46322°W
DATUM: NAD1927

LAT: 36.19898 °N
LONG: 107.46382 °W
DATUM: NAD1983

17 OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom-hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral working interest or a royalty pooling agreement or a compulsory pooling order heretofore entered by the division.

Signature Abby Liu Date 03/01/2014


Holly Hill
Printed Name
holly.hill@encana.com

10 SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Date Revised: OCTOBER 22, 2013
Survey Date: OCTOBER 22, 2012

Signature and Seal of Professional Surveyor



JASON C. EDWARDS
Certificate Number 15269

Attachment No. 1 to Sundry dated March 20, 2014
Chronology of Footage Changes
Encana Oil Gas (USA) Inc.

Well Name:	SHL Footages	Document Submitted	Document Submittal Dated	BLM Approved	OCD Approved	Comments
Lybrook E27-2306 03H	1629 FNL, 199 FWL	Application for Permit to Drill	05/16/2013	08/13/2013	08/21/2013	
	1629 FNL, 199 FWL	Pilot Hole Change Sundry	07/12/2013	08/13/2013	09/20/2013	No C-102 was supplied.
	1629 FNL, 199 FWL	Updated Cement Volumes Sundry	08/28/2013	08/30/2013		No C-102 was supplied.
API No. 30-043-21150	1599 FNL, 330' FWL*	Revised SHL, BHL and Casing Change Sundry	09/27/2013	10/17/2013		*Sundry incorrectly stated SHL was 1599 FNL, 330' FWL; when C-102 attached stated the SHL was 1599 FNL, 199 FWL. Text in sundry was incorrect.
		Request to Withdraw 09/27/13 Sundry	11/11/2013			No C-102 was supplied
Legal Location: E-Sec 27-T27N-R6W	1599 FNL, 199 FWL	Surface Sundry	12/12/2013	12/17/2013	12/17/2013	No C-102 was supplied
	1599 FNL, 199 FWL	Intermediate Sundry	12/30/2013	12/31/2013	01/08/2014	No C-102 was supplied.
	1599 FNL, 199 FWL*	Plugback Sundry	12/30/2013	01/02/2014	01/29/2014	No C-102 was supplied; OCD crossed off 1599 FNL
	1599 FNL, 199 FWL	Production Sundry	01/02/2014	01/08/2014	01/15/2014	No C-102 was supplied
	1569 FNL, 199 FWL*	Footage Correction Sundry	02/06/2014			* Sundry incorrectly stated SHL as 1569 FNL, 199 FWL, C-102 indicated SHL was 1599 FNL, 199 FWL. Text in sundry was incorrect.
	1599 FNL, 199 FWL	Well Completion Sundry	03/12/2014			Amendment to this Sundry needs to be filed to correct this entirely.
	1599 FNL, 199 FWL	Final C-104	03/14/2014			Amendment to this Sundry needs to be filed to correct this entirely.
		OCD NSL-6897 Approval				
	1599 FNL, 199 FWL	Sundry	03/14/2014			
Prior to the Well Completion Sundry submittal it was Encana's intent to have the SHL as follows: 1599 FNL, 199 FWL						

POE Footages	Document Submitted	Document Submittal Dated	BLM Approved	OCD Approved	Comments
1730 FNL, 330 FEL	Application for Permit to Drill	05/16/2013	08/13/2013	08/21/2013	
Not listed in sundry*	Revised SHL, BHL and Casing Change Sundry	09/27/2013	10/17/2013		* C-102 attached stated the POE was 2145 FNL, 330 FEL.
700 FNL, 330 FEL*	Footage Correction Sundry	02/06/2014			* Sundry incorrectly stated POE as 700 FNL, 330 FEL, when C-102 attached indicated POE was 1730 FNL, 330 FEL. Text in sundry was incorrect.
1720 FNL, 350 FEL	Well Completion Sundry	03/12/2014			Amendment sundry needs to be filed to correct this sundry entirely.
Not listed in sundry	Final C-104	03/14/2014			Attached C-102 states POE was 1720 FNL, 350 FEL.
Not listed in sundry	OCD NSL-6897 Approval Sundry	03/14/2014			OCD order states POE was 1730 FNL, 330 FEL
Prior to the Well Completion Sundry submittal it was Encana's intent to have the SHL as follows: 1730 FNL, 330 FEL.					

BHL Footages	Document Submitted	Document Submittal Dated	BLM Approved	OCD Approved	Comments
1730 FNL, 330 FWL	Application for Permit to Drill	05/16/2013	08/13/2013	08/21/2013	
1730 FNL, 330 FWL	Pilot Hole Change Sundry	07/12/2013	08/13/2013	09/20/2013	No C-102 was supplied.
1730 FNL, 330 FWL	Updated Cement Volumes Sundry	08/28/2013	08/30/2013	09/20/2013	No C-102 was supplied.
2145 FNL, 330 FWL	Revised SHL, BHL and Casing Change Sundry	09/27/2013	10/17/2013		
	Request to Withdraw 09/27/13 Sundry	11/11/2013			No C-102 was supplied.
1730 FNL, 660 FWL*	Surface Sundry	12/12/2013	12/17/2013	12/17/2013	No C-102 was supplied.
1730 FNL, 660 FWL*	Intermediate Sundry	12/30/2013	12/31/2013	01/08/2014	No C-102 was supplied.
1730 FNL, 660 FWL*	Plugback Sundry	12/30/2013	01/02/2014	01/29/2014	No C-102 was supplied.
1730 FNL, 660 FWL	Production Sundry	01/02/2014	01/08/2014	01/15/2014	No C-102 was supplied.
700 FNL, 660 FWL*	Footage Correction Sundry	02/06/2014			* Sundry incorrectly stated POE as 700 FNL, 660 FWL, C-102 indicated POE was 1730 FNL, 660 FWL. Text in sundry was incorrect.
1732 FNL, 689 FWL	Well Completion Sundry	03/12/2014			Amendment to this Sundry needs to be filed to correct this entirely.
1732 FNL, 689 FWL	Final C-104	03/14/2014			Amendment to this Sundry needs to be filed to correct this entirely.
	OCD NSL-6897 Approval Sundry				*Sundry does not reflect As-Drilled BHL which is 1732 FNL, 689 FWL; OCD order states BHL was 1730 FNL, 660 FWL
1730 FNL, 660 FWL*		03/14/2014			
Prior to the Well Completion Sundry submittal it was Encana's intent to have the BHL as follows: 1730 FNL, 660 FWL.					