		•					
•	Form 3160-5 UNITED STATES						FORM APPROVED
	(April 2004) DEPARTMENT OF THE INTERIOR					OMB No. 1004- 0137	
	BUREAU OF LAND MANAGEMENT					Expires: March 31, 2007	
		DUKEAU OF LANI	JWIANAC	HEIVIEIN I		5. Lease Serial	No
	SUNDRY NOTICES AND REPORTS ON WELLS					1	
							arilla Contract 110
OIL CONS. DIV DIST. 3 JUN 1 2 2014	Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee, or Tribe Name						
	abandoned well. Use Form 3160-3 (APD) for such proposals.					4	Jicarilla Apache
	SUBMIT IN TRIPLICATE - Other Instructions on Teverse side . / . If Unit or CA. Agreement Name and/or N						A. Agreement Name and/or NO.
	1. Type of Well Oil Well Gas Well Gas Well	Oiher			2011.	8. Well Name	and No.
				JUN 10 2014			
s//S	2. Name of Operator			upaton Fi	ald Office	9. API Well N	Jicarilla A #7F
L CONS. DIV DIS JUN 1 2 2014					eld Office	9. API Well N	30-039-31171
	3a. Address 1001 Fannin St, Suite 800 Bu Houston, TX 77002-6707				anagemen 713-970-1847	10. Field and F	Pool, or Exploratory Area
S m	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			037-3300,	/15-//0-104/	4	Aesaverde/Basin Dakota
No N		660' FNL & 2053' FWL, Unit Letter C, S			N. R05W	11. County or	and the second
S S							Rio Arriba
JIC .	12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT					. OR OTHE	
<b>.</b>					PE OF ACTION		
					E OF ACTION		
	Notice of Intent	Acidize	Deepen		Production ( S	tart/ Resume)	Water Shut-off
`		Altering Casing	Fracture	Treat	Reclamation		Well Integrity
	<b>V</b> Isature Prove						
	X Subsequent Report	Casing Repair		instruction	Recomplete		X Other
	BP	Change Plans	Plug an	d abandon	Temporarily A	bandon	Completion Operations
	Final Abandonment Notice	Convert to Injection	Convert to Injection Plug back Water Disposa			1	•
	'13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof.						
	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.) 3/27/14 - 4/4/2014: MIRU Triple P WS. Cleaned out wellbore down to 7572', Relsd rig, prep for frac. R						
	3/27/14 – 4/4/2014: MIRU Triple P WS. Cleaned out wellbore down to 7572'. Relsd rig, prep for frac. BP 4/24/14 - Pressure test casing to 6000 psi w/chart. 30min Per Jennie McMillian Ver bal 6-13-14						
		4: MIRU Hurricane WS Rig #17. Tag'd TOC at 7579'. Drill out cmt fr 7579'-7594' (25' above float					
	shoe). Ran GR,CCL & CHNL fr 7574' to 7000'. Drill out fr 7574' to 7577'. Stuck tbg, fished free. PU 3-7/8" s						
journal bit & tbg string & TIH. Tag'd at 7572', washed to 7577'. Drill FC @ 7577', drld cm							7578-7607' (hard
	drilling at this depth). Press test csg to 1500 psi for 5 mins - OK. RIH & logged well fr 7613' (WL depth) up to						
	RD & relsd rig.						
	5/09-10/2014: MIRU WL truck, perf Dakota fr 7449' to 7588', 156 shots on 3 runs. MIRU Baker Huges, Frac w/3230						
	bbls & 255,262# sd. Perf 7360-7410', 84 holes in 8' interval, frac w/2700 bbls fl, 175,180# sd.						
	5/11-16/2014: Perf MesaVerde from 5306-5422' - 105 holes, Frac w/1450 bbls fl, 249,160# sd. Perf 5164'-5246'						
	w/1218 bbls fl, 167,680# sd. Frac MV from 5028-5080'. 3 spf, total of 81 holes, frac w/1027 bbls fl, 153,685# sd. Perf						
	4862-4903', 63 holes, frac w/830 bbls fl & 124710# sd. RD & relsd rig. SWI. RU closed loop sys to start flow back.						
	Drill out frac plugs, clean out to PBTD 7618'. Circ around in Closed loop system.						
	As is wellbore schematic attached with detailed frac information. 14. Thereby certify that the foregoing is true and correct.						
	Name (Printed' Typed)	strue and correct.	1.				
		McMillan		Title Sr. Regulatory Analyst			
	Signature Seamie McMillan			Date June 10, 2014			
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
	Approved by			Title		· lt	Date
	Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office						
	which would entitle the applicant to conduct operations thereon.						
	Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction.						
	(Instructions on page 2)						
						I MUL	0 2014

NMOCD PY

FARMINGTON FIELD OFFICE BY: 12 Salyors .

, she