State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

David Martin

Cabinet Secretary-Designate

NMOCD Approved by Signature

Jami Bailey, Division Director Oil Conservation Division



Brett F. Woods, Ph.D. Deputy Cabinet Secretary

New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

	, TOHOWII	1g <u>J</u>	100-4 01 3	100	<u>-</u>	101111.	•						
Operator Sign	nature Date: 5/28/14	4											
	· · · · · · · · · · · · · · · · · · ·		g/Casing		an	ge [Rec	on	np	let	e/[⊃⊢	łC
Well informa		ngc	, Outo										
API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/I
30-039-21474-00- 00	VALENCIA CANYON UNIT	005	XTO ENERGY, INC	G	A	Rio Arriba	F	Р	26	28	Z	4	W
	CD 24hrs prior to be	eginn	ing operations	S						•			
Extend Ojo A	Alamo plug to 3472												
Provide CBL	to agencies prior to	cem	enting										

1220 South St. Francis Drive • Santa Fe, New Mexico 87505 Phone (505) 476-3460 • Fax (505) 476-3462 • www.emnrd.state.nm.us/ocd

Date

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013
Expires July 31, 2010

5. Lease Serial No.

NMNM-14920

SUNDRY NOTICE	S AND	REPORTS	ON	WELLS
---------------	-------	---------	----	-------

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICA	TE - Other instruction	ons on page 2	المنا المنا	7. If Unit or CA/Agre US FOREST SERV	ement, Name and/or No
Type of Well Oil Well Sas Well Other		MAY 29	2014	8. Well Name and No	
2. Name of Operator XTO ENERGY INC.		Firem, Will		9. API Well No.	N UNIT #5
3a. Address 382 CR 3100 AZTEC, NM 87410		3b. Phone No. (include ar 505-333-3176	ed code)-	30-039-21474 10. Field and Pool, o	r Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey	Description) 26 (P) -T28N-R4W	N.M.P.M.		CHOZA MESA PIC	TURED CLIFFS
12. CHECK APPROPRIATI	E BOX(ES) TO INI	DICATE NATURE OF N	NOTICE, REPO	RT, OR OTHER DA	TA
TYPE OF SUBMISSION		TY	PE OF ACTION		
 X Notice of Intent Subsequent Report Final Abandonment Notice 	Acidize Alter Casing Casing Repair Change Plans Convert to Injectiv	Deepen Fracture Treat New Construction X Plug and Abandon Plug Back	Production Reclamatio Recomplet Temporaril Water Disp	e Q Q Abandon	Water Shut-Off Well Integrity Other
13. Describe Proposed or Completed Operation (clear If the proposal is to deepen directionally or recomp Attach the Bond under which the work will be pe	y state all pertinent deta plete horizontally, give s	ils, including estimated starting	ng date of any prosured and true ver	oposed work and approxitical depths of all pertin	nent markers and zones.

It the proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

XTO Energy Inc. intends to plug and abandon this well per the attached procedure and will be using a Cloosed Loop System. Please see also, the attached current and proposed wellbore diagrams.

OIL CONS. DIV DIST. 3

JUN 06 2014

ELLIS AFFEDVAL DE ACCEPTANCE OF THIS ACTION DE SE MOT ELLISVE THE LESSEE AND DELEARCH GENALING ANY OTHER AUTHOUTE ENAMED ELECTIONS ON CITATION AND ENEVAL LANDS

SEE ATTACHED FOR CONDITIONS OF APPROVAL

Title	REGULATORY	ANALYST	
Date	5/28/2014		
L OR	STATE OFFICE	USE	
Tit	Petroleum	Engineer	Date 6 3 2014
Of	fice	7	
	FFo		
	Date AL OR Ti	Date 5/28/2014 AL OR STATE OFFICE Title Petroleum Office	Date 5/28/2014 AL OR STATE OFFICE USE Title Petroleum Engineer Office

LWA	
MTG	
Approved	

PLUG AND ABANDONMENT PROCEDURE

May 21, 2014

Valencia Canyon Unit #5

Choza Mesa Pictured Cliffs 1185' FSL and 850' FEL, Section 26, T28N, R4W Rio Arriba County, New Mexico / API 30-039-21474 Lat: / Lat:

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- 2. Rods: Yes____, No__X_, Unknown___.
 Tubing: Yes__X_, No___, Unknown___, Size __2-3/8"___, Length __4240'
 Packer: Yes____, No__X_, Unknown___, Type____.
 If this well has rods or a packer, then modify the work sequence in step #2 as appropriate.

NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or where a T.S. or CBL log was not previously run. The procedure will be modified as necessary based on the CBL. ✓

3. Plug #1 (Pictured Cliffs interval and Fruitland top, 4050' – 3858'): Round trip 4.5" gauge ring to 4050'or as deep as possible. RIH and set 4.5" CR at 4050'. Pressure test tubing to 1000#. Circulate well clean. Pressure test casing to 800 PSI. If casing does not test, then spot or tag subsequent plug as appropriate. Mix and pump 19 sxs Class B cement above CR to isolate the Pictured Cliffs interval and cover the Fruitland top. PUH.

See COA

4. Plug #2 (Kirtland and Ojo Alamo tops, 3582' – 3310'): Mix and pump 25 sxs cement inside casing to cover the Kirtland and Ojo Alamo tops. PUH.

See COA

- 5. Plug #3 (Nacimiento top, 2180' 2080'): Mix and pump 12 sxs cement inside casing to cover the Nacimiento top. TOH and LD tubing.
- 6. Plug #4 (Surface Casing shoe, 369' to Surface): Perforate 3 squeeze holes at 369'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 120 sxs Class B cement and pump down the 4.5" casing to circulate good cement out bradenhead. Shut in well and WOC.
- 7. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.



XTO - Wellbore Diagram

Order 1970	39214740000 85 Configuration Type XTO ID B				FSL	T28N-R04V	ソーシン	6 (Choz	a Mess	a PC	Rio Ar	riba	New Me	XICO
April Company Fig. April Apr		Orig KB Elev (ft)					V-02						1	
Mode														
Production	Well Config: Vertica			, AVD	Zones	L. L. Hiller	اردي پېره مواديو د کا							
Production	Schematic	- Actual	Incl (TVD)				. (J. Q.)*	34.20	化型器列			44.88.75	Btm (ftKB)	
Carried Description Oxford String Grade Top Connection Sale				1. 7			WYY:		W-4-19-17			<u>(8.55) - 8.57)</u>	STEPPENSE "	
Surface					Casing Descri	rings/ ption						Top Cor	nection S	et Depth
Came Description Oil Print String Grade Description Set Description	mental and the second s		44	10							-	' '		319.
319						•	C		1 1		-	Top Cor	nection S	
Security Surface Saring Surface Surf							. 11. 23.					West No. 2001 No. 7	No. of the state of the party of the	
Surface Casing Cement		2		319									. (25.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.2.	A CONTRACTOR
1,500						asing Ceme	ent		na				319.0ftKB	}
Description Type Production Casing Production 4.375.0ft/SB					Comment									
### Production Casing Cement Casing Production, 4,375.0ffkB ### Comment Cmtd wi1145 sx50/50 POZMIK w/6% get & 2#/SX MTP. Tailed in w/120 sx CL B cmt DID NOT CIRC CMT TO SURF. ### A1100 Production Produc				1,500		50 sx cmt w	/2%		Circ 11	sx cmt to				
4.100						Canina Co	man		20				n 1275	Off K B
Comit of w1145 sx50/59 POZMIX w6% get & 2#/SX MTP. Tailed in w120 sx CL B cmt DID NOT CIRC CMT TO SURF. 4.110				4 400	\	Casing Ce	men	Casi	ig .			Toductic	JII, 4,373.	JIIND
DID NOT CIRC CMT TO SURF.				4,100		145 sx50/50	POZ	ZMIX w/6	% gel 8	& 2#/SX MT	P. Taile	d in w/12	20 sx CL	B cmt.
A 126									5					
A 126				4 110	Perforation	ns Pro	3	100	in the			the section is		Te a
A 126				.,			3.47		7 (3CH	Hole	TOTAL STATE			<u> </u>
4,156 10/13/1977 4,100.0 4,110.0 1.0 Pictured Cliffs						The same of	S 35	4 . C. C	Shot D	ens Diameter	Phasing	Cur		
10/13/1977				4,126	10/13/197	7 4 10					16450X(2, "			
10/13/1977					10/13/197	7 4.12								
4.166 10/13/1977 4.246.0 4.288.0 1.0 Pictured Cliffs 10/13/1977 4.282.0 4.316.0 1.0 Pictured Cliffs 11/3/1978 Pictured Cliffs 11/3/1978											 			
A 168 Tubing Strings Tubing Description Run Date Set Depth (RKB) A 239 6				4,156	10/13/197			4,268	.0	1.0		Pi	ctured Cli	ffs
Tubing - Production Run Date Set Depth (Rick) 4,239 6						7 4,28	2.0	4,316					ctured Cli	ffs
Tubing - Production Run Date Set Depth (Rick) 4,239 6				4.400	Tuhing St	rings 9			2,047				. STATES	
Tubing 1 1 2 3/8 1 10 4 23/8 1 10 23/8 1 10 23/8 1 10 23/8 1 10 23/8 1 10				4,168	Tubing Descri	ption	344	Run D	ate	Santie American	S	et Depth (f	•	
A 180														
Note				4 180	Tubing Co	mponents	1.				Table Climit		A. J.	3 34 5 34 4 44 34 34 34
Tubing 136 T&C 2 3/8 4.70 J-55 4,195.20 10.0 4.2 Tubing 1 T&C 2 3/8 4.70 J-55 32.80 4,205.2 4.2 Tubing 1 T&C 2 3/8 4.70 J-55 32.80 4,205.2 4.2 Seat Nipple 1 2 23/8 1.10 4,238.0 4.2 Notched Collar 1 2 3/8 0.550 4,239.1 4.2 Rod S. Rod Description Run Date Sing Length (ft) Set Depth (ft/K) Rod Components 1 tem Description To July 1 Set Model Coll (ft) In July 2 2,050.0 MTP (psi) ISIP (10/13/1977 4110 4316 W/65.268 GALS FOAM & 378,000 LBS 10/20 SD @ 12 Bf 4,383 4,282 BTD, 4,323 BTD, 4,323				.,	Item Des	scription	Jts	Model				Len (ft)	Top (ftKB)	Blm (
Tubing 1 T&C 2 3/8 4.70 J-55 32.80 4,205.2 4,2 4.238 Seat Nipple 1 2 3/8							136	T&C	2 3/8	4.70 J-55	4.	195.20	10.0	4,2
4.238 Seat Nipple 1 2 3/8 1.10 4,238.0 4,239.1 4,239 Rod Description Run Date String Length (ft) Set Depth (ft/S) Rod Components Treatments Treatm				4,205										<u> </u>
4.238 Seat Nipple 1 2 3/8 1.10 4,238.0 4,2 Notched Collar 1 2 3/8 0.50 4,239.1 4,2 Rods		Des:Pictured Clins			Tubing		1		2 3/8	4.70 J-55		32.80	4,205.2	4,2
Notched Collar 1 2 3/8 0.50 4,239.1 4,239					C- of Nine			opset	2 2/0			1 10	4 220 0	1 4 2
A				4,238										
Rod Components String Length (ft) Set Depth (ft/KB)					Notched C	Ollai		N. 19 A 400 a 13		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5-3-3-3-8-	0.50 ₁	7,200.1	1 7,2 (3% 35)
Rod Components Jis Model OD (in) Grade We Len (it) Top (fixE) Relim (it) Stimulations & Treatments Top Stan Date Top Perf (it Bottom Pe V (slurry) (Total Prop AIR (b AIP (psi) SIP (it 10/13/1977 4110 4316 V (4316				4,239		on.	TDuni		her dear			100	at Donth (ftK)	<u>원</u> 라 변화 21
4,240 Stimulations & Treatments V(slurry) (Total Prop AlR (b ATP (psi) SIP (r. 10/13/1977 4110 4316 4316 4,268 4,268 4,282 4,316 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,282 4,282 4,282 4,323				4,239	Trou Description	OII	Num	Date		Duning Len	gui (it)	0	st Dopur (Art	-,
4,240 Stimulations & Treatments V(slurry) (Total Prop AlR (b ATP (psi) SIP (r. 10/13/1977 4110 4316 4316 4,268 4,268 4,282 4,316 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,323 4,282 4,282 4,282 4,323					Rod Com	ponents		STATES		ETTE ME	Profession Co.		W. T.	ANTHONY.
4,246. Frac Start Date Top Perf (ft Bottom Pe V (slurry) (Total Prop AIP (ps) MTP (ps) ISIP (ft. 10/13/1977 4110 4316 W/65,268 GALS FOAM & 378,000 LBS 10/20 SD @ 12 BF 2050 PSIG. ISIP 1700 PSIG. 15" SIP 15 PSIG. 4,282 4,316 4,323				4,240	item [Description	·	"Jts 🔆 🏭	Model 🐥	OD (in) Gr	ide - Le	n (ft) 🤼 👢	Top (ftKB) ₈ °	@Btm (f
4,246. Frac Start Date Top Perf (ft Bottom Pe V (slurry) (Total Prop AIP (ps) MTP (ps) ISIP (ft. 10/13/1977 4110 4316 W/65,268 GALS FOAM & 378,000 LBS 10/20 SD @ 12 BF 2050 PSIG. ISIP 1700 PSIG. 15" SIP 15 PSIG. 4,282 4,316 4,323					200 11 01 22	্ৰাক্ত ক্ৰম্মেক	5	VI 1169 3	Car . Minima	1 x 2 x x x x x x x x x x x x x x x x x	الارائات الجوامل	3,7,753.	The Darwinson	
10/13/1977 4110 4316 12 2,050.0 1,70 Comment F. PERFS FR/4100'-4316' W/65,268 GALS FOAM & 378,000 LBS 10/20 SD @ 12 BF 2050 PSIG. ISIP 1700 PSIG. 15" SIP 15 PSIG. 4,268 4,268 4,282 4,316 4,323				4 0 4 0		ons & Treat	Botto	om Pe IV	্রক্রিটি ই (slurry) /	. Total Prop	A 1/2/16/16	ATP (psi)	MTP (psi)	
4,268 F. PERFS FR/4100'-4316' W/65,268 GALS FOAM & 378,000 LBS 10/20 SD @ 12 BF 2050 PSIG. ISIP 1700 PSIG. 15" SIP 15 PSIG. 4,316 4,323				4,246	.				,			.,,		1,70
4.268 2050 PSIG. ISIP 1700 PSIG. 15" SIP 15 PSIG. 4.282 4.316 4.323						ED/44601 :	240	\AU05.00	0.001	2.50444.2	270 000	100.40	120 CD @	10 00
4,282 4,316 4,323				4,268							o10,000	LDO 10/	20 SD @	12 01
4,316 4,323					2000 F 310	J. 1011 17U	J 1 G		J., 1J	. 5.5.				
4,316 4,323														
BTD, 4,323				4,282										
BTD, 4,323														
BTD, 4,323				4 240										
1,323				4,316										
1,323	PBTD,				1									
				4,323										
4,375	4,323			,										
1,375														
	4,375			4,375										
				I	1									

Valencia Canyon Unit #5

Proposed P&A

Choza Mesa Pictured Cliffs

1185' FSL, 850' FEL, Section 26, T-28-N, R-4-W, Rio Arriba County, NM / API #30-039-21474

Today's Date: 5/21/14

Spud: 9/17/77 Completed: 10/20/77 Elevation: 7333' GL

7343' KB

12.25" hole

8-5/8", 24#, K-55 Casing set @ 319' Cement with 250 sxs (Circulated to Surface)

Perforate @ 369'

Plug #4: 369' - 0' Class B cement, 120 sxs

TOC unknown, did not circulate and calculated cement should have been to surface. Similar wells have casing issues above the 1100'.

See COA Plug #3: 2180' - 2080' Class B cement, 12 sxs

See COR Plug #2: 3582' - 3310' Class B cement, 25 sxs

Plug #1: 4050' - 3858' Class B cement, 19 sxs

Set CR @ 4050'

Pictured Cliffs Perforations: 4100' - 4316'

4.5", 10.5#, K-55 Casing set @ 4375' Cement with 1265' sxs (1771 cf)

Nacimiento @ 2130' *est


Ojo Alamo @ 3360' *est

Kirtland @ 3532' *est

Fruitland @ 3908' *est

Pictured Cliffs @ 4098'

7-7/8" hole



TD 4375' **PBTD 4333'**

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Valencia Canyon Unit #5

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) *Set plug #2 (3851-3524) ft. to cover the Kirtland and Ojo Alamo tops. Adjust cement volume accordingly.
 - b) *Set plug #3 (2478-2378) ft. to cover the Nacimiento top.

Note: Plugs 1 and 2 can be combined to be set from the CR @ 4050 ft. to 3524 ft. This will be to the discretion of the operator.

*Plugs 1, 2 and 3 will be set inside assuming good cement isolation on backside of 4.5" production casing. Operator will run a CBL to verify cement top. Outside plugs will be required if cement top is not adequate for zonal isolation. Submit electronic copy of the log for verification to the following BLM address: tsalyers@blm.gov

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.