	BI SUNDRY I Do not use this	UNITED STA DEPARTMENT OF TH JREAU OF LAND M NOTICES AND REP form for proposals	HES HE INTERIOR ANAGEMENT ORTS ON WELL to drill or to re-	MA S		201	5. Lease S	78360		
	abandoned well. Use Form 3160-3 (APD) for such proposals.							6. If Indian, Allottee or Tribe Name		
1.7	SUBMIT IN TRIPLICATE Other instructions on page 2. 1. [Type of Well						7. If Unit o	of CA/Agreement, Name and/or No.		
							8. Well Name and No.			
Oil Well Gas Well Other 2. Name of Operator Other							CHACO 2307-13L #238H 9. API Well No.			
WPX Energy Production, LLC					30-039-31213			_		
1	Address D Box 640 Aztec, NM 8	3b. Phone No. (includ 505-333-1822					10. Field and Pool or Exploratory Area Lybrook Gallup			
SH	4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL:1543' FSL & 121' FWL, sec 13, T23N, R7W – BHL:2447' FNL & 285' FWL, Sec 14, T23N, R7W					11. Country or Parish, State Rio Arriba County, NM				
	12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA									
	TYPE OF SUBMISSION TYPE OF ACT						N			
Ē	Notice of Intent	Acidize	Deepen			Produc /Resun		Water Shut-Off		
T		Alter Casing	Fracture Treat			Reclam		Well Integrity		
	Subsequent Report	Casing Repair	New Constructio			Recomj Fempoi	•	Other: COMPLETION		
	Final Abandonment Notice	Change Plans	Plug and Abando	n	Abano	don	Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 3/32/14- MIRU HWS #10										
prsr test csg and WH to 1500 psi and chart for 30 min for integrity test, tested good w/ no leak of							,			
OIL CONS. DIV DIST. 3 3/26/14- RD HWS #10					MAY 2 3 2014					
3/27	7/14- CO to PBTD 10452	MAY 2	282014	<u>C</u> N	NFIL	JEN	ITIAI	FARMINGTON FIELD OFFICE BY: <u>William Tamber</u>	kou	
3/28	3/14 thru 4/13/14-Prepare	for Frac				/61	VIINL			
20/4	0 PSA Sand.		L @ 10530' with 18, 0	.40" ho	les. Frac	: Gallı	up 1 st stage	e 10323'-10530' with 201,383 #		
Name	hereby certify that the foregoing i e (<i>Printed/Typed</i>) y Higgins	s true and correct.		Title	Regula	tory S	Spec		_	
	and the i									
Signature Date 5/22/14 THIS SPACE FOR FEDERAL OR STATE OFFICE USE									-	
Appr	oved by	···· · · · · · · · · · · · · · · · · ·	· · · · · ·			_		······	-	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify t the applicant holds legal or equitable title to those rights in the subject lease which would entitle applicant to conduct operations thereon.					Title Date Office				•	
	18 U.S.C. Section 1001 and Title d States any false, fictitious or fra						to make to ar	ny department or agency of the	-	
(Instructions on page 2)										
	Co	opyright 2006 Forms in Word	(www.formsinword.com)	For ind	ividual or s	single-	branch use	only.		
	NMOCD									

1

٩

. Ap

СНАСО 2307-13L #238Н — раде 2

Set flo-thru frac plug @ 10275' MD. Perf 2nd 10036'-10224' with 32 total, 0.40" holes. Frac Gallup 2nd stage with 212,579 # 20/40 PSA Sand Set flo-thru frac plug @ 9990' MD. Perf 3rd stage 9748'-9933', with 32, 0.40" holes.

4/15/14-Frac Gallup 3rd stage with 193,024#, 20/40_PSA_Sand

Set flo-thru frac plug @ 9710' MD. Perf 4th stage 422 -9640'- with 32, 0.40" holes. Frac Gallup 4th stage with 212,464#, 20/40 PSA Sand Set flo-thru frac plug @ 9380' MD. Perf 5th stage 9073'-9292'-with 32, 0.40" holes. Frac Gallup 5th stage with 213,791#, 20/40 PSA Sand Set flo-thru frac plug @ 9040' MD. Perf 6th stage 8752'-8960' with 32, 0.40" holes. Frac Gallup 6th stage with 212,445#, 20/40 PSA Sand Set flo-thru frac plug @ 9720' MD. Perf 6th stage 8752'-8960' with 32, 0.40" holes. Frac Gallup 6th stage with 212,445#, 20/40 PSA Sand Set flo-thru frac plug @ 8720' MD. Perf 7th stage 8444'-8652' with 32, 0.40" holes. Frac Gallup 7th stage with 218,761#, 20/40 PSA Sand Set flo-thru frac plug @ 8400' MD. Perf 8th stage 8140'-8342'- with 32, 0.40" holes.

4/16/14- Frac Gallup 8th stage with 220,897# , 20/40 PSA Sand

Set flo-thru frac plug @ 8084' MD. Perf 9th stage 7837'-8044'- with 32, 0.40" holes. Frac Gallup 9th stage with 218,454#, 20/40 PSA Sand Set flo-thru frac plug @ 7790' MD. Perf 10th stage 7530'-7741'- with 32, 0.40" holes. Frac Gallup 10th stage with 216,331#, 20/40 PSA Sand Set flo-thru frac plug @ 7480' MD. Perf 11th stage 7224'-7428' - with 32, 0.40" holes. Frac Gallup 11th stage with 244,683#, 20/40 PSA Sand Set flo-thru frac plug @ 7170' MD. Perf 12th stage 6916' 124' - with 32, 0.40" holes. Frac Gallup 11th stage with 271,758#, 20/40 PSA Sand Set flo-thru frac plug @ 6876' MD. Perf 12th stage 6916' 124' - with 32, 0.40" holes. Frac Gallup 12th stage with 271,758#, 20/40 PSA Sand Set flo-thru frac plug @ 6876' MD. Perf 13th stage 6598'-6818'- with 32, 0.40" holes. Frac Gallup 13th stage with 257,507#, 20/40 PSA Sand Set flo-thru frac plug @ 6556' MD. Perf 14th stage 6284'-6494'- with 32, 0.40" holes. Frac Gallup 14th stage with 271,379#, 20/40 PSA Sand Set flo-thru frac plug @ 6556' MD. Perf 14th stage 6284'-6494'- with 32, 0.40" holes. Frac Gallup 14th stage with 271,379#, 20/40 PSA Sand Set flo-thru frac plug @ 6556' MD. Perf 14th stage 6284'-6494'- with 32, 0.40" holes. Frac Gallup 14th stage with 271,379#, 20/40 PSA Sand Set 4-1/2" CIPB @ 5000'

MIRU HWS #7

4/24/14- TEST BOP, DO CIBP @ 5000'

4/25/14 - DO flo thru Frac plug @ 6556', 6876' and 7170'

4/26/14- 4/28/14- DO FISH

4/29/14- DO flo-thru frac plug @ 7480', 7790' and 8084'

4/30/14-5/3/14- DO FISH

5/4/14- First deliver Oil to sales

5/6/14- DO flo-thru frac plug @ 8400' and 8720'

5/7/14- DO flo-thru frac plug @ 9040'

5/8/14- DO flo-thru frac plug @ 9380', 9710' and 9990'

5/9/14- DO flo-thru frac plug @ 10275' Flow, test and C/O well 10523' MD

<u>5/15/14-</u> Land well at 6082' w/ 14' KB as follows 1/2 MS, 1 Jt of 2.375" J55 4.7lb 8rnd EUE tbg, 1.87" XN at 6048', 187 Jts of 2.375" J55 4.7lb 8rnd EUE tbg 188 jts total

<u>5/18/14-</u>Choke Size= 2", Tbg Prsr= 50 psi, Csg Prsr= 650 psi, Sep Prsr= 120 psi, Sep Temp= 65 degrees F, Flow Line Temp= 54 degrees F, Flow Rate= 139 mcf/d, 24hr Wtr= 7 bbls, Total Wtr Accum= 4273 bbls, 24hr Oil= 58 bbls, Total Oil Accum= 3440 bbls

NOTE: 4-1/2" tie back string from surface to TOL @ 6036' will be removed at a later date when artificial lift is installed in this well.