## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

REPERM

1149IND8466
-------------

SUNDRY NOTICES AND REPORTS ON WELLS	P. Essen	1
Do not use this form for proposals to drill or to re-enter an		
abandoned well. Use form 3160-3 (APD) for such proposals.	Λο	20

6. If Indian, Allottee or Tribe Name

		,		() 9 2014	EASTERN NAVA	JO		
SUBMIT IN TRI	PLICATE - Other instruc	tions on rev	erse side.	n Field O	7. If Unit or CA/Agreem	ent, Name and/or No.		
1. Type of Well					Sawell Name and No.	2		
Oil Well Gas Well Oth  2. Name of Operator								
FOUR STAR OIL GAS COMP		9. API Well No. 30-045-30604-00-S1						
			L'Include aren code) 13-1941 L'CONS. DIV DIST. 3		10. Field and Pool, or Exploratory MESAVERDE POINT LOOKOUT			
4. Location of Well (Footage, Sec., T	LOUNS. DIV DIST. 3 11. County or Parish, and State			d State				
Sec 13 T27N R9W SWNE 197	JUL 29 2014		SAN JUAN COUNTY, NM					
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHER	DATA		
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent     ■	☐ Acidize	☐ Deep	oen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	☐ Frac	ture Treat	☐ Reclam	ation	■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	Other		
☐ Final Abandonment Notice	□ Change Plans	Plug	and Abandon	Tempor	arily Abandon	Well Test		
61	☐ Convert to Injection	Plug	Back		Disposal			
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion or the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  It was discovered this well had an issue with the Bradenhead. Please see procedure for proposed repair. The NMOCD is being notified as well.  ? Rig up, install BOPs and test. Recover plunger lift equipment and pull tubing, lay down. ? Run bit and scrapper to PBTD 4550?. Set CBP at ~3800?. Load hole with water and test plug/casing to 500 psi ? Rig up wireline: o Run sector bond log from 3800? to surface  Without applied pressure and 1500 psi of applied pressure o Run noise log? set detector at top of good bond ~3100? ? Seek entry location of bradenhead gas. Review results with NMOCFD staff for next step of performed and correct.  Cementing operation:  O Perforate 4 squeeze holes above suspected gas entry  14. Thereby certify that the foregoing is true and correct.  Electronic Submission #252365 verified by the RIM Well Information System.								
Electronic Submission #252245 verified by the BLM Well Information System For FOUR STAR OIL GAS COMPANY, sent to the Farmington Committed to AFMSS for processing by TROY SALYERS on 07/25/2014 (14TS0147SE)								
Name (Printed/Typed) JAMES MICIKAS			Title PRODUCTION ENGINEER					
Signature (Electronic S	Submission)		Date 07/09/2	2014				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE			
Approved By TROY SALYERS			TitlePETROLE			Date 07/25/2014		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive th	Office Farmington							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					ike to any department or ag	ency of the United		

## Send Email

From:

tsalyers@blm.gov

To:

april.pohl@chevron.com

jdmi@chevron.com

CC:

Subject:

Well JOHN CHARLES 6C

Message:

The sundry for Well Test you submitted has been approved by the BLM. Your original Electronic Commerce (EC) transmission was assigned ID 252245. Please be sure to open and save all attachments to this message, since they contain

important information.

James and April,

BLM Condition of Approval: Submit a copy of the bond log with the subsequent report. Upon drilling cement and retainer out, pressure test squeeze holes to 500 psi for 30 min, with no more than a 10% bleed off.

Attachments:

EC252245.pdf

Approved By:

TROY SALYERS


PETROLEUM ENGINEER

Status:

Queued to Send-2014-07-25 09:39:19

## Chevron

## John Charles #6C San Juan, New Mexico Current Well Schematic as of 3-30-09



Prepared by: Jeannie Kohoutek Date: 3/30/2009