Submit 3 Copies To Appropriate District	Copies To Appropriate District State of New Mexico		Form C-103
District I	Energy, Minerals and N	latural Resources	Jun 19, 2008
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		30-045-09669
District III			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE S
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Salita Pe, INIVI 67505		6. State Oil & Gas Lease No.
87505		FEE	
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name  Harvey
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1
2. Name of Operator			9. OGRID Number
Burlington Resources Oil Gas Company LP			14538
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM 87499-4289			Aztec Pictured Cliffs
4. Well Location			
Unit Letter L: 1718	feet from theSouth	line and923	feet from the West line
Section 9	Township 30N	Range 11W	NMPM San Juan County
	11. Elevation (Show whether 55	<i>DR, RKB, RT, GR, etc.,</i> 588' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			<del></del>
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	<u> </u>
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB []
DOWNHOLE COMMINGLE			
OTHER: MIT		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
Burlington Resources requests permission to perform a MIT to extend the TA status for the subject well per the attached			
procedure and current wents	ore senematic. The last Will W	10	
			DIST. 3
Spud Date:	Rig I	Released Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
() $()$ $()$ $()$ $()$ $()$ $()$ $()$			
SIGNATURE / Xalle X	Susse TITLE	Staff Regulatory	Technician DATE 8 25-14
=• · · · · · · · · · · · · · · · · · · ·	E-mail address: dol	lie.l.busse@conocophil	llips.com PHONE: 505-324-6104
For State Use Only	$\mathcal{O}_{I}$	Deputy Oil 8	& Gas Inspector,
K-///			strict #3
APPROVED BY:	TITLE TITLE	:	DATE 8-29-14
Conditions of Approval (if any):	PY		

## ConocoPhillips HARVEY 1 Expense - MIT

Lat 36° 49' 26.364" N

Long 108° 0' 4.68" W

## PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Notify regulations, Notify regulations,
- 2. MIRU pump truck. Check casing, intermediate, and bradenhead pressures and record them in Wellview. If there is pressure on the BH, contact Wells Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and blow down any casing pressure. Ensure well is dead. Record any pressures seen in Wellview and contact Wells Engineer.
- 4. Load tubing with 2 % KCl water & corrosion inhibitor, as necessary. Perform MIT (Mechanical Integrity Test) above the cement retainer at 1,993 to 560 psig for 30 minutes on a 2 hour chart with 1000# spring. If the test passes, SI the well. RD pump truck and MOL. If the test fails, contact the Rig Superintendent and Wells Engineer.

