Form	3160-	5
(Nove	mber	1994)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM	APP	RO۱	/EC
OMB N	o. 10	004-	013
Expires	July	31,	199

	PARTMENT OF THE INT		,		les July 31, 1996
· ·	JREAU OF LAND MANAGE	1	777	5. Lease Serial No	
SUNDRY NOTICES AND REPORTS ON WELLS				NOO-C-14-20	
Do not use this form for proposals to drill or reenter an abandoned well. Use Form 3160-3 (APD) for such proposals 6 2 1 2014			6. If Indian, Allot		
abandoned well.	. Use Form 3160-3 (APD)	for such proposal	<u> 10 21 2014</u>	Navajo Indian	Allotted
		I *	سد و د د فخارد ۸	7. If Unit or CA/A	Agreement, Name and/or No.
SUBMIT IN TRIPL	ICATE – Other instru	ctions on rever	se side - Omo	NMNM89332	
1.		Section 1	Lacrota Volumetre, Como	wi 11	
Oil Well 🗶 Gas Well	Other			8. Well Name and	i No.
2. Name of Operator				Buena Suerte	33L Com #1
Elm Ridge Exploration Compar	าy, LLC			9. API Well No.	,
3a. Address		3b. Phone No. (inclu	·	30-045-28879	
PO Box 156 Bloomfield, NM 8	-	505-632-3476 ex	t. 201		, or Exploratory Area
4. Location of Well (Footage, Sec., T.,	R., M., or Survey Description)			Basin Fruitlan	
40051 504 W 7001 514/				11. County or Paris	sh, State
1805' FSL X 790' FWL "L" Sec.33-T26N-R11W				San Juan Cou	inty, NM
		Antiomen nenon		<u> </u>	
12. CHECK APPROPRIATE BOX(E	<u>, </u>	OF NOTICE, REPOR	T, OR OTHER DA	TA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
_	Alter Casing	Fracture Treat	Reclamation	`	Well Integrity
Subsequent Report	Casing Repair			_	Other
	Change Plans	Plug and Abandon	_		
Final Abandonment Notice	Convert to Injection	☐ Plug Back	Water Dispo	ısal	
13. Describe Proposed or Completed Operatic If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved ope Testing has been completed. Final Abadetermined that the site is ready for final inspection. The Ridge Exploration Co., attached procedure.	or recomplete horizontally, give si- will be performed or provide the B- erations. If the operation results in andonment Notices shall be filed or ction.)	ubsurface locations and mo bond No. on file with BL a multiple completion or only after all requirements,	easured and true vertical M/BIA. Required substruction in a new including reclamation,	I depths of all pertine equent reports shall be interval, a Form 3160 have been completed. PCVI ag well accordin	ent markers and zones e filed within 30 days 0-4 shall be filed once and the operator has 0 AUG 29 14
					vous. vr. NST. 3
	ζ.				Edla I
SEE ATTACH CONDITIONS OF	APPROVAL operation	inning	BLM'S APPROVAL ACTION DOES NO OPERATOR FROM AUTHORIZATION ON FEDERAL AND	OT RELIEVE THE I I OBTAINING ANY REQUIRED FOR	LESSEE AND Y OTHER
14. I hereby certify that the foregoing s	true and correct	Title			
Name (Printed/Typed) Amy Ai	rchu)eta	Title	Sr. Regula	atory Superviso	or
Signature	- Indiana	Date			
/\/\				ıst 19, 2014	
	THIS SPACE	FOR FEDERAL OR S	TATE USE		
Approved by Troy Salvers		Title Pet	roleum Eng.	Date 8 2	6 a014
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduct	itable title to those rights in the sub	varrant or Office	FO		
Title 18 U.S.C. Section 1001, makes it a c traudulent statements or representations as			y department or agenc	y of the United State	s any false, fictitious or

(Instructions on reverse)



Elm Ridge Resources

Pertinent Data Sheet

Well Name:

Buena Suerte 33L Com #1

Footage:

1805' FSL and 790' FWL

Location:

NWSW Section 33, T26N, R11W

County:

San Juan County, NM

API#:

30-045-28879

Field: Basin Fruitland Coal

Elevation: 6246' KB

TD: 1385' KB

PBTD: 1330' KB

Completed: 01/14/1993

Casing Record:

Į	Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
	8-3/4"	7"	20#	J-55	127'	70.8 cu. ft. (Circ. to surface)
	6-1/4"	4-1/2"	9.5#	J-55	1374'	269.5 cu. ft. (Circ. to surface)

Tubing: 2-1/16" tubing set at 1247'

Formation Tops:

Nacimiento

Surface

Fruitland

1120'

Pictured Cliffs

1276'

Perforations:

Fruitland perforations: 1240'-1262'

Notes:

Wellbore Diagram Buena Suerte 33L Com #1 NWSW Sec. 33, T26N, R11W San Juan County, NM API #30-045-28879

Before

8-3/4" OH 7" 20# J-55 set @ 130' Circulated cmt to surface Nacimiento - surface Fruitland - 1120' Fruitland perforations: 1240'-1262' 2-3/8" tbg set at 1247' Pictured Cliffs - 1276' 6-1/4" OH 4-1/2" 10.5# J-55 set @ 1374' Circulated cmt to surface TD: 1385'

Wellbore Diagram Buena Suerte 33L Com #1 NWSW Sec. 33, T26N, R11W San Juan County, NM API #30-045-28879

After

Nacimiento - surface

8-3/4" OH 7" 20# J-55 set @ 130' Circulated cmt to surface 2-3/8" tbg set at 1247'

Fruitland - 1120'

Pictured Cliffs - 1276'

Fruitland perforations: 1240'-1262'

6-1/4" OH 4-1/2" 10.5# J-55 set @ 1374' Circulated cmt to surface TD: 1385'

Plugging Program for Bisti 33L Com #1

- 1) MOL RU. TOOH with 2-1/16" tubing.
- 2) PU and TIH with 4-1/2" retainer to 1235'. Squeeze below retainer with 11 sx cmt.
- 3) Sting out, mix and pump 98 sx, or sufficient volume, to bring cement to surface inside 4-1/2" casing.
- 4) Cut off well head 4 feet below surface and remediate location in accordance with regulatory agencies' conditions of approval.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment	to	notice	of
Intention to	Αh	andon	

Re: Permanent Abandonment Well: Buena Suerte 33L Com #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Note: H2S has not been reported in this section; however, low concentrations of H2S (11-16 ppm GSV) have been reported in the NE/NE of section 27-26N-11W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.