State of New Mexico Energy, Minerals and Natural Resources Department

	-	
Susana Martinez Governor David Martin Cabinet Secretary Brett F. Woods, Ph.D. Deputy Cabinet Secretary	Jami Bailey, Division Director Oil Conservation Division	OF NEW MCHOO
New Mexico Oil Conservation Divis listed below are made in accordance and are in addition to the actions a following <u>3160-4 or 3</u>	with OCD Rule 19. approved by BLM o	.15.7.11
30-045-31439-00-00 MCKENZIE A 003 XTO ENERGY, INC G A Application Type:	Change Loca	tion Change

Conditions of Approval:

Notify NMOCD 24hrs prior to beginning operations

Extend Ojo Alamo plug up to 305 feet.

NMOCD Approved by Signature

<u>9-15-14</u> Date

:				
· (August 2007) DEPARTM	NITED STATES ENT OF THE INTERIC			FORM ÁPPROVED OMB NO. 1004-0137 Expires July 31, 2010
BUREAU O	F LAND MANAGEME	NT		5. Lease Serial No.
	S AND REPORTS C			NMNM024158
Do not use this form fo abandoned well. Use Fo			ר ד דוח	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICA	ATE - Other instruction		And the second second	7. If Unit or CA/Agreement, Name and/or No NMNM104899
1. Type of Well Oil Well Gas Well Other		AUG 04	2014	8. Well Name and No. MCKENZLE A #3
2. Name of Operator XTO ENERGY INC.		Purcon offeren		9. API Well No.
3a. Address		3b. Phone No. (include an	ea code)	30-045-31439
382 CR 3100 AZTEC, NM 87410 4. Location of Well (Footage, Sec., T., R., M., or Surve	v Description)	505-333-3630		10. Field and Pool, or Exploratory Area BASIN FRUITLAND COAL
	C.9(P)-T30N-R12W	N.M.P.M.		11. County or Parish, State
12. CHECK APPROPRIAT			LOTICE DEDO	SAN JUAN NM
TYPE OF SUBMISSION	TE BOX(ES) TO IND	ICATE NATURE OF N	PE OF ACTION	
		·······		<u> </u>
X Notice of Intent	Acidize	Deepen Fracture Treat	Production Reclamatio	(Start/Resume) Water Shut-Off
Subsequent Report	Casing Repair	New Construction	Recomplete	
Final Abandonment Notice	Change Plans	X Plug and Abandon	Temporaril	
	Convert to Injection	n 🔲 Plug Back	Water Disp	osal
13. Describe Proposed or Completed Operation (clear If the proposal is to deepen directionally or recorn Attach the Bond under which the work will be p following completion of the involved operations. testing has been completed. Final Abandonment determined that the final site is ready for final insp XTO Energy Inc. intends to plug	nplete horizontally, give su performed or provide the B If the operation results in Notices shall be filed only pection.) and abandon this	bsurface locations and meas ond No. on file with BLM. a multiple completion or re y after all requirements, inc well per the attac	sured and true ver BIA. Required so completion in a n sluding reclamatio	tical depths of all pertinent markers and zones. ubsequent reports shall be filed within 30 days ew interval, a Form 3160-4 shall be filed once n, have been completed, and the operator has re and will be using a
Closed Loop System. Please see reclamation plan.	-	6. DIV DIST. 3	osed weilbor	e diagrams and surface
		1 4 2014	see	Attached for
BLM'S APPROVAL OR ACCEPTA ACTION DOES NOT RELIEVE TH OPERATOR FROM OBTAINING A AUTHORIZATION REQUIRED FO ON FEDERAL AND INDIAN LAND	HE LESSEE AND ANY OTHER OR OPERATIONS DS Noti	fy NMOCD 24 hrs or to beginning		ONS OF APPROVAL
		operations		H ₂ S POTENTIAL EXIST
 I hereby certify that the foregoing is true and correct Name (Printed/Typed) SHERRY J. MORROW 	ct	Title REGULA	TORY ANALYS	c
Signature Sherned more	now	Date 8/1/2014	L	
		ERAL OR STATE OF	FICE USE	
Approved by Troy Salves Conditions of approval, if any, are attached. Approval of this n the applicant holds legal or equitable title to those rights in the s	otice does not warrant or certif	y that Office FF0	eum En	g. Date 8132014
entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 121. fictitious or fraudulent statements or representations as to any r			ake to any departme	nt or agency of the United States any false,

n.	-n-	76	ð	Ð	
N	W	N	JU	U	AV

BRB	
MTG	
Approved	

McKenzie A #3 Sec 9, T 30 N, R 12 W San Juan County, New Mexico 6/30/2014

Plug and Abandon Procedure

AFE Number:	1406090				
Spud Date:	5/15/2003				
Surface Casing:	7", 20#, J-55 csg @ 233'. Cmt'd w/64 sx. Circ 9 bbls cmt to surf.				
Production Casing:	4-1/2", 10.5#, J-55 csg @ 2,239'. Cmt'd w/215 sx. Circ 20 bbls cmt to surf. Capacity: .0159 bbls/ft or .6699 gal/ft				
Production Tubing:	2-3/8" string				
Rod String:	3/4" string				
Pump:	1-1/2" insert pump				
Perforations:	Fruitland Coal: 1,928' – 1,951'				
PBTD:	2,196'				
Recent Production:	INA since 4/22/2013. 10 mcfpd, 10 bwpd.				
Notify NMOCD & BLM 24 hours prior to beginning plugging operations					

- 1. Check for COA's and approved NOI before beginning operations.
- 2. Test rig anchors.
- 3. Set flowback tank.
- 4. MIRU completion rig. Review JSA.

÷.

- 5. Kill well.
- 6. TOH & LD rods and pump.
- 7. ND WH. NU & FT BOP.
- 8. TOH tubing.
- 9. TIH 3-7/8" bit & 3-7/8" string mill to 1,928'. TOH.
- 10. TIH 4-1/2" CR and set @ ±1,900'. PT tubing. Sting out of CR and circulate hole clean.

.

- 11. PT casing and CR to 550 psig. If casing does not test, contact engineer.
- 12. MIRU cement truck. Review JSA.
- 13. Perforation Isolation Plug (1,900' 1,850'): Pump 10 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 1,900' 1,850' (volume calculated with 50' excess).
- See CoN
 14. Fruitland Coal Top Plug (1,447' 1,347'): Pump 15 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 1,447' 1,347' (volume calculated with 50' excess).

See COA

- 15. Kirtland & Ojo Alamo Top Plug (553' 331'): Pump 20 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 553' 331' (volume calculated with 50' excess).
- 16. Surface Plug (283' Surface): Pump 30 sx Class "B" cement (15.6 ppg, 1.18 cuft/sx yield) down tubing and spot a balanced plug from 283' Surface (volume calculated with 50' excess).
- 17. TOH & LD tubing.
- 18. RDMO cement truck.
- 19. WOC 4 hours.
- 20. Cut off WH. Fill in casing as needed with cement. Install above ground P&A marker.
- 21. Cut off anchors and reclaim location.

Checklist

Regulatory:

- 1. NOI to P&A on form C-103 & 3160-5
- 2. Submit a post-work sundry on form C-103 & 3160-5 which details the P&A work and location work within 30 days of completing all required restoration work.

Equipment:

- 1. 1 flowback tank
- 2. If tbg does not PT, 2,000' 2-3/8" workstring
- 3. 4-1/2" cement retainer
- 4. 3-7/8" string mill
- 5. 75 sx Class "B" cement
- 6. 1 above ground marker

Services:

- 1. Completion rig
- 2. Cement truck




XTO - Wellbore Diagram

97/JWI 0045314390000	Ell Name: McKenzie A 03 E/W Dist (ft) E/W Ref 14390000 990.0		N/S R				Field Name		Coun		State/Province			
ell Configuration Type		Orig KB Elev (ft)	Gr Elev (ft)	KB-Gr	FSL T30N-F Grd (ft) Spud Dat				Basin Fruitland Coal PBTD (All) (ftKB)			Juan Depth (ftKB)	New Mexico Method Of Production	
ertical	68976	5,732.00	5,726.00		6.00	5/15/2		0	riginal H	ole - 2196.0) :	2,240.0	Beam	
Well Confi	g: Vertical - C	original Hole, 6/30/2014	10:06:41 AM	ftKB	Zones	7000		an yan					Dim (HVD	
State Stat	chematic - Ac	ctual	Ind (TVD)	(MD) 🗟	Fruitland Co		ويجبع الموتيع محموه	100 2 20 24	ALT 142-6-16- \$		1,928.0		<u>'apan Invo</u>	1,95
			.		Casing Str	ings		2 P .	C Children		5			
	1			-6	Casing Descrip Surface	tion	0	D (in) 7		bs/ft) St 20.00	ring Grad J-55	e Top Co	nnection \$	6et Depth (f 233.0
AND DESCRIPTION OF A DE	I ALLIARATE DE CALLAR			6	Casing Descrip	tion		D (in)			ring Grad	e Top Co	nnection S	Set Depth (f
				0	Production			4 1/		10.50	J-55			2,239.0
				10	Cement			<u></u> Тур				String	Pr 901	
					Surface Ca	sing Cem	ent	1	sing			, v	233.0ftKi	3
				28	Comment	04 av. Ci						4		
			i	233	Cmt'd with (Description	04 SX. UI	00 00	Typ				String		
					Production	Casing C	ement	ca	sing			Producti	on, 2,239.	OftKB
				235	Comment	215 sx _ C	irc 20	hbls o	mt to su	f				
				328	Domonto			22.3.15					- 精神の	
				520	Perforation	ю. С		<u>844 . N. s</u> Englisher Englisher		Hole				
8	II I I	······	-	532	Date	Top (fi	KB)	Btm (ft)	(B) (shot	Dens Diamete s/ft)	r Phasir	g Curr	12 Sec.	ine
					5/30/2003	1,9	28.0	1,95	51.0	3.0 0.45	0	AC F	ruitland C	oal
			1	605	Tubing Stri	ings '	البینج میں البینج میں الع	1. S.						
	II Ø			1,528	Tubing Descript	tion		Rur	n Date	27/2012		Set Depth	ftKB) 2.011.6	
					Tubing Col	monent	e de la composita de la compos		ں۔ چھڑچی ا	2112012		 }	2,011.0	
				1,853	1 25 C			<u>.</u>		Wt (lbs/ Gra	Top		Contraction of the	
	H A			1,928	Tubing	ription		T&C		4.70 J-55		1.974.51	<u>- ιορ (πκΒ)</u> 6.(
		Top (MD):1,928,		1,520	· • • • • • •			Upset				.,		.,.
19	E E	Des:Fruitland Coal		1,951	Seat Nipple)	1		2 3/8			1.10		- i-
				1.050	OEMA	7.8 24 5	1	Wr. C.	2 3/8	4.70 J-55	E starter	30.00		3 2,0
				1,959	Rods Rod Description		Run D	ate		String Ler	ath (ft)		et Depth (ftK	R)
				1,978	Rod String		1	3/27	/2012		1,997.0			91.0
					Rod Comp	onents		<u>n a a</u> sh	s t Par		6	S		
				1,979	Polished Ro		<u></u> 29	<u>Jtş ş¦≓</u> 1	Model	OD (in) Gr	ade	16.00	<u>-(iop (πκΒ)</u> -6.0	
	ИВ			1,979	Rod Sub			3		3/4 D		18.00	10.0	
					Sucker Roo	l w/Molde	d	12		3/4 D		300.00	28.0	3
	IT B			1,980	Guides			61 1	UCN 70	2/4 D		525.00	228.0	1 0
				1 0.04	Sucker Roc Sucker Roc		d	3	VCN-78	3/4 D 3/4 D		,525.00 75.00	328.0	
				1,981	Guides		-	Ĩ					.,	.,0
	R E			1,982	Sinker Bar			2		1 1/4 K		50.00	1,928.0	· · ·
8	ANE			4 6 5 5	Lift Sub Spiral Rod	Guido		1		3/4		1.00 0.40	1,978.0	
	n B			1,990	Spiral Rod RHBO Tool			$-\frac{1}{1}$		3/4	-+	0.40	1,979.0	
				1,991	Rod Insert	Pump		1		1 1/2		10.00	1,980.0	1,9
					Strainer Nip			1	The second	1		1.00	1,990.0	
				2,011	Stimulatio	Top Perf (ff	Botto	n Pe	V (slurrv) (. AIR (b.	ATP (psi)	MTP (ps) SIP (p
	<u></u>			2,190	6/3/2003	1928		951	(183,76			0 2,114.	
	ß				Comment Frac'd w/10)2 856 and	s 20#	XI ae	wtr carr	ving 183 76		40 Brady	sd coated	with
				2,19 5	Sandwedge		JJ ∠U#	∧∟ ye	i wa Gali	ying 100,70	/U# 2.0/	ro Diauy	Ju Juaieu	****
PBTD,				2 400						_				
2,196				2,196										
				2,236										
2				2,239										
D, 2,240				2,240										
· • • · ·			1 1	, <u>, , , , , , , ,</u> , , , , , , , , , ,	1									

McKenzie A #3 Sec 9, T 30 N, R 12 W San Juan County, New Mexico

Proposed P&A Diagram



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: McKenzie A #3

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

3. The following modifications to your plugging program are to be made:

- a) Set plug #2 from (1661-1561) ft. to cover the Fruitland top. BLM picks the top of the Fruitland at 1611 ft.
- b) Set plug #3 from (649-390) ft. to cover the Kirtland and Ojo Alamo tops. BLM picks the top of the Kirtland at 599 ft., top of Ojo Alamo at 440 ft.

Note: Low concentrations of H2S (10 ppm- 20ppm GSV) have been reported in wells within a 1 mile radius of this location.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.