Form 3160-5 (August 2007) DEPARTMEN BUREAU OF SUNDRY NOTICES Do not use this form for y abandoned well. Use Form SUBMIT IN TRIPLICAT 1. Type of Well Oil Well X Gas Well Other 2. Name of Operator XTO Energy Inc. 3a. Address 382 CR 3100, AZTEC, NM 87410 4. Location of Well (Footage, Sec., T., R., M., or Survey II 1,190' FNL & 820' FWL NWNW SE	FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010 5. Lease Serial No. NMNM8405 6. If Indian, Allottee or Tribe Name PCUD OCT 3 '14 OIL COMS. DILL 7. If Unit or CA/Agreement, Name and/or No. NMNM75814 DIST. 3 8. Well Name and No. CANYON #6E 9. API Well No. 30-045-29154 10. Field and Pool, or Exploratory Area BASIN DAKOTA 11. County or Parish, State						
	or Mancos formation.	SAN JUAN NM					
12. CHECK APPROPRIATE	E BOX(ES) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF AG	CTION					
Notice of Intent Subsequent Report Final Abandonment Notice	Alter Casing Fracture Treat R Casing Repair New Construction X R Change Plans Plug and Abandon T	roduction (Start/Resume) water Shut-Off Well Integrity ecomplete Emporarily Abandon PASIN MC & PWOP Ater Disposal					
Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) XTO Energy Inc. proposes to recomplete this well to the Basin Mancos formation per the following: MIRU. TOH with 2-3/8" tbg. Pick up bit and string mill, clean out to PBTD @ 6,089. MIRU WLU. RIH with 4-1/2" CIBP plug and set at 5,300'. PT casing to 4,280 psig. Perforate Mancos with a 3-1/8" select fire csg gum with 1 JSPF (0.41" dia., 25 holes). POH w/csg gum. RDMO WLU. Acidize with 1,000 gals of 15% NEFE HCl acid. Frac Mancos perfs from 4,833' - 5,093' with 138,895 foam gals carrying 175,000 lbs 20/40 Brady sand & 25,000 lbs 20/40 SLC sand. CO to CIBP at 5,300'. Circ clean. Run IP test. Drill out CIBP at 5,300' and CO to PBTD at 6,089'. TIH with 2-3/8" tubing to land EOT at 6,000'. TIH w/rods & pmp.							
Please see the attached WED, formation tops & Basin Mancos C102 Plat. An application to DHC will be submitted separately. XTO Energy Inc. will obtain the DHC order before commingling. BLM'S APPROVAL OR ACCEPTANCE OF THIS							
SEE ATTAC CONDITIONS O	F APPROVAL OPER	ON DOES NOT RELIEVE THE LESSEE AND ATOR FROM OBTAINING ANY OTHER ORIZATION REQUIRED FOR OPERATIONS COFRAL AND INDIAN LANDS					
14. I hereby certify that the foregoing is true and correct Name (Printed Typed) SHERRY J. MORROW	Title REGULATORY A	NALYST					
Signature Llung Comprison Date 9/11/2014							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by Salvers Conditions of approval, if any, are attached. Approval of this noti the applicant holds legal or equitable title to those rights in the subentitle the applicant to conduct operations thereon.		Eng. Date 10 1 2014					
Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, infictitious or fraudulent statements or representations as to any ma	makes it a crime for any person knowingly and willfully to make to any iter within its jurisdiction.	department or agency of the United States any false,					



www.peloton.com

XTO - Wellbore Diagram

Well Name: Canyon 06E API/UWI E/W Dist (ft) N/S Dist (ft 30045291540000 820.0 1,190.0 FNL. T25N-R11W-S11 Basin Dakota San Juan New Mexico Well Configuration Type IXTO ID B Orig KB Elev (ft) KB-Grd (ft) Total Depth (ftKB) Gr Elev (ft) Spud Date PBTD (All) (ftKB) Method Of Production 70141 Vertical 6,327.00 6,311.00 16.00 8/26/1994 Original Hole - 6089.0 6,132.0 Plunger Lift .Well Config: Vertical - Original Hole, 5/27/2014 4:34:11 PM Zones ftKB ftKB Top (ftKB) Schematic - Actual Incl (TVD) (MD) : Dakota 5,792.0 5,928,0 Casing Strings Casing Description OD (in) Wt (lbs/ft) Set Depth (ftK String Grade Top Connection Surface J-55 8 5/8 24.00 872.0 Casing Description OD (in) Vt (lbs/ft) String Grade Top Connection Set Depth (ftK. 16 Production 4 1/2 11,60 K-55 6,132.0 Cement Surface Casing Cement Surface, 872.0ftKB casing 872 Cmt'd w/800 sx CL B Cmt w/2% CaCl2 & 1/4#/sx Flocele. Circ Cmt to surf. Туре String **Production Casing Cement** casina Production, 6,132.0ftKB 875 Cmt'd w/950 sx CL B 50:50 POZ w/2% Gel, 5#/sx Gilsonite, 0.8 Halad 344 & 1.4#/sx Flocele foamed cmt. Tailed in w/200 sx CL B 50:50 POZ w/2% Gel, 5#/sx Gilsonite, 0.8 Halad 344 & 1.4#/sx Flocele. Cap Top Cmt w/100 sx CL B Cmt w/2% CaCl2. Circ Cmt to Surf. 5 792 **Perforations** Hole Shot Dens Diameter Phasing Curr. Date Top (ftKB) Btm (ftKB) (shots/ft) (°). Status Zone 5,796 9/7/1995 5,792.0 5,810.0 2.0 Dakota 9/21/1994 5,796.0 5,918.0 Dakota 9/7/1995 5,860.0 5.904.0 2.0 Dakota 9/7/1995 5.908.0 5.928.0 2.0 Dakota 5,810 **Tubing Strings** Run Date Set Depth (ftKB) Tubing - Production 9/7/1995 5,874.0 **Tubing Components** Top (MD):5,792, 5 860 Des:Dakota Thread Item Description Model OD (in) (lbs/... Gra. Len (ft) Top (ftKB) Btm (ftKB) Tubing T&C 2 3/8 4.70 J-55 8RD 5,858.00 16.0 5,874.0 Upset EUE 5,874 Rods Run Date String Length (ft) Rod Description Set Depth (ftKB) **Rod Components** OD (in) Grade 5.904 Model Top (ftKB) Btm (ftKB) Stimulations & Treatments Frac Start Date | Top Perf (ft... | Bottom Pe. AIR (b.. MTP (psi) |ISIP (psi) V (slurry) (... Total Prop... ATP (psi) 5796 3,667.0 3,720.0 10/3/1994 5918 157,00.. 20 5,908 Frac DK f/5,796'-5,918' w/27,216 Gals 70 Q Foam & 157,000# 20/40 Ottawa SD @ 20 BPM & 3,667 PSIG. ISIP 3,720 PSIG. 5" SIP 2,968 PSIG. 10" SIP 2,942 PSIG. 15" SIP 2,953 PSIG 5.918 5,928 PBTD 6.089 6.089 6,132 TD, 6,132

Page 1/1

Report Printed: 5/27/2014

37. SUNIMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

GEOLOGIC MARKERS

FORMATION	ТОР	воттом		DESCRIPTION	N, CONTENTS,	ETC.		то	98
						'	NAME	MEAS, DEPTH	TRUE VERT. DEPTH
			,						· (
							IRUITLAND	940	
		;					PICTURE CLIFFS	1350'	
							LEWIS	1400	
							CLIFF HOUSE	2782'	
							Menefee	2830'	
							Point Lookout	3774'	
							Mancos	4140'	
							Collup	4380'	
							CREENHORN	5696	-
							Chaneros	5750'	
. • •							Dahota Mprezisan	5785	
							" piccisari	6085	
es de		,							
				•		•			
,									
	<u> </u>								
•								COVERNING OF UNIVERSE	PARTITIONS AND AREAS
							10.3	S. GOVERNMENT PRIMITING	COPPUTE P94-574-226

District I 1625 N. French Dr., Hobbs, NM 88240

<u>District II</u> 811 South First, Artesia, NM 88210

District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals & Natural Resources Department **OIL CONSERVATION DIVISION** 1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-102 Revised October 19, 2009 Submit one copy to appropriate District Office

1220 S. St. Francis	Dr., Santa F	,	TILIC)	A AND A CD	DE A CE DEDIC	CATION DI A	_	AME	NDED REPORT	
				CATION	N AND ACK	REAGE DEDIC	ATION PLA	1 1			
¹ API Number			T	² Pool Code		³ Pool Name					
30-	30-045-29154 97232					BASIN MANCOS					
⁴ Property (Code	⁵ Property Name					⁶ Well Number			Well Number	
2266	9	-	CANYON							#6E	
7OGRID	No.		8 Operator Name							9 Elevation	
5380)		XTO ENERGY INC.							6311'	
¹⁰ Surface Location											
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West	line	County	
D	11	25N	11W		1190'	NORTH	820'	WES1	г	SAN JUAN	
¹¹ Bottom Hole Location If Different From Surface											
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West	line	County	
SAME											
12 Dedicated Acres MC: 320 ACRE	1	r Infill 14 (Consolidation	Code 15 Or	rder No.						

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-

STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION								
.0611			17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true & complete to the best of my knowledge & belief and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. Lucy American Street, and the information of the proposed by the division.					
BASIN MANCOS	_11		Signature Sherry J. Morrow Printed Name SHERRY J. MORROW Title REGULATORY ANALYST Date 9/11/2014 SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of					
			actual surveys made by me or under my supervision, and that the same is true & correct to the best of my belief. 6/23/1984 Date of Survey Original Survey Signed By: John A. Vukonich					
			14831 Certificate Number					

BLM CONDITIONS OF APPROVAL

CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed **prior** to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations: Please contact Troy Salyers @ (505) 608-1989 if casing leaks are identified and a plan of repair is established.

SPECIAL STIPULATIONS:

ال ان به و

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.