Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter approach to the form 2160-2 (APD) for such proposals 17 2014

6. If Indian, Allottee or Tribe Name

| | II. Use form 3160-3 (APD) for | | | o. Il maian, motice c | THOC Name |
|---|---|--|---|-------------------------------|------------------------|
| SUBMIT IN TRI | PLICATE - Other instructions | on reversessidencion | Field Off | റ്റു If Unit or CA/Agre അബ | ement, Name and/or No. |
| 1. Type of Well | | President Lat 1 with | Bi . Wale SOld | 8. Well Name and No. | |
| ☐ Oil Well 	☐ Gas Well ☐ Other . | | | | GALLEGOS CANYON UNIT 265 | |
| Name of Operator BP AMERICA PRODUCTION | A COLVIN .com | 9. API Well No. 30-045-20655-00-S1 | | | |
| 3a. Address 200 ENERGY COURT FARMINGTON, NM 87401 | Phone No. (include area code) 281-366-7148 | | 10. Field and Pool, or Exploratory BASIN MANCOS | | |
| 4. Location of Well (Footage, Sec., T | | | 11. County or Parish, and State | | |
| Sec 25 T28N R12W SESE 79 36.628080 N Lat, 108.056210 | | | SAN JUAN COUNTY, NM | | |
| 12. CHECK APPE | ROPRIATE BOX(ES) TO IND | DICATE NATURE OF N | OTICE, RE | PORT, OR OTHE | R DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | | | | |
| Notice of Intent ■ | ☐ Acidize | ☐ Deepen | ☐ Producti | on (Start/Resume) | ☐ Water Shut-Off |
| _ | ☐ Alter Casing | ☐ Fracture Treat | ☐ Reclama | tion | ■ Well Integrity |
| ☐ Subsequent Report | □ Casing Repair | ■ New Construction | ☐ Recomp | lete | ☐ Other |
| ☐ Final Abandonment Notiae | ☐ Change Plans | ☑ Plug and Abandon | ☐ Tempora | arily Abandon | |
| est 1 | ☐ Convert to Injection | □ Plug Back | ■ Water Disposal | | |
| for the amended P&A procedu Powell of the NMOCD. Please see the attached proce | rit Rule 19.15.17.9 NMAC, BP / | 2014 from Troy Salyers America Production Com | at the BLM a | and Brandon | RECEIVED JAN 2 8 2015 |
| ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER CD AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS | | | | | |
| 14. I hereby certify that the foregoing is | Electronic Submission #28556 | DUCTION CO, sent to the | Farmington | - | |
| · · · · · · · · · · · · · · · · · · · | | | ATORY ANA | • | |
| | | | | | |
| Signature (Electronic S | Submission) | Date 12/17/20 | 014 | | |
| | THIS SPACE FOR F | EDERAL OR STATE | OFFICE US | SE | |
| Approved By_TROY SALYERS | | TitlePETROLE | EUM ENGINEER | | Date 01/26/2015 |
| Conditions of approval, if any, are attache ertify that the applicant holds legal or equivalent would entitle the applicant to conductive the conductive the applicant to conduct the applicant | et lease | Office Farmington | | | |
| Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent | | | willfully to ma | ke to any department or | agency of the United |

Gallegos Canyon Unit 265

Mancos
API # 30-045-20655
T-28N, R-12-W, Sec. 25
San Juan County, New Mexico


BP would like to request approval to amend the P&A program for GCU 265 as per following procedure.


All cement will be class B, mixed at 15.60 ppg, 1.18 cf/sx

- 1. RIH and set a cement retainer @ 5650'. MIT (500psi)
- 2. Pump balanced cement plug on top of CICR 5.4 bbls/26sks (Top Mancos perforations)
- 3. POH to 3400' and pump 4.2 bbls/20sks cement plug (Mesaverde top)
- 4. POH to 2406' and pump 4.2 bbls/20sks cement plug (Chacra top)
- 5. POH to 1780' and pump 6.5 bbls/31sks cement plug (Picture Cliffs and Fruitland tops)
- 6. POOH and LD tubing
- 7. RIH and perforate 5' from 700'-695'
- 8. Try to establish circulation to surface.
- 9. If GOOD circulation to surface, then Set cement retainer at 675'
- 10. Balance plug 11.0 bbls inside and 31 bbls outside casing. Mix 200 sks. Continue step 17
- 11. If **NO** circulation to surface, then pump 3.3 bbls inside casing from 700'.16sks cement plug (Kirtland and Ojo Alamo tops)
- 12. RIH and perforate 5' from 435'-430'
- 13. Establish circulation to surface
- 14. Set cement retainer at 410'
- 15. Balance plug 7.0 bbls inside and 19.0 bbls outside casing. Mix 130 sks.
- 16. Cut wellhead and weld plate with marker and P&A information

Attachments:

- current wellbore diagram
- proposed WBD P&A





Created by Neevia Document Converter trial version http://www.neevia.com