		F THE INTERIOR D MANAGEMENT	FEB 03 20	15	OMB No. 1004-0137 Expires: March 31, 2007	
		•	e	5. Lease Serial		
SUNDRY	NOTICES AND	REPORTS ON WE	ELS CONTRACTOR	A CONTRACT		
abandoned wel	l. Use Form 316	osals to drill or to ro 0-3 (APD) for such	proposals.	6. If Indian, Al	lottee or Tribe Name	
		E – Other instructions on	<u>· · · · · · · · · · · · · · · · · · · </u>		A/Agreement, Name and/or No.	
1. Type of Well				132829	1	
• 🛛 Oil Well	Gas Well	Other			COM #265H	
2. Name of Operator WPX Energy Production, LLC				9. API Well No. 30-039-31290		
3a. Address PO Box 640 Aztec, N	ddress 3b. Phone No. (inclu		irea code)	4). Field and Pool or Exploratory Area	
4. Location of Well (Footage,	Sec., T.,R.,M., or Surve		Chaco Unit NE HZ(c 11. Country or Parish,			
SHL: 1366' FSL & 268' FWL BHL: 1553'FNL & 915' FWI				Rio Arriba, NN	Λ	
		TE BOX(ES) TO INDICAT	E NATURE OF NOTIC	L. CE, REPORT OR	OTHER DATA	
TYPE OF SUBMISSION			TYPE OF ACTIO	N		
Notice of Intent	Acidize	Deepen	Production (St	art/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
	Casing Repair	New Construction	Recomplete		Other	
	Change-Plans	Plug and Abandon	Temporarily A	bandon SPUD SURFACE		
Final Abandonment	Convert to	<u> </u>				
Notice 3. Describe Proposed or Com duration thereof. If the pro all pertinent markers and subsequent reports must b recompletion in a new into	Injection pleted Operation: Clear pposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m	ctionally or recomplete hori under which the work will ollowing completion of the ust be filed once testing has	zontally, give subsurfac be performed or provide involved operations. If t been completed. Final A	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Not	proposed work and approximate easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all	
Notice 3. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and subsequent reports must b recompletion in a new into requirements, including re-	Injection pleted Operation: Clear oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m sclamation, have been c	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final A	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Not	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all	
Notice 13. Describe Proposed or Com duration thereof. If the pro all pertinent markers and subsequent reports must b recompletion in a new into requirements, including re NOTE: MO-TE SET SURFAC	Injection pleted Operation: Clean oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m cclamation, have been c	rly state all pertinent details, ctionally or recomplete hori under which the work will following completion of the uust be filed once testing has completed and the operator h	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final A	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Not	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and a subsequent reports must b recompletion in a new into requirements, including re NOTE: MO-TE SET SURFAC	Injection pleted Operation: Clear posal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m eclamation, have been c CE S. <u>TD 12-1/4</u> " SURF	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the ust be filed once testing has completed and the operator f	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>i</i> has determined that the s	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Not	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and a subsequent reports must b recompletion in a new inter- requirements, including re- NOTE: MO-TE SET SURFACE L/28/15- SPUD @ 08:00HR L/29/15-RAN 13jts, 9-5/8", rest lines, pump 10bbls FW	Injection pleted Operation: Clear oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m sclamation, have been c c F S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#_1-55</u> _CSC / spacer & 51bbls Typ	rly state all pertinent details, ctionally or recomplete hori under which the work will following completion of the sust be filed once testing has completed and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>i</i> has determined that the s	rting date of any p e locations and me the Bond No. on he operation resul Abandonment Noi ite is ready for fin	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and : subsequent reports must b recompletion in a new into requirements, including re NOTE: MO-TE SET SURFAC L/28/15- SPUD @ 08:00HR L/29/15-RAN 13jts_9-5/8", rest lines, pump 10bbls FW 202psi. Circ 24bbls good cn	Injection pleted Operation: Clear oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m calamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#_1-55.</u> CSC ' spacer & 51bbls Typ nt to surface. RDMO	rly state all pertinent details, ctionally or recomplete hori under which the work will following completion of the sust be filed once testing has completed and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te.	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s <i>f</i> . SPPG. Dropped plug <i>§</i>	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Nor ite is ready for fin	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and : subsequent reports must b recompletion in a new inter requirements, including re- NOTE: MO-TE SET SURFAC 1/28/15- SPUD @ 08:00HR 1/29/15-RAN 13jts_9-5/8", Fest lines, pump 10bbls FW 202psi. Circ 24bbls good cm NOTE: WPX will MI AWS to 4. I hereby certify that the pree Name (Printed/Typed)	Injection pleted Operation: Clear oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m eclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#.1-55.</u> CSG / spacer & 51bbls Typ nt to surface. RDMO	rly state all pertinent details, ctionally or recomplete hori under which the work will following completion of the sust be filed once testing has completed and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te.	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s 9. 8PPG. Dropped plug & file another sundry at	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Nor ite is ready for fin	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and : subsequent reports must b recompletion in a new inter requirements, including re- NOTE: MO-TE SET SURFAC 1/28/15- SPUD @ 08:00HR 1/29/15-RAN 13jts_9-5/8", Fest lines, pump 10bbls FW 202psi. Circ 24bbls good cm NOTE: WPX will MI AWS to 4. I hereby certify that the pree Name (Printed/Typed)	Injection pleted Operation: Clean oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m eclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#, 1-55</u> , CSG / spacer & 51bbls Typ nt to surface. RDMO o Install & test BOP a oing is true and correct.	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the uust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te. at a later date. We will f	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s BPPG. Dropped plug & file another sundry at Permit Tech	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Noi ite is ready for fin & displaced w/ 2 t that time.	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and is subsequent reports must be recompletion in a new intor requirements, including re- NOTE: MO-TE SET SURFAC 1/28/15- SPUD @ 08:00HR 1/29/15-RAN 13jts_9-5/8", Fest lines, pump 10bbls FW 202psi. Circ 24bbls good cm NOTE: WPX will MI AWS to 4. Thereby certify that the force lame (Printed/Typed) Marie E. Jaramillo Signature	Injection pleted Operation: Clean oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m eclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#, 1-55</u> , CSG / spacer & 51bbls Typ nt to surface. RDMO o Install & test BOP a oing is true and correct.	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the uust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te. at a later date. We will f	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s BPPG. Dropped plug & file another sundry at Permit Tech	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Nor ite is ready for fin	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice 3. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and : subsequent reports must b recompletion in a new into- requirements, including re- NOTE: MO-TE SET SURFAC 1/28/15- SPUD @ 08:00HR 1/29/15-RAN 13jts_9-5/8", Test lines, pump 10bbls FW 202psi. Circ 24bbls good cm NOTE: WPX will MI AWS to 4. Thereby certify that the force lame (Printed/Typed) Marie E. Jaramillo Signature	Injection pleted Operation: Clean oposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m eclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#, 1-55</u> , CSG / spacer & 51bbls Typ nt to surface. RDMO o Install & test BOP a oing is true and correct.	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the uust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te. at a later date. We will f	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s BPPG. Dropped plug & file another sundry at Permit Tech	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Noi ite is ready for fin & displaced w/ 2 t that time.	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice (3) Describe Proposed or Com duration thereof. If the pro- all pertinent markers and is subsequent reports must be recompletion in a new inter requirements, including re NOTE: MO-TE SET SURFACE (28/15- SPUD @ 08:00HR (29/15-RAN 13jts, 9-5/8", Fest lines, pump 10bbls FW 202psi, Circ 24bbls good cm NOTE: WPX will MI AWS to (4) Thereby certify that the pree lame (<i>Printed/Typed</i>) Marie E. Jaramillo Signature onditions of approval, if any, ar certify that the applicant holds	Injection pleted Operation: Clean poposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m clamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C <u>, 36#.1-55.</u> CSC / spacer & 51bbls Typ nt to surface. RDMO D Install & test BOP a oing is true and correct. MARK SPA e attached. Approval of t legal or equitable title to	rly state all pertinent details, ctionally or recomplete hori under which the work will ollowing completion of the uust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.8 Mo-Te. at a later date. We will f <u>Title</u> Date ACE FOR FEDERAL	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If t been completed. Final <i>J</i> has determined that the s BPPG. Dropped plug & file another sundry at Permit Tech CR STATE OFF	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Noi ite is ready for fin & displaced w/ 2 t that time.	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.)	
Notice 13. Describe Proposed or Comduration thereof. If the proal pertinent markers and is subsequent reports must be recompletion in a new interequirements, including response of the properties of t	Injection pleted Operation: Clean poposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m sclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C, <u>36#, 1-55, CSC</u> / spacer & 51bbls Typ nt to surface. RDMO D Install & test BOP a oing is true and correct. WAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the ust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.4 Mo-Te. at a later date. We will f Mo-Te. at a later date. f Mo-Te. at a lat	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If the been completed. Final <i>J</i> has determined that the s solution of the subsurfactors in the subsur	rting date of any p e locations and m the Bond No. on he operation resul Abandonment Noi ite is ready for fin & displaced w/ 2 t that time. FICE USE	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.) 29bbls H2O. Bumped plug @ Date	
Notice 13. Describe Proposed or Com duration thereof. If the pro- all pertinent markers and is subsequent reports must be recompletion in a new inter- requirements, including re- NOTE: MO-TE SET SURFACE 1/28/15- SPUD @ 08:00HR 1/29/15-RAN 13jts_9-5/8", Fest lines, pump 10bbls FW 202psi. Circ 24bbls good cm NOTE: WPX will MI AWS to 4. I hereby certify that the pree- Name (Printed/Typed) Marie E. Jaramillo	Injection pleted Operation: Clean poposal is to deepen dire zones. Attach the Bond e filed within 30 days f erval, a Form 3160-4 m sclamation, have been c E S. <u>TD 12-1/4</u> " SURF ST&C, <u>36#, 1-55, CSC</u> / spacer & 51bbls Typ nt to surface. RDMO D Install & test BOP a oing is true and correct. WAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	rly state all pertinent details ctionally or recomplete hori under which the work will ollowing completion of the ust be filed once testing has sompleted and the operator f HOLE @ 418'. G <u>SET @ 413'</u> , FC @ 379 pe G cmt (245sxs) @ 15.4 Mo-Te. at a later date. We will f Mo-Te. at a later date. f Mo-Te. at a lat	, including estimated sta zontally, give subsurfac be performed or provide involved operations. If the been completed. Final <i>J</i> has determined that the s solution of the subsurfactors in the subsur	rting date of any p e locations and m the Bond No. on he operation result Abandonment Nor ite is ready for fin & displaced w/ 2 t that time. IICE USE	easured and true vertical depths of file with BLM/BIA. Required its in a multiple completion or tices must be filed only after all al inspection.) 29bbls H2O. Bumped plug @ Date	