Form 3160-5

INITED STATES

السان	FORM APPROVES
	 - : : : : : : : : : : : : : : : : : : :

(February 2005)	DEPARTMENT OF	THE INTERIOR	السرك سال		OMB No. 1			
		MANAGEMENT		15	Expires: Mar	rch 31, 2007		
			11 20	3. Lease Seri	al No.	/ RECEIVE		
SUNDRY	NOTICES AND I	REPORTS ON WE	ELLO. 11	1300 H	1-1000	<u> </u>		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, A	Allottee or Tri	be Name FEB 1 7 2015		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					CA/Agreemer	Name and/or No.		
1. Type of Well	THE TRUE LIGHT	Outer manded one of	r page 2.		<i>6</i>	COOMM /		
Oil Well Gas Well Other					8. Well Name and No. Chaco 2308 04L #284H			
2. Name of Operator					9. API Well No.			
WPX Energy Production, LLC 3a. Address 3b. Phone No. (include area code)				30-045-35607 10. Field and Pool or Exploratory Area				
PO Box 640 Aztec, N	M 87410	505-333-1808			Nageezi Gallup / Basin Mancos			
4. Location of Well <i>(Footage, Sec., T.,R.,M., or Survey Description)</i> SHL: 2431' FSL & 383' FWL, Sec 4, T23N, R8W BHL: 2220'FSL & 230' FWL, Sec 5 T23N, R8W				11. Country or Parish, State San Juan, NM				
12. CHEC	K THE APPROPRIATI	E BOX(ES) TO INDICA	TE NATURE OF NOTIC	E, REPORT OI	R OTHER DA	ATA		
TYPE OF SUBMISSION			TYPE OF ACTION	1				
□ x .: sxt	Acidize	Deepen	Production (Sta	art/Resume)	Water	Shut-Off		
Notice of Intent	Alter Casing	Fracture Treat	Reclamation		Well I	Integrity		
	Casing Repair	New Construction	Recomplete		Other_			
Subsequent Report	Change Plans	Plug and Abandon	Temporarily Al	bandon SPUD SURFACE CASING				
Final Abandonment	Convert to Injection	Plug Back	Water Disposal	l		51110		
duration thereof. If the propagation and zero subsequent reports must be recompletion in a new interrequirements, including reconditions and the second seco	ones. Attach the Bond u filed within 30 days fol rval, a Form 3160-4 must clamation, have been con	nder which the work will llowing completion of the st be filed once testing ha	be performed or provide involved operations. If the involved operations is been completed. Final A	the Bond No. o. ne operation res .bandonment N	n file with BL ults in a multi lotices must be	M/BIA. Required iple completion or effect only after all		
2/9/15- SPUD @ 08:00HRS.	TD_12-1/4" SURF HC	LE <u>@</u> 419'.						
2/10/15-RAN 13jts, 9-5/8", 9	ST&C, 36#, J- <u>55, CSG</u>	SE <u>T @ 414</u> ', FC @ 380)'.					
Test lines, pump 10bbls FW			.8 PPG. Dropped plug 8	k displaced w	/ 29bbls H20	O. Bumped plug @		
235psi. Circ 25bbls good cm	: to surface. RDMO N	lo-Te.						
NOTE: WPX will MI AWS to	Install & test BOP at	a later date. We will	file another sundry at	that time. 🗸				
14. I hereby certify that the forego Name (<i>Printed/Typed</i>) Marie E. Jaramillo	ing is true and correct.	Tit	le Permit Tech					
Signature J	ma		te 2/11/15 L OR STATE OFFI	OF USE				
Approved by	I HIS SPAC	SE FUR FEDERA	LORSTATEOFFI	CE USE	·			
- Approved by		•	Titlo		Data			
Conditions of approval, if any, are or certify that the applicant holds lease which would entitle the appli	egal or equitable title to the	nose rights in the subject	Office		Date			
Title 18 U.S.C. Section 1001 and Tunited States any false, fictitious of				fully to make to	any departmen	nt or agency of the OR RECOSD		

(Instructions on page 2)

FTB 12 205

NWCCDPY

FARMINGTON FIELD OFF! BY: William Tarmbekon Copyright 2006 Forms in Word (www.formsinword.com). For individual or single-branch use only.