Form 3160-5 (August 2007)

✓ Final Abandonment Notic

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Convert to Injection

SUNDRY NOTICES AND REPORTS ON WELLS 1 2 2015

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. SF-078243

6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals office Bureau of Land Managementi (Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 1. Type of Well 8. Well Name and No Oil Well Gas Well Other Southern Union #2E 2. Name of Operator Roddy Production Co. 9. API Well No. 30-045-24387 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 2221 Farmington NM 87499 Basin Dakota 505 325 5750 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State San Juan County New Mexico 2690' FSL 965' FWL, S-31, T-27N, R-08W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Deepen Acidize Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Install Dry Hole Mark Casing Repair New Construction Recomplete Subsequent Report July 29 2003 Plug and Abandon ___ Change Plans Temporarily Abandon

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Plug Back

July 29 2003: Dug out old well head. Remove temporary cap, fill 4 1/2" casing with 11 sacks (5.5 cf) quickcrete. Weld on dry hole marker on 4 1/2" casing stub. Fill bell hole and level area around dry hole marker. This completes rehab requirements for this well bore. Location will be reclaimed when the Owen #2R is plugged and abandoned. This sundry was sent to the BLM in August 2003.

OIL CONS. DIV DIST. 3

Water Disposal

PARMINGTON COPY

MAR 1 9 2015

Entered into AFMSS

	By: M. Nelly
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	
Jeremy Divine	Title Foreman
Signature Rumy Jww	Date 03/05/2015
THIS SPACE FOR FEE	DERAL OR STATE OFFICE USE
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant of	Title MAR 1 3 2015
Conditions of approval, if any, are attached. Approval of this notice does not warrant of	or certify
that the applicant holds legal or equitable title to those rights in the subject lease which	would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

entitle the applicant to conduct operations thereon.