Form 3160-5 (August 2007)

UNITED STATES . DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED	
OMB No. 1004-	0137
Evnires: July 31	2010

5. Lease Serial No.

SF-080517 6. IF Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Farm Myel Name and No. Oil Well X Gas Well Other Bureau of Land Manageme Payne 4A 2. Name of Operator 9. API Well No. **Burlington Resources Oil & Gas Company LP** 30-045-23911 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 4289, Farmington, NM 87499 (505) 326-9700 Blanco MV / Basin DK 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface UNIT P (SESE), 1100' FSL & 135' FEL, Sec. 22, T32N, R10W San Juan New Mexico 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Well Integrity Alter Casing Fracture Treat Reclamation X Subsequent Report Casing Repair New Construction Recomplete Other Temporarily Abandon Change Plans Plug and Abandon Remove Tbg Strings & Final Abandonment Notice Convert to Injection Plug Back Water Disposal Packer & Commingle 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) OIL CONS. DIV DIST. 3 4/13/15 MIRU A PLUS #12. 4/14/15 NDWH. NU BOPE. PT BOPE. TEST OK. TOOH w/ 1" short string tubing. MAY 06 2015 4/15/15 TOOH w/ 1" short string tubing. POOH w/ packer. 4/16/15 TOOH w/ 2 3/8" long string tubing. Cleaned out to PBTD @ 8350'. 4/22/15 TIH w/ 262 jts., 2 3/8", 4.7#, J-55 tubing, set @ 8,302' w/ FN @ 8,301' (new tubing size & set depth). 4/23/15 ND BOPE. NU WH. PT tubing to 500#. Good test. RD RR @ 10:00 hrs on 4/23/15. This well is now a Blanco Mesaverde/Basin Dakota well being commingled per DHC Order 3925AZ. AL CEPTED FOR RECORD Land 0 1 2015 FARMINGTON FIELD OFF CE BY: William Tambekon 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Arleen White Staff Regulatory Technician Title Theen White Date Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

NIMOCUA

V

entitle the applicant to conduct operations thereon

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would