(February 2005)	DEPARTMENT OF		FEB 25 2015		FORM APPROVED OMB No. 1004-0137	
	BUREAU OF LAND				xpires: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No. NMNM 109397		
Do not use this form for proposals to drill or to re-enter an				6. If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA	Agreement, Name and/or No.	
1. Type of Well						
Oil Well Gas Well Other				8. Well Name and No. Chaco 2308 11A #408H		
2. Name of Operator				9. API Well No. 30-045-35563		
WPX Energy Production, LLC  3a. Address  3b. Phone No. (include area code)				10. Field and Pool or Exploratory Area		
PO Box 640 Aztec, NM 87410 505-333-1808				Basin Mancos		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 386' FNL & 1062' FEL, SEC 11, T23N, R8W BHL: 2479' FNL & 241' FEL SEC 12, T23N R8W				11. Country or Parish, State San Juan, NM		
12. CHI	ECK THE APPROPRIATE	E BOX(ES) TO INDIC	CATE NATURE OF NOTIC	CE, REPORT OR C	THER DATA	
TYPE OF SUBMISSION TYPE OF ACTION				N		
	Acidize	Deepen	Production (St	tart/Resume)	Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	Well Integrity		
	Casing Repair	New Constructi	on Recomplete		Other COMPLETION	
Subsequent Report	Change Plans	Plug and Aband		orarily Abandon —————		
Timb Abada and Timb Comment						
Notice	Injection	Plug Back	POOL NAME			
duration thereof. If the p all pertinent markers and subsequent reports must recompletion in a new in requirements, including 1/27/15- MIRU HWS #6	roposal is to deepen direct zones. Attach the Bond u be filed within 30 days fol terval, a Form 3160-4 mus reclamation, have been con	ionally or recomplete lander which the work work work with the work work of the filed once testing and the operation of the filed and the operation.	horizontally, give subsurface vill be performed or provide the involved operations. If the has been completed. Final a for has determined that the s	e locations and mea the Bond No. on fi the operation results Abandonment Notic ite is ready for fina		
P110 4 ½" tie back string, Drift, Tally, PU, TIH w/ seal assembly, No-Go, & 4 ½" P110 casing as follows: Seal Assembly w/ No-Go 5.85" OD 4.00" ID, 43jts 4 ½" 11.6# P110 casing, 19.75 X 4 ½" 11.6# P110 casing sub / marker jt set @ 4095.59' – 4115.34', 92jts 4 ½" 11.6# P110 casing, 2.04' casing sub, 1 X 6.04" casing sub, 1 44.10'jt, and 2.50' casing hanger and sub. Total length of all Tubulars ran in well = 5990.63'. Had an up wt of 58K and down wt of 48K. Landed w/ 24K						
on liner top and leaving 24K on hanger. Total with KB difference is 6001.67'. Pressure test 4 ½" casing and 4 ½" X 7" casing to 1500psi- Test good.						
1/28/15-TIH w/ 2 3/8" PH6 work string & CO to 10800'.						
<u>1/29/15</u> -RDMO					AIII IDMITTING	
2/6/15-Perf Gallup 1 <sup>st</sup> stage, 10612'-10737' + RSI TOOL @10803' with 18, 0.40" holes. RD. (Final casing reported RSI @ 10800'.)						
<u>2/7/15-2/9/15</u> - Prepare for frac.					/ RECEIVED	
14. I hereby certify that the foregoing is true and correct.  Name (Printed/Typed)						
Marie E. Jaramillo			Title Permit Tech III		FFR 2.6 2015	
Signature Date						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by			Title		DISTRICTION	
Conditions of approval, if any, a or certify that the applicant hold lease which would entitle the applicant to the applicant of the applicant to the applicant	s legal or equitable title to the	hose rights in the subject	office Office	'		

(Instructions on page 2)

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

# Chaco 2308 11A #408H - page 2

2/10/15-Frac Gallup 1st stage 10612'-10803'- with 219,792# 20/40 PSA Sand

Set flo-thru frac plug @ 10585' MD. Perf 2<sup>nd</sup> stage 10326'-10512'- with 24, 0.40" holes. Frac Gallup 2<sup>nd</sup> stage with 214,251#, 20/40 PSA Sand Set flo-thru frac plug @ 10295' MD. Perf 3<sup>rd</sup> stage 9995'-10226'- with 24, 0.40" holes. Frac Gallup 3<sup>rd</sup> stage with 214,007#, 20/40 PSA Sand Set flo-thru frac plug @ 9960' MD. Perf 4<sup>th</sup> stage 9664'-9895'- with 24, 0.40" holes.

# 2/11/15-Frac Gallup 4<sup>th</sup> stage with 215,443#, 20/40 PSA Sand.

Set flo-thru frac plug @ 9640' MD. Perf 5<sup>th</sup> stage 9378'-9564'-with 24, 0.40" holes. Frac Gallup 5<sup>th</sup> stage with 215,700#, 20/40 PSA Sand Set flo-thru frac plug @ 9340' MD. Perf 6<sup>th</sup> stage 9092'-9273'- with 24, 0.40" holes. Frac Gallup 6<sup>th</sup> stage with 214,000#, 20/40 PSA Sand Set flo-thru frac plug @ 9070' MD. Perf 7<sup>th</sup> stage 8806'-8992'- with 24, 0.40" holes. Frac Gallup 7<sup>th</sup> stage with 215,760#, 20/40 PSA Sand Set flo-thru frac plug @ 8770' MD. Perf 8<sup>th</sup> stage 8520'-8703'-with 24, 0.40" holes. Frac Gallup 8<sup>th</sup> stage with 212,060#, 20/40 PSA Sand Set flo-thru frac plug @ 8480' MD. Perf 9<sup>th</sup> stage 8234'-8420'-with 24, 0.40" holes.

# 2/12/15-Frac Gallup 9<sup>th</sup> stage with 216,240#, 20/40 PSA Sand

Set flo-thru frac plug @ 8180′ MD. Perf 10<sup>th</sup> stage 7948′-8134′- with 24, 0.40″ holes. Frac Gallup 10<sup>th</sup> stage with 214,498#, 20/40 PSA Sand Set flo-thru frac plug @ 7910′ MD. Perf 11<sup>th</sup> stage 7662′-7848′- with 24, 0.40″ holes. Frac Gallup 11<sup>th</sup> stage with 211,928#, 20/40 PSA Sand Set flo-thru frac plug @ 7625′ MD. Perf 12<sup>th</sup> stage 7376′-7556′- with 24, 0.40″ holes. Frac Gallup 12<sup>th</sup> stage with 212,060# 20/40 PSA Sand Set flo-thru frac plug @ 7335′ MD. Perf 13<sup>th</sup> stage 7090′-7276′- with 24, 0.40″ holes.

# 2/13/15- Frac Gallup 13<sup>th</sup> stage with 217,980#, 20/40 PSA Sand

Set flo-thru frac plug @ 7050' MD. Perf 14<sup>th</sup> stage 6804'-6890'- with 24, 0.40" holes. Frac Gallup 14<sup>th</sup> stage with 215,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6760' MD. Perf 15<sup>th</sup> stage 6518'-6706'- with 24, 0.40" holes. Frac Gallup 15<sup>th</sup> stage with 220,000#, 20/40 PSA Sand Set flo-thru frac plug @ 6470' MD. Perf 16<sup>th</sup> stage 6232'-6415'- with 24, 0.40" holes. Frac Gallup 16<sup>th</sup> stage with 215,000#, 20/40 PSA Sand Set 4-1/2" CBP @5010'. RDMO Frac & WL.

2/15/15- MIRU HWS #10. Pressure Tested BOP- OK. DO CBP @ 5010'

2/17/15-. DO flo- thru Frac plug @ 6470', 6760', 7050', 7335', 7625', 7910', 8180', 8480', 8770', 9070', 9340', and 9640'.

### 2/18/15-DO flo-thru Frac plug @ 9960', 10295', 10585' & CO to 10800'.

Pulled and landed tieback string: Pulled 72K on casing, started LD 4.5" 11.6# P110 casing, Loading casing on floats, Total 136jts & marker jt.

2/19/15 – Land tbg @ 6272'. As Follows: Hanger, KB 14.50' 35jts. of 2.7/8" 6.5# J-55tbg, GLV #9 @ 1,140' 24jts of 2.7/8 6.5# J-55tbg GLV #8 @ 1,946' 17jts of 2.7/8 6.5# J-55tbg, GLV #7 @ 2,505' 16jts 2.7/8 6.5# J-55tbg, GLV #6 @ 3,030' 16jts of 2.7/8 6.5# J-55tbg, GLV #5 @ 3,556' 15jts of 2.7/8 6.5# J-55tbg, GLV #4 @ 4049' 16jts of 2.7/8 6.5# J-55tbg, GLV #3 @ 4,574' 16jts of 2.7/8 6.5# J-55tbg, GLV #2 @ 5099' 10jts of 2.7/8 6.5# J-55tbg, 5,426' pro-nipple 2.31, 2jts of 2.7/8 6.5# J-55tbg, GLV #1 @ 5,919' 1jt of 2.7/8 6.5# J-55tbg. @ 5,951' 4' Pup jt, 7"X 2.7/8 T-2 ON & Off Tool, w/ 2.25 F-Nipple @ 5,957, 7"X 2.7/8 Arrowset 1- X 10K packer, @ 5,965' X over 9jts 2.375tbg, @ 6,239' 2.375 X 1.87 " X Nipple' @ 6,241', 1jt of 2.375 4.7# J-55tbg, @ 6,272' 2.375 1/2 Mull shoe @ 6,272' EOT, Packer was set at 10 K tension, Total 181jts 2.7/8 6.5# J-55 8rd tbg, Total 10jts 2.375 4.7# J-55 EUE 8rd, 64% Degrees. Rig down HWS #10.

# 2/20/15 – First delivered oil to sales.

Choke Size= 1", Tbg Prsr=580psi, Csg Prsr=850psi, Sep Prsr=220psi, Sep Temp=71degrees F, Flow Line Temp= 84degrees F, Flow Rate= 1602mcf/d, 24hr Fluid Avg=14bph, 24hr Wtr=204bbls, 24hr Wtr Avg=9bph, Total Wtr Accum=204bbls, 24hr Oil=141bbls, 24hr Oil Avg=6bph, Total Oil Accum=141bbls