OIL CONS. DIV DIST. 3

MAY 22 2015

RECEIVED

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

OMB No. 1004-0137 Expires: March 31, 2007

BOILEAU OF EARLY WANAGEMENT						
				5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLShington Field Of				ficeNMSF 078362		
Do not use this form for proposals to drill or to re-enter and Manag				6. If Indian, Allottee or Tribe Name		
abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE - Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well				132829		
1. Type of Hon				0. 111.11.11		
Мания Пания Пан				8. Well Name and No. NE CHACO COM #254H		
Oil Well Gas Well Other						
2. Name of Operator				9. API Well No.		
WPX Energy Production, LL			30-039-31289			
3a. Address 3b. Phone No. (inc PO Box 640 Aztec, NM 87410 505-333-1808			e area code)	10. Field and Pool or Exploratory Area		
	505-333-1808		Chaco Unit NE HZ(oil)			
4. Location of Well (Footage, S	Description)	11. Country or Parish, State				
SHL: 1325' FSL & 250' FWL, Sec 5, T23N, R6W BHL: 2192'FNL & 245' FEL, Sec 1 T23N, R7W				Rio Arriba, N	IVI	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION TYPE OF ACTION						
	Acidize	Deepen	Production (Sta	rt/Resume)	Water Shut-Off	
Notice of Intent						
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	n Recomplete		Other SIDETRACK_	
Subsequent Report	Change Plans	Plug and Abando	n Temporarily Al	Temporarily Abandon INTERMEDIATE		
Final Abandonment	Convert to					
Notice Plug Back Water Disposal						
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration						
					e vertical depths of all pertinent markers	
and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4						
must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed						
and the operator has determined that the site is ready for final inspection.)						
After drilling out of the surface casing the on the NE Chaco COM 254H the direction of the well was planned to drop angle and steer the well bore in the						
appropriate direction to pass the existing wellbore on the pad with sufficient clearance. As the current wellbore was being frilled the path was not						
corrected to the planned azimuth with an aggressive enough approach for proper clearance on the previously drilled well. Directly after a slide was put in						
the string was picked up and rotation began the driller noticed some torque spikes while rotating as he set the bit on bottom and picked the bit up off bottom. The directional driller notified essential personnel and the call was made at this point to plug back this section of the well due to a low projected						
					n had not already occurred at the	
point the torque spikes were e						
planning to cement the well back into the surface shoe and re-drill the top section of the intermediate hole in a direction that will give proper clearance.						
The details of the plug will be calculated once final volumes are calculated and volume adjusted for yield. The existing wells' casing integrity (NE Chaco						
COM #255H) will be reviewed and verified prior to stimulation operations commencing on that well.						
WPX Energy ran in the well open ended with drill pipe to a total measured depth of 792' and pumped a 440' cement plug from 792' to 352' with						
Halliburton cementing. The job was pumped as follows: 36.8bbls of tuned spacer, 10.5ppg, yield 6.15, 190sx of PlugCem (33bbl Slurry) 17.2ppg, yield 0.97,						
Mix ratio 3.7, Displaced with 3.3bb;s of tuned spacer 10.5ppg, 6.15 yield. The pipe was pulled out to 347' and hole was circ evacuating 7 bbl of excess cement to surface. The hole was left stable for 24 hrs while cement cured.						
Centent to surface. The note was left stable for 24 ms while tentent cured.						
Plug back job was witnessed by	the BIM (Walter Gage	a)				
After the 24 hrs set time was exhausted a new BHA was picked up and the well was side tracked off the old hole @ 481' after dressing down cement and						
time drilling off cement plug. The well was then drilled with the same target points as the original planned wellbore.						
14. I hereby certify that the forego	ing is true and correct.	T				
Name (Printed/Typed)						
Lacey Granillo			Title Permit Tech III			
TY VIRALINA						
Signature Date 5/12/15						
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by						
A.F.						
			Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warra				AC	CEPTED FOR RECORD	
or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.						
TI	A		1		3 17 17 17 17 17 17 17 17 17 17 17 17 17	