



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office
6251 College Blvd. - Suite A
Farmington, New Mexico 87402
www.blm.gov/nm



In Reply Refer To:
NMF0100(3162)

July 29, 2015

OIL CONS. DIV DIST. 3

JUL 31 2015

EnerVest Operating LLC
1001 Fannin Street Suite 800
Houston, TX 77002

30.039-22300

Gentlemen:

This letter is in reference to the plugged well, Jicarilla Apache Tribe 396 #1, 800FNL & 970FEL, Section 8, T23N R03W, Jicarilla lease number JIC396. Our records indicate that you are the approved operator for this well. This well was plugged on June 19, 2000. Conditions of Approval (COA's) attached to the approved Notice of Intent to Abandon required that the well location and access road be reclaimed within one year of the plugging date.

On July 21, 2015, the Bureau of Land Management, Farmington Field Office conducted a field inspection of the above referenced well site to evaluate the success of the final reclamation for this well site. The results of our inspection are identified below.

- 1) Significant erosion in the SE corner of the location.
- 2) Oilfield debris and undesirable vegetation on the well pad.
- 3) Cut slope on the west side of the location has not been re-contoured.

A remedial reclamation plan for this well and access road is required to be submitted to this office within 30 days of receipt of this letter. Your plan must address the deficiencies identified above, including a timeframe for completing the necessary remedial earthwork and seeding.

If you have any questions or need additional information, please contact Ty Swirin at (505) 564-7701 or by email at tswirin@blm.gov.

Sincerely,

Mark Kelly

Mark Kelly
Branch Chief, Environmental Protection

cc:
Well File JIC396
Ty Swirin
Jicarilla BIA
Jicarilla Oil & Gas

AV

2

