



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office
6251 College Blvd. - Suite A
Farmington, New Mexico 87402
www.blm.gov/nm



In Reply Refer To:
NMF0100(3162)

July 29, 2015

OIL CONS. DIV DIST. 3

EnerVest Operating LLC
1001 Fannin Street Suite 800
Houston, TX 77002

JUL 31 2015

30-039-22921

Gentlemen:

This letter is in reference to the plugged well, Jicarilla Apache Tribal 396 #2, 1120FSL & 820FEL, Section 8, T23N R03W, Jicarilla lease number JIC396. Our records indicate that you are the approved operator for this well. This well was plugged on February 12, 2002. Conditions of Approval (COA's) attached to the approved Notice of Intent to Abandon required that the well location and access road be reclaimed within one year of the plugging date.

On July 21, 2015, the Bureau of Land Management, Farmington Field Office conducted a field inspection of the above referenced well site to evaluate the success of the final reclamation for this well site. The results of our inspection are identified below.

- 1) Location has not been re-contoured; cut/fill slopes are eroding.
- 2) Oilfield debris and non-native material on the well pad.
- 3) Access road is wide open, un-vegetated and has trash along it.

A remedial reclamation plan for this well and access road is required to be submitted to this office within 30 days of receipt of this letter. Your plan must address the deficiencies identified above, including a timeframe for completing the necessary remedial earthwork and seeding.

If you have any questions or need additional information, please contact Ty Swirin at (505) 564-7701 or by email at tswirin@blm.gov.

Sincerely,

Mark Kelly
Branch Chief, Environmental Protection

cc:
Well File JIC396
Ty Swirin
Jicarilla BIA
Jicarilla Oil & Gas

AV

2

