State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary David R. Catanach, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following <u>3160-4 or 3160-5</u> form.

Operator Signature Date: 7/20/2015 Well information:

an dan dari										· · · · · ·			
API WELL	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	N/E
30-045-25577 00-00	TRADING POST	001	ENERGEN RESOURCES CORPORATION	G		San Juan	F	В	34	27	N	12 V	N

Application Type:

X P&A Drilling/Casing Change Location Change

**Recomplete/DHC** (For hydraulic fracturing operations review EPA Underground injection control Guidance #84)

Other:

Conditions of Approval: Place 100 foot Pictured Cliffs plug: 50 feet below formation top; tag one foot below bottom of perf.

NMOCD Approved by Signature

<u>8/5/15</u> Date

Form 3160-5 • (Augusi 2007)	DEPARTMENT	ED STATES		RECEIV	ΈD	FORM APP OMB NO. 1 Expires July	004-0137		
а <b>ц</b> — на		ND MANAGEMI		11.11 0 0	6 A 102	5. Lease Serial No.	51,2010		
sundry notices and reports on wells JUL 2.0 2015						NMM33026			
Do aban	not use this form for pro doned well. Use Form 3	onecole to drill	or to re-ent r such prop Fa	er an osals. rmington Fie	ld Office	6. If Indian, Allottee or	Tribe Name		
S	UBMIT IN TRIPLICATE	- Other instruction	Burea ons on page	2	anagement	7. If Unit or CA/Agreer	nent, Name and/or N		
1. Type of Well Oil Well X Gas W	/ell Other	ı				8. Well Name and No. Trading Post	#1		
2. Name of Operator									
ENERGEN RESOURCES	CORPORATION		3h Phone N	o. (include area	(code)	9. API Well No.			
	Farmington, NM 874	01		325-6800	(couc)	30-045-25577 10. Field and Pool, or 1	Exploratory Area		
	, Sec., T., R., M., or Survey Des		000	0000		Basin Fruitland			
790'FNL 1750' FE	L, Sec. 34 T27N R1	2W N.M.P.M.,	(B) NW/NE	2					
						11. County or Parish, S	State		
	·····	·				San Juan	<u>NM</u>		
12.	CHECK APPROPRIATE I	BOX(ES) TO IN	DICATE NA	TURE OF NO	OTICE, REPO	RT, OR OTHER DAT	A		
TYPE OF SU	BMISSION	· · · · · · ·		TYPI	E OF ACTION				
<b>x</b> Notice of Ir	tent	Acidize	Deep	en	Production	n (Start/Resume) W	ater Shut-Off		
Subsequent	Report	Alter Casing		ure Treat Construction	Reclamation		ell Integrity		
Final Abane	lonment Notice	Change Plans Convert to Injecti		and Abandon Back	Temporari Water Dis	ly Abandon			
If the proposal is to de Attach the Bond under following completion of testing has been comp determined that the fin Energen Resource	Completed Operation (clearly st epen directionally or recomplete which the work will be perfor of the involved operations. If the leted. Final Abandonment Not al site is ready for final inspection ses intends to plug a closed loop operation	e horizontally, give s med or provide the l re operation results i ices shalt be filed or on.) and abandon th	ubsurface loca Bond No. on fi n a multiple co nly after all rec e Trading	tions and measu le with BLM/B ompletion or rec uirements, incl Post #1 ad	ITED and true ver IA. Required s ompletion in a r uding reclamati	rtical depths of all pertine ubsequent reports shall b new interval, a Form 316 on, have been completed on the attached pr	nt markers and zone: e filed within 30 day 0-4 shall be filed one , and the operator ha		
	TACHED FOR Is of Approval OI	L CONS. DIV I	DIST. 3	ACTIO OPER AUTH	ON DOES NOT ATOR FROM ORIZATION 1	OR ACCEPTANCE OF F RELIEVE THE LESS OBTAINING ANY OTH REQUIRED FOR OPEI INDIAN LANDS	EE AND IER		
		JUL <b>2</b> 4 20	115						
14. I hereby certify that the f Name (Printed/Typed)	oregoing is true and correct								
Anna Stotts	1		Title	Regulat	ory Analys	t			
Signature	lati		Date	7/20/15					

THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by	Salvers	Title <b>PE</b>	Date 7/21/2015				

Conditions of approval, if any, are attacked. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. FFO Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Office

## PLUG AND ABANDONMENT PROCEDURE

June 30, 2015

Trading Post #1 Basin Fruitland Coal 790' FNL, 1750' FEL, Section 34, T27N, R12W, San Juan County, New Mexico API 30-045-25577 / Long \_\_\_\_\_ / Lat: \_\_\_\_\_


- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
  - Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.

  - 3. NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.
  - Plug #1 (Chacra top, 1770' 1638'): TIH with tubing and tag existing CIBP at 1770'. Spot 18 sxs Class B cement (excess due to open perfs) inside casing from 1770' to isolate the Chacra interval. PUH and WOC. TIH and tag cement; if necessary top off plug.TOH.
  - 5. Plug #2 (Pictured Cliffs Interval and Fruitland top, 1176' 846'): Round trip gauge ring or casing scraper to 1176', or as deep as possible. RIH and set 4.5" cement retainer at 1176'. Pressure test tubing to 1000 PSI. Load casing with water and circulate well clean. Pressure test casing to 800#. <u>If the casings do not test, then spot or tag subsequent plugs as appropriate.</u> Circulate well clean. Mix 29 sxs Class B cement inside casing from CR to isolate the Pictured Cliffs Interval and the Fruitland top. TOH and LD tubing.
  - Plug #3 (8.625" Surface casing shoe and Kirtland top, 360' 0'): Perforate squeeze holes at 360'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 115 sxs Class B cement and pump down the 4.5" casing to circulate good cement to surface. Shut in well and WOC.
  - ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations

\_ ·

• ,

 \_\_\_\_\_



·• · ·

ID 6000' New PBTD @ 1770'

		Trading Post #1					
		Proposed P&A					
Today's Date: 6/30/15		<b>Basin Fruitland Coal</b>					
		EL, Section 34, T-27-N, R-12-W, Sa	-				
Spud: 2/22/83 DK Completed: 3/16/83	Lat: N	/ Long: W/ API	#30-045-25577				
FtC Completed: 4/23/03 Plugback: 4/23/03				Plug #3: 360' – 0' Class B Cement, 115 sxs			
Kirtland @ 176'	10.4/48.5		8-5/8" 24#, K-55 Casin	g set @ 310'			
Elevation: 5846' Gl 5858' KB	12-1/4" hole		Cmt with 295 cf; cement fell back. Spot additional 59 cf to surface.				
			Perforate @ 360'				
Fruitland @ 896'				<b>Plug #2: 1176' – 846'</b> Class B Cement, 29 sxs			
			Set CR @ 1176'				
			Fruitland Coal Perforati 1226' – 1240'	ons:			
Pictured Cliffs @ 1240'			DV Tool @ 1405' Stage 3: Cement with 4 TOC by TS @ 450'	142 cf			
Chacra @ 1688'			Set CIBP @ 1770' (20	Plug #1: 1770' – 1638' Class B Cement, 18 sxs (excess due to open perfs) 03)			
Mesaverde @ 2122'				Existing Plug #3: 2120' – 1958' 11 sxs Class C Cement (2003)			
			TOC at DV tool, (calc	75%)			
			DV Tool @ 4111' Stage 2: Cement wit TOC at 3 <sup>rd</sup> DV Tool	h 877 cf			
Gallup @ 4820'				Existing Plug #2: 4920' – 4758' 11 sxs Class C Cement (2003)			
				<b>Existing Plug #1: 5805' – 5643'</b> 11 sxs Class C Cement (2003)			
			Set CIBP @ 5805' (200	)3)			
Dakota @ 5790′			Dakota Perforations: 5855' – 5880'				
	7-7/8" hole		4-1/2" 10.5#, J-55 Casi Stage 1: Cement with 3	ng set @ 5999' 362 cf			

• • •

TD 6000' PBTD 1770'

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Trading Post #1

## CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: tsalyers@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.