
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO. 30-045-21533
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E0-1200-0002
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Jaques Com
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 1
2. Name of Operator Four Star Gas & Oil Company			9. OGRID Number 131994
3. Address of Operator ATTN: Permitting Specialist 332 Road 3100 Aztec, New Mexico 87410		10. Pool name or Wildcat Otero Chacra	
4. Well Location			
Unit Letter O : 1060 feet from the South line and 1730 feet from the East line			
Section 2 Township 27N Range 9W NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.			County San Juan
	6154' GL	, KKB, K1, GK, etc.,	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL □	SUB REMEDIAL WOR COMMENCE DRI CASING/CEMEN	LLING OPNS. P AND A
OTHER:	П	OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
This is an amended notice of PA work to be done. The original C-103 was approved 5/21/15. Reilly Spence of Four Star has consulted with Brandon Powell and Mr. Powell has verbally accepted these proposed changes. Amended wellbore			
diagram is attached.			
Rig up rig. Install and test BOP. POOH with tubing. Run Cement Bond Log. Consult with NMOCD to make any necessary P&A design modifications based on CBL results			
Set CIBP @ ~3148'. Spot cement from CIBP @ ~3148' to 1300'. Perforate casing @ ~1300'. Establish circulation to			
surface. If no circulation, discuss different options with NMOCD.			
Pump cement down casing and circulate to surface. Fill annular volume. Cutoff wellhead, top off 2-7/8" and all annular			
spaces with cement, install d	ry hole marker, clean location,	and reclaim surfac	
Spud Date: 12/17/1974	Rig Release Da	ate:	OIL CONS. DIV DIST. 3
			AUG 1 3 2015
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE April &	Pohl TITLE PE	ermitting Specialist	DATE8/13/15
Type or print name April E. Pohl E-mail address:April.Pohl@chevron.com PHONE:505-333-1941 For State Use Only			
APPROVED BY: Conditions of Approval (if any):	52MTITLE	DISTRICT	#3 DATE 8/24/15
Conditions of Approval (II ally).	F-V		



Jacquez Com Well #1 San Juan County, New Mexico PROPOSED Wellbore Diagram



Prepared by: Simon Martin Date: 03/16/2015

Updated by: Date: