

RECEIVED

Form 3160-5
(August 2007)

JUL 23 2015

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010Farmington Field
Bureau of Land Management
SONDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well☒ Gas Well☐ Other

2. Name of Operator

Burlington Resources Oil & Gas Company LP

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No. (include area code)

(505) 326-9700

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

UL K (NESW), 2245' FSL & 790' FWL, SEC. 19, T32N, R9W

5. Lease Serial No.

SF-078513

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

SAN JUAN 32-9 UNIT

8. Well Name and No.

SAN JUAN 32-9 UNIT #273

9. API Well No.

30-045-28033

10. Field and Pool or Exploratory Area

BASIN FRUITLAND COAL

11. Country or Parish, State

San Juan

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☒ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing Repair☐ New Construction☐ Recomplete☒ Other☐ Final Abandonment Notice☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7/21/15 MIRU A-PLUS 12. ND HH. PT tbg to 1000# - good test. POH w/pump & rods. ND WH, NU BOP, PT- OK. TOH w/tubing. Used air, mist, foamer and corrosion inhibitor to c/o wellbore. Circ. hole for 2 days, C/O to 3439'. 7/23/15 RIH w/107 jts 2-3/8", 4.7# J-55 tubing and set @ 3424'. 7/24/15 ND BOP, NU WH. RIH w/rods & pumpd. Seat pump. Load tbg w/12 bbls 2% KCL. PT tbg to 1000# - good test. Stroke test pump. OK. NU HH. Spaced out rods. RD & released righ @ 1430 hrs 7/24/15.

OIL CONS. DIV DIST. 3

JUL 31 2015

ACCEPTED FOR RECORD

JUL 28 2015

FARMINGTON FIELD OFFICE
BY: William Tambekou

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Patsy Clugston

Title

Staff Regulatory Technician

Signature

Date

7/27/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

12