


UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0115
Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.



Lease Serial No. **36096**
NM

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Pride Energy Company

3a. Address

P.O. Box 701950, Tulsa, OK 74170

3b. Phone No. (include area code)

(918) 524-9200

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter D: 660' FWL and 660' FNL of Section 12-20N-3W

8. Well Name and No.

San Isidro 12-4

9. API Well No.

30-043 -20723

10. Field and Pool, or Exploratory Area

Rio Puerco

11. County or Parish, State

Sandoval County, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

☒ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☒ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Set CIBP at ~~2,600'~~ ^{3,910'} and dump ~~20'~~ ^{36'} cmt. on top
Run CBL and block squeeze if necessary
Perforate Fruitland formation from 950' - 960'
Acidize Fruitland perforations
If necessary, frac Fruitland perfs

Estimated Start Date: Sometime between 1/16/06 and 3/16/06 (depending on rig availability)

Estimated Duration of workover: 4 days

Bond#: BD 101035

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

By: Pride Production Co., Inc.

Title: General Partner

By: Matthew L. Pride

Title: President

Signature

Matthew L. Pride

Title

Date 01/17/06

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

JAN 23 2006

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

NMOCD