OIL CONS. DIV DIST. 3

JU	1	2	4	20	15
00	-		100		

Form 3160-5 (February 2005) D BU	ED 5. Lease	FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.					
SUNDRY N Do not use this is	6 If Indi	NMSF078359 6. If Indian, Allottee or Tribe Name					
abandoned well.	agement	7. If Unit of CA/Agreement, Name and/or No.					
SUBM 1. Type of Well		132829					
Oil Well Ga		8. Well Name and No. NE CHACO COM #271H					
2. Name of Operator WPX Energy Production, LLC		9. API Well No. 30-039-31288					
3a. Address PO Box 640 Aztec, NM 8	7410	3b. Phone No. (include area code 505-333-1816	e) 10. Fiel	10. Field and Pool or Exploratory Area Chaco Unit NE HZ			
4. Location of Well (Footage, Sec., SHL: 1430' FSL & 353' FWL SEC BHL: 1576' FNL & 59' FWL SEC	16 23N 6W		11. Country or Parish, State Rio Arriba, NM				
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION		TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Start/Resume)	Water Shut-Off			
	Alter Casing	Fracture Treat	Reclamation	Well Integrity			
Subsequent Report	Casing Repair	New Construction	Temporarily	Other COMPLETION			
6	Change Plans Plug and Abandon At		Abandon				
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal				
all pertinent markers and zones subsequent reports must be file recompletion in a new interval,	al is to deepen directionally of s. Attach the Bond under wh ad within 30 days following , a Form 3160-4 must be file		osurface locations and a provide the Bond No. o ons. If the operation res Final Abandonment N	measured and true vertical depths of on file with BLM/BIA. Required sults in a multiple completion or lotices must be filed only after all			
NOTE: WPX originally permitted BHL	L in Sec 18 but we did not rea	ach our planned TD. BHL is now in s	ec 17 which changes th	e lease #.			
& Tested 7" casing to 1,500 psi & 4.			6 # P110 casing, subs : ACCEPTED F(2'- 3'- 8- w/ 1jt. 2'sub & Hanger, RU DR RECORD			
C/O 11179' Perf Gallup 1 st stage, 10994'-11119' + RSI TOOL @11182' with 18, 0.40" holes. RDMO JUL 20 2015							
<u>6/4/15-6/28/15</u> - Prepare for frac.	FARMINGTONF BY:	MINGTO FILE OFFICE					
14. I hereby certify that the foregoing	is true and correct.		V	CUAFIDENTIAL			
Name (Printed/Typed)	A	Title P	Itle PERMITTING TECH III				
Khat	A		H	WARDEN BREED GREAT			
Signature	THIS SPACE FO	OR FEDERAL OR STATE	OFFICE USE				
Approved by	P	18					
			tle	Date			
Conditions of approval, if any, are atta the applicant holds legal or equitable to applicant to conduct operations thereon	itle to those rights in the subje		Office				
Title 18 U.S.C. Section 1001 and Title United States any false, fictitious or fra-				o any department or agency of the			



NE Chaco Com #271H - page 2

6/29/15-Frac Gallup 1st stage 10994'-11182'- with 216,503# 20/40 PSA Sand

Set flo-thru frac plug @ 10945' MD. Perf 2nd stage 10715'-10894'- with 24, 0.40" holes. Frac Gallup 2nd stage with 218,100#, 20/40 PSA Sand Set flo-thru frac plug @ 10680' MD. Perf 3rd stage 10422'-10608'- with 24, 0.40" holes. Frac Gallup 3rd stage with 217,700#, 20/40 PSA Sand

6/30/15-Set flo-thru frac plug @ 10360' MD. Perf 4th stage 10136'-10322'- with 24, 0.40" holes. Frac Gallup 4th stage with 217,700#, 20/40 PSA Sand

Set flo-thru frac plug @ 10070' MD. Perf 5th stage 9850'-10033'-with 24, 0.40" holes. Frac Gallup 5th stage with 216,120#, 20/40 PSA Sand Set flo-thru frac plug @ 9790' MD. Perf 6th stage 9564'-9749'- with 24, 0.40" holes. Frac Gallup 6th stage with 217,920#, 20/40 PSA Sand Set flo-thru frac plug @ 9530' MD. Perf 7th stage 9278'-9463'- with 24, 0.40" holes. Frac Gallup 7th stage with 216,040#, 20/40 PSA Sand Set flo-thru frac plug @ 9240' MD. Perf 7th stage 8992'-9177'- with 24, 0.40" holes. Frac Gallup 8th stage with 215,640#, 20/40 PSA Sand Set flo-thru frac plug @ 9240' MD. Perf 8th stage 8706'-8892'- with 24, 0.40" holes. Frac Gallup 9th stage with 215,640#, 20/40 PSA Sand Set flo-thru frac plug @ 8940' MD. Perf 9th stage 8706'-8892'- with 24, 0.40" holes. Frac Gallup 9th stage with 219,780#, 20/40 PSA Sand Set flo-thru frac plug @ 8650' MD. Perf 10th stage 8420'-8606'- with 24, 0.40" holes. Frac Gallup 10th stage with 217,700#, 20/40 PSA Sand

7/1/15-Set flo-thru frac plug @ 8350' MD. Perf 11th stage 8134'-8320'- with 24, 0.40" holes. Frac Gallup 11th stage with 218,040#, 20/40 PSA Sand

Set flo-thru frac plug @ 8070' MD. Perf 12th stage 7848'-8033'- with 24, 0.40" holes. Frac Gallup 12th stage with 214,240# 20/40 PSA Sand Set flo-thru frac plug @ 7790' MD. Perf 13th stage 7562'-7747'- with 24, 0.40" holes. Frac Gallup 13th stage with 218,980#, 20/40 PSA Sand Set flo-thru frac plug @ 7530' MD. Perf 14th stage 7276'-7461'- with 24, 0.40" holes. Frac Gallup 14th stage with 220,260#, 20/40 PSA Sand Set flo-thru frac plug @ 7240' MD. Perf 15th stage 6990'-7176'- with 24, 0.40" holes. Frac Gallup 14th stage with 220,260#, 20/40 PSA Sand Set flo-thru frac plug @ 6920' MD. Perf 15th stage 6990'-7176'- with 24, 0.40" holes. Frac Gallup 15th stage with 220,180#, 20/40 PSA Sand Set flo-thru frac plug @ 6920' MD. Perf 16th stage 6704'-6890'- with 24, 0.40" holes. Frac Gallup 16th stage with 217,400#, 20/40 PSA Sand Set flo-thru frac plug @ 6660' MD. Perf 16th stage 6418'-6604'- with 24, 0.40" holes. Frac Gallup 17th stage with 217,400#, 20/40 PSA Sand Set flo-thru frac plug @ 6660' MD. Perf 17th stage 6418'-6604'- with 24, 0.40" holes. Frac Gallup 18th stage with 217,440#, 20/40 PSA Sand Set flo-thru frac plug @ 6670' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 217,440#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 217,440#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 216,300#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 216,300#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 216,300#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th stage 6134'-6318'- with 24, 0.40" holes. Frac Gallup 18th stage with 216,300#, 20/40 PSA Sand Set flo-thru frac plug @ 6370' MD. Perf 18th

7/2/15-Set 4-1/2" CBP @ 5020'

7/3/15- RDMO Frac & WL.

7/9/15- MIRU

DO CBP @ 5020. DO flo- thru Frac plug @ 6370', 6660', 6920', 7240', 7530', 7790', 8070', 8350', 8650', 8940', 9240' and 9530'

7/10/15-DO flo- thru Frac plug @ 9790', 10070', 10360', 10680' 10945'

Circ. & CO well to 11179'

Pulled seal assembly out of tieback. seal assembly, BO landing sub and mandrel, continue to LD subs and 133 jts of 4.5" P110 Csg

7/11/15-Land tbg @ 6025'. As follows, Run production tbng with GLV on 2 7/8" N-80 tbng 36 jts of 2 7/8" 1114.46 GLV #9 @1144.36 4.10 25 jts of 2 7/8"773.42 GLV #8 @1921.88 4.10 20 jts of 2 7/8" 618.70 GLV #7 @2544.68 4.10 17 jts of 2 7/8" 527.36 GLV #6 @3076.14 4.10 16 jts of 2 7/8" 495.93 GLV #5 @3576.17 .10 17 jts of 2 7/8" 525.01 GLV #4 @4105.28 4.10 17 jts of 2 7/8" 524.03 GLV #3 @4633.41 4.10 16 jts of 2 7/8" 494.02 GLV #2 @5131.53 4.10 14 jts of 2 7/8" 433.71 2.313" XN @5566.44 1.20 9 jts of 2 7/8" 278.42 GLV #1 @5848.96 4.10 1 jt of 2 7/8" 30.77 2 7/8" pup jt and on/off tool 6.02 7" ASI-X packer set @5893.25 7.50 2 7/8" x 2 3/8" xo 50 3 jts of 2 3/8" J-55 tbng 96.56 1.791" XN @5991.56 1.25 1 jt of 2 3/8" w/ ms collar 3.45 EOT @6025.01

7/15/14- Choke Size= 1", Tbg Prsr= 660 psi, Csg Prsr= 694 psi, Sep Prsr= 133 psi, Sep Temp= 89 degrees F, Flow Line Temp= 106 degrees F, Flow Rate= 2006 mcf/d, 24hr Fluid Avg= 63 bph, 24hr Wtr= 233 bbls, 24hr Wtr Avg= 10 bph, Total Wtr Accum= 1859 bbls, 24hr Oil= 534 bbls, 24hr Oil Avg= 53 bph, Total Oil Accum= 1344 bbls, 24hr Fluid= 767 bbls