RECEIVED

JUL 1 4 2015

Form 3160-5 (February 2005) D	UNITED STA EPARTMENT OF TH					OMB No	APPROVED . 1004-0137	
	JREAU OF LAND M			Farmington	Field Offic	ceExpires: M	arch 31, 2007	
			Bu	ireau of Lar	id manage	ACTHENINO.	the second second	
SUNDRY NOTICES AND REPORTS ON WELLS					NMSFO	NMSF078359		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If India	6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No. 132829				
Oil Well Gas Well Other						8. Well Name and No. NE CHACO COM #209H		
2. Name of Operator WPX Energy Production, LLC					9. API Well No. 30-039-31292			
3a. AddressPO Box 640Aztec, NM 8	3b. Phone No. (include area code) 505-333-1816				10. Field and Pool or Exploratory Area Chaco Unit NE HZ			
4. Location of Well (<i>Footage, Sec., T.,R.,M., or Survey Description</i>) SHL: 1410' FSL & 361' FWL SEC 16 23N 6W BHL: 2451' FSL & 53' FWL SEC 17 23N 6W					11. Country or Parish, State Rio Arriba, NM			
12. CHECK T	HE APPROPRIATE BOX(ES) TO INDICATE NAT	URE	OF NOTICE,	REPORT OR	OTHER DA	TA COMPSASAND	
TYPE OF SUBMISSION	TYPE OF ACTION							
Notice of Intent	Acidize	Deepen		Start/Re	luction sume)	Water	Shut-Off	
	Alter Casing	Fracture Treat		Rec	amation	Well I	ntegrity	
Subsequent Report	Casing Repair	New Construction	1		omplete	Other	COMPLETION	
Subsequent Report	Change Plans	Plug and Abandon	1	Abandon	porarily			
Final Abandonment Notice	Convert to Injection	Plug Back			er Disposal			
duration thereof. If the proposa all pertinent markers and zones subsequent reports must be file recompletion in a new interval, requirements, including reclam <u>6/2/15-</u> MIRU Tie Back- TIH w/ seal assemley w/ 9 4804.56 19.97 106 jts of 4 1/2" casi Total length of all tubulars including record test for 30 minutes. Test was 1,500 psi. Nipple down BOPE, Instal	Attach the Bond under wh d within 30 days following a Form 3160-4 must be file ation, have been completed 5.85 Nogo 4.5, P110 11.6# ng 4694.11 3 casing pups f g KB 5790.09 Landed with 3 s good. Pressure test 7" Int	hich the work will be performed to the involve completion of the involve ed once testing has been of and the operator has deter casing Seal assembly with for spacing 9.78, 7.20, 5.3 36,000# on liner top, 20,00 ermediate casing to 1,500	ormed ed oper omple rmined NO-G 80 22. 00# on 0 psi. C	or provide the ations. If the of ted. Final Aba I that the site i O 1.16 22 jts of 78 1 jt of 4 1/2 csng hanger. hart record te	Bond No. on operation resu ndonment No s ready for fin of 4 1/2" casin 2" casing 43.0 Pressure test st for 30 minu	a file with BL alts in a multi- ptices must be nal inspection of 984.57 M 0 csng sub wi 4 1/2" casing utes. Test wa	M/BIA. Required ple completion or e filed only after all n.) arker jt 4784.59 - ith csng hanger 2.50 g to 1,500 psi. Chart s good. Shut in 7" with	
6/3/15-PSI tested 4-1/2" casing (a							IL CONS. DIV DIST.	
RDMO CO to 10892'							JUL 17 2015	
Perf Gallup 1 st stage, 10707'-10821'	+ RSI TOOL @ 10896' with	18, 0.40" holes. RD.		ITUN	NEIUE	03	002 21 2010	
740.67-60 5 78 611								
<u>6/4/15-6/21/15</u> - Prepare for frac. 14. I hereby certify that the foregoing i	is true and correct.							
Name (Printed/Typed) LACEY GRANILLO				PERMITTING TECH III				
S ALL			Title		ING ILCI	111		
Signature			Date					
1001	THIS SPACE FO	OR FEDERAL OR	STA	TE OFFIC	E USE			
Approved by	A			Title		Date		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the				Office				
applicant to conduct operations thereon.				ACCEPTED FOR RECORD				
Title 18 U.S.C. Section 1001 and Title United States any false, fictitious or fra					lly to make to	any department	nt or agency of the 1 4 2015	
						~~L		

A

2

3

NE Chaco Com #209H - page 2

6/22/15-Frac Gallup 1st stage 10707'-10896'- with 216,460# 20/40 PSA Sand

Set flo-thru frac plug @ 10675' MD. Perf 2nd stage 10421'-10607'- with 24, 0.40" holes. Frac Gallup 2nd stage with 217,420#, 20/40 PSA Sand 6/23/15-Set flo-thru frac plug @ 10375' MD. Perf 3rd stage 10135'-10321'- with 24, 0.40" holes. Frac Gallup 3rd stage with 210,640#, 20/40 PSA Sand PSA Sand

Set flo-thru frac plug @ 10080' MD. Perf 4th stage 9854'-10035'- with 24, 0.40" holes. Frac Gallup 4th stage with 218,840#, 20/40 PSA Sand Set flo-thru frac plug @ 9790' MD. Perf 5th stage 9563'-9749'-with 24, 0.40" holes. Frac Gallup 5th stage with 211,800#, 20/40 PSA Sand Set flo-thru frac plug @ 9510' MD. Perf 6th stage 9277'-9463'- with 24, 0.40" holes. Frac Gallup 6th stage with 213,100#, 20/40 PSA Sand Set flo-thru frac plug @ 9235' MD. Perf 7th stage 8991'-9177'- with 24, 0.40" holes. Frac Gallup 7th stage with 216,000#, 20/40 PSA Sand

6/24/15-Set flo-thru frac plug @ 8960' MD. Perf 8th stage 8705'-8891'- with 24, 0.40" holes. Frac Gallup 8th stage with 214,440#, 20/40 PSA Sand

Set flo-thru frac plug @ 8660' MD. Perf 9th stage 8419'-8605'- with 24, 0.40" holes. Frac Gallup 9th stage with 218,380#, 20/40 PSA Sand Set flo-thru frac plug @ 8370' MD. Perf 10th stage 8133'-8319'- with 24, 0.40" holes.

6/25/15-Frac Gallup 10th stage with 214,480#, 20/40 PSA Sand

Set flo-thru frac plug @ 8080' MD. Perf 11th stage 7847'-8033'- with 24, 0.40" holes. Frac Gallup 11th stage with 214,860#, 20/40 PSA Sand Set flo-thru frac plug @ 7800' MD. Perf 12th stage 7561'-7747'- with 24, 0.40" holes. Frac Gallup 12th stage with 217,120# 20/40 PSA Sand Set flo-thru frac plug @ 7535' MD. Perf 13th stage 7275'-7461'- with 24, 0.40" holes. Frac Gallup 13th stage with 219,240#, 20/40 PSA Sand Set flo-thru frac plug @ 7235' MD. Perf 14th stage 6992'-7175'- with 24, 0.40" holes.

6/26/15-Frac Gallup 14th stage with 212,940#, 20/40 PSA Sand

Set flo-thru frac plug @6930' MD. Perf 15th stage 6670'-6889'- with 24, 0.40" holes. Frac Gallup 15th stage with 215,148#, 20/40 PSA Sand Set flo-thru frac plug @ 6610' MD. Perf 16th stage 6337'-6553'- with 24, 0.40" holes. Frac Gallup 16th stage with 214,700#, 20/40 PSA Sand Set flo-thru frac plug @ 6285' MD. Perf 17th stage 6001'-6210'- with 24, 0.40" holes. Frac Gallup 17th stage with 216,500#, 20/40 PSA Sand

Set 4-1/2" CBP @5000'

6/27/15- RDMO Frac & WL.

7/6/15- MIRU Pressure Tested BOP- OK.

<u>7/7/15</u>- DO CBP @ 5000'. DO flo- thru Frac plug @ 6285', 6610', 6930', 7235', 7535', 7800', 8080', 8370', 8660', 8960', 9235', 9510', 9790', 10080', 10375' and 10675'

7/8/15- Circ. & CO well to 10892'

7/8/15- pull tieback string as follows: seal assembly w/ 5.85 Nogo 4.5, P110 11.6# casing Seal assembly with NO-GO 1.16 ,22 jts of 4 1/2"casing ,Marker jt106 jts of 4 1/2" casing, 3 casing pups, 1 jt of 4 1/2" casing,csng sub with csng hanger. Total length of all tubularsincluding KB5790.09

Land tbg @ 5886'. Run production tbng with GLV on 2 7/8" N-80 tbng 37 jts of 2 7.8" 1144.17 GLV #9 @1163.57 4.10 24 jts of 2 7/8" 740.67 GLV #8 @1908.34 4.10 19 jts of 2 7/8" 586.20 GLV #7 @2498.64 4.10 16 jts of 2 7/8" 495.78 GLV #6 @2998.52 4.10 16 jts of 2 7/8" 495.22 GLV #5 @3497.84 4.10 16 jts of 2 7/8" 495.05 GLV #4 @3995.99 4.10 16 jts of 2 7/8" 494.0 GLV #3 @4494.09 4.10 16 jts of 2 7/8" 496.71 GLV #2 @4994.90 4.10 12 jts of 2 7/8" 370.31 X-nipple @5366.41 1.20 10 jts of 2 7/8" 308.95 GLV #1 @5679.46 4.10 1 jt of 2 7/8" 31.14 2 7/8" pup jt with on/off tool 6.02 7" packer @5724.12 7.50 2 7/8" x 2 3/8" xo 50 X nipple @5852.51 1.25 1 jt of 2 3/8" tbng ms collar 33.54 EOT @5886.05 Set packer w/ 10,000# tension

NOTE: Will file flowback test info and delivery info on delivery sundry.