State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

David Martin Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary David R. Catanach, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 10/22/15

Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng	W/
30-045-13253- 00-00	WARREN LS	ACCOUNTY.	BP AMERICA PRODUCTION COMPANY	G	Α	San Juan	F	G	24	28	N	9	w

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMSF077123

6.	If	Indian,	Allottee	or	Tribe	Name

abandoned we			6. If indian, Anouee of Thoe Name			
SUBMIT IN TRI	7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. WARREN LS 5 9. API Well No. 30-045-13253-00-C1				
Type of Well ☐ Oil Well ☑ Gas Well ☐ Ott						
Name of Operator BP AMERICA PRODUCTION						
. Address 200 ENERGY CT. FARMINGTON, NM 87401		3b. Phone No. (include area code Ph: 281-366-7148		Field and Pool, or Exploratory Multiple—See Attached		
Location of Well (Footage, Sec., 7		11. County or Parish, and State SAN JUAN COUNTY, NM				
Sec 24 T28N R9W SWNE 18 36.649780 N Lat, 107.736328			SAN JUAN CO	JUNIY, NM		
36.649780 N Lat, 107.736328	3 W Lon		NOTICE, REPORT, OR OTH			
36.649780 N Lat, 107.736328	3 W Lon		NOTICE, REPORT, OR OTH			

testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP America Production Company respectfully requests to plug the Aztec Pictured Cliffs formation in the subject well and produce the well efficiently from the Otero Chacra & Blanco-Mesaverde.

OIL CONS. DIV DIST. 3

Please see the attached procedure including wellbore diagrams.

CONDITIONS OF APPROVAL

OCT 29 2015

In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations.

SEE ATTACHED FOR

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

14. I hereby certify that	the foregoing is true and correct. Electronic Submission #321027 verifie For BP AMERICA PRODUCTIO Committed to AFMSS for processing by ABDEL	N CO	sent to the Farmington		
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST		14.5
Signature	(Electronic Submission)	Date	10/22/2015		
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE		
Approved By ABDEL	GADIR ELMANDANI	TitleF	PETROLEUM ENGINEER	Date 10/	26/2015
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Additional data for EC transaction #321027 that would not fit on the form

10. Field and Pool, continued OTERO CHACRA

IL COMS. DIV DIST 8

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT BELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

COOM

SOMETHINGS OF A PROVES

Warren LS 005-PC/CH/MV

API # 30-045-13253-00 Location: G SEC. 24, T28N, R09W San Juan County, New Mexico

Reason/Background for Job

The proposed work is to isolate the Pictured Cliffs formation and produce the well efficiently from the Chacra and Mesaverde formations.

Basic job procedure

- 1. Pull tubing
- 2. RIH and set 5-1/2" RBP at +/- 2,370' KB
- 3. Set 7-5/8" pkr at +/- 2,330' KB and pressure test RBP to 500psig
- 4. TOH with 7-5/8" pkr
- 5. Isolate Pictured Cliffs perforations with casing patch or cement squeeze
- 6. RIH and set 7-5/8" pkr above abandoned PC perforations
- 7. Pressure test isolation job to 500psig
- 8. POOH with 7-5/8" pkr and retrieve 5-1/2" RBP
- 9. TIH with tbg and cleanout to PBTD @ 4660' KB
- 10. Land tubing @ +/- 4470' KB
- 11. Return well to production

Current WBD



WARREN LS 005-PC/CH/MV

Pictured Cliffs / Chacra / Mesaverde API # 300451325300 SEC 24, T28N, R9W **NEW MEXICO**

Max Temp 139 deg F

GL: 5896* KB: 10'

TOC: Surface (circ.)

Surface Casing Data

Hole Size

10-3/4", 32.75#, Armoo SW @ 171"

150 sxs cmt

TOC: 810" (T.S. 3/19/57)

Pictured Cliffs Completion

2230'-2270' (2spf), frac w/ 40k# 20/40 snd & water

Production Casing Data

9-7/8" Hole

7-5/8", 26.4#, J-55 @ 2420"

200 sxs 50/50 poz, tail w/ 50 sxs reg. cmt

TOL: 2349"

TOC: TOL (sqz'd liner top w/ additional 100 sxs neat cmt,

primary TOC @ 3900' - T.S. 3/2/57)

Chacra Completion

3182'-3373' gross (4spz, 60 holes) frac w/ 256,500# 16/30 snd & 70Q N2 foam

Mesaverde Completion MN: 3980'-4365' gross (2spf, 30 holes)

frac w/ 99,500# 16/30 Brady snd & Propnet, N2 foam

Tubing Details

2-3/8", 4.7#, J-55@ 4541

Nipple Data

Stop @ 4522'wlm 6/8/04 X-Nipple @ 4533* F-Nipple @ 4538'

End of Tubing

4541

PL: 4467'-4484', 4530'-4550', 4570'-4586', 4640'-52' (4spf) frac w/ 60k# 20/40 sand & water

Production Liner Data

6-3/4" Hole

5-1/2", 15.5#, J-55@ 2349'-4707'

300 sxs 50/50 poz emt

Updated 10/9/15 JJvW

PBTD: 4660° Total Depth: 4712'

Proposed WBD



WARREN LS 005-PC/CH/MV

Pictured Cliffs / Chacra / Mesaverde API # 300451325300 SEC 24, T28N, R9W NEW MEXICO

* Max Temp 139 deg F

GL: 5896' KB: 10'

TOC: Surface (circ.)

Surface Casing Data

Hole Size

10-3/4", 32.75#, Armoo SW @ 171"

150 sxs omt

TOC: 810" (T.S. 3/19/57)

Pictured Cliffs Completion (Abandoned 2015) 2230'-2270' (2spf), frac w/ 40k# 20/40 snd & water

Production Casing Data

9-7/8" Hole

7-5/8", 26.4#, J-55 @ 2420"

200 sxs 50/50 poz, tail w/ 50 sxs reg. cmt

TOL: 2349'

TOC: TOL (sqz'd liner top w/ additional 100 sxs neat cmt,

primary TOC @ 3900' - T.S. 3/2/57)

Chacra Completion

3182"-3373" gross (4spz, 60 holes) frac w/ 256,500# 16/30 snd & 70Q N2 foam

Tubing Details

2-3/8", 4.7#, J-55 @ 4470"

Nipple Data

PRSV Stop in F-nipple F-Nipple @ +/- 4467' KB

> End of Tubing 4470'KB

PBTD: 4660'

Total Depth: 4712'

Mesaverde Completion

MN: 3980'-4365' gross (2spf, 30 holes) frac w/ 39,500# 16/30 Brady snd & Propnet, N2 foam PL: 4467'-4484', 4530'-4550', 4570'-4586', 4640'-52' (4spf)

frac w/ 60k# 20/40 sand & water

Production Liner Data

6-3/4" Hole

5-1/2", 15.5#, J-55 @ 2349'-4707'

300 sxs 50/50 poz omt

Updated 10/9/15 JJvW

BLM CONDITION OF APPROVAL

CASING REPAIR, WORKOVER AND RECOMPLETION OPERATIONS:

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs. If a CBL or other logs are run, provide this office with a copy.
- 2. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minute test period. Provide test chart with your subsequent report of operations
- 3. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 4. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.